



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|---|-----------------|---|--|
| LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428 | | | Ref: CS/LIP22010450/Avy3m4 Date: 21/12/2022 Code: LIP | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | GBK 7568B | Veh. Inspected | SND 4308A | |
| Policy No. | | Coverage (\$) | 0.00 | |
| Claim No. | AVS22/2558 | Excess (\$) | 0.00 | |
| Assign From | ANDY SEAH | Assign Date | 20/10/2022 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | BMW 116D | c.c | 1496 | |
| Engine No. | HIDDEN | Year of Reg. | | |
| Chassis No. | WBA1V72060V250192 | Colour | WHITE | |
| Odometer | 102445 KM | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | SPORTS RIM | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 225/40 R18 | MICHELIN | 6 mm | |
| L/H Front Tyre | 225/40 R18 | MICHELIN | 6 mm | |
| R/H Rear Tyre | 225/40 R18 | MICHELIN | 6 mm | |
| L/H Rear Tyre | 225/40 R18 | MICHELIN | 6 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 09/09/2022 | Inspection Date | 31/10/2022 | |
| Survey held at | YSK AUTO WORKSHOP 1 KAKI BUKIT AVE 6 @ AUTOBAY #01-71 SINGAPORE 417883 | | | |
| 5a. Remarks | | | | |
| A)REGISTRATION DATE: 27 NOV 2015 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | | 3 Working Days | |