

SND 4308A 2015 Nov TP Liberty
Veron.

BMW 116D. 1496cc

WBA1V72060V250192

Rees	Number Plate.	Cracked	30(SN)	✓
		x 1	30(SN)	X
Rees	Number Plate Holder			
Rees	Number Plate Lamp x 02	14	76 x 2 = 152.	X.
		14		
Rees	Bumper	Deformed	1120.	✓
Rees	Bumper Clips.	14	30(SN).	✓
		14		
Rees	Bumper Side Holder.	14	102 x 2 = 204	X.
		14		
Rees	Bumper Reinforcement.	Dented	635	✓
Rees	Bumper Reflector x 02	14	104 x 2 = 208	X
		14		
Rees	Bumper Centre Guide.	Cracked	153	✓
			240	
Reverse	Sensor x 04.	1 piece damaged	240 x 4 = 960	
Reverse	Sensor Holder x 04.	14	25 x 4 = 100	✓
		14		
Rees	End Panel.	14	1028.	X
		14		
Rees	End Panel Top Garnish.	14	291	X

SND4308A.

Rees End Panel Top Garnish clips. ^{HP} 20 X
 Rees End Panel Sealant. ^{HP} 60(SN) X
 2248 S.N. 60
 2023.20

Panel Beating ~~800~~ 250
 Spray Painting ~~600~~ 250
 Wiring. 580 ~~100~~ 30
 To remove reverse sensor ~~100~~ 50
 To spray tilt coat ~~150~~ X
 To remove upholstery. 150 X
 To perform diagnostic test. 200. X.

7121

total: 2063.20
 L/S: 2.1K
 03 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Accepted by: _____
 S.