

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721

TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

MCQUEEN RENTALS PTE LTD
c/o 46 Lentor Plain
Singapore 786548

Date: 27/10/2022

Not Authorized
11 Sep 8 1550h
Resurvey After Paint
2 days

QUANTITY	PARTICULARS	AMOUNT (\$)
RE: TOYOTA WISH / SLL 9103 Y		
1 pc	front head lamp RH <i>1245.90</i>	<i>CM</i> 1,640.30
1 pc	front head lamp lower bracket	<i>Sm</i> 124.00
1 pc	front grille	<i>Pm</i> 568.10
1 pc	front grille chrome moulding	<i>Sm</i> 235.00
1 pc	front bumper <i>545</i>	<i>Bm</i> 687.50
1 pc	front bumper dust cover <i>178.10</i>	<i>CM</i> 239.10
1 pc	front bumper lower grille side	<i>Sm</i> 287.60
1 pc	front bumper side retainer RH	<i>ors</i> 89.60
1 pc	front bumper reinforcement	<i>R</i> 568.40
1 pc	front bumper reinforcement sponge	<i>Sm</i> 468.30
1 pc	windscreen washer tank	<i>Sm</i> 365.00
Sub-total		5,272.90
Less 25%		1,318.23
Sub-total		3,954.68
To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.		800.00
To spray painting on affected areas.		500.00
To check wiring system.		50.00
Total		5,304.68

200/-
220/-
20/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: