

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jacqueline Tan

Date: 16 Feb 2023

Preliminary Advice

Vehicle No	: GBJ1074D	Accident Date	: 19/10/2022
Make	: TOYOTA DYNA 150	Policy No.	: DMCVSNW0003422202
Assignment Date	: 21/10/2022	Excess	: S\$350.00
Date of Inspection	: 10/11/2022	Est. Duration of Repair	: 5 days
Inspection At	: LAI HUAT (MENG KEE) MOTOR PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,236.78
Revised Amount	:S\$	3,236.78
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,236.78
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	74,000.00
COE / PARF Rebate	:S\$	16,744.00
Salvage Value	:S\$	
Margin for Repair	:S\$	57,256.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Kindly approve on Supplementary and Final Amount.