

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jacqueline Tan

Date: 10 Nov 2022

## **Preliminary Advice**

Vehicle No	: GBJ1074D	Accident Date	: 19/10/2022
Make	: TOYOTA DYNA 150	Policy No.	: DMCVSNW0003422202
Assignment Date	: 21/10/2022	Excess	: S\$350.00
Date of Inspection	: 10/11/2022	Est. Duration of Repair	: 05 DAYS
Inspection At	: LAI HUAT (MENG KEE) MOTOR PTE LTD		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,138.78
Revised Amount	:S\$	3,138.78
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,138.78

Lump Sum Repair	:S\$	
-----------------	------	--

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	74,000.00
COE / PARF Rebate	:S\$	16,744.00
Salvage Value	:S\$	
Margin for Repair	:S\$	57,256.00

### **Remarks**

( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( X ) Other comments : Part by Part repair.

Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.