

ASSIGNMENT

From _____ Date _____
 Estimated Cost: _____
 CO ☒ TP / ☐ VS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To Inspect Vehicle No: _____
 at Workshop m/s COMFORTDELGRO

of _____
 Insured: _____

Policy No _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SH2934A Yr Regn: 03 Oct/2017

Type: M.Car / M.Cycle / Bus / Van / Lorry ☒ Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA PRIUS c.c 1798

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB3FU303564903 *

Gen. Cond ☒ Good / Fair / Poor / Burnt

Steering: ☒ norde / Jammed / Leaked / Burnt or

Brake: ☒ norde / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / ☒ S/D A/R or

Tyre Size: F: 195/65R15

R: //

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or WESTLAKE

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 21-10-2022

*Survey held at W/S 4PM

Des. of Damages ☒ Frt Rear / O/S / ☒ N/S / U/C / Rooftop or

The ☒ U/C Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
31/1/23	Naz finalised LS \$9750/-; 6 days with Mr Chiang. (Red. 9251.84, 48%)

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 6

1)

☒ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Insp (\$

☐ : MSA Insp (\$

Survey Fee:

Transportation:

____ \$ + PS. ____ \$

Photos

Other:

TOTAL

Report F 10/11

TP

Long Sum / M/L: LS \$9750/-

Celine Fong (LKKAUTO)

From: Naz (LKKAUTO)
Sent: Tuesday, 31 January 2023 11:18 AM
To: Chiang Liat Choon
Cc: Celine Fong (LKKAUTO)
Subject: Re: SH 2934A FINALIZE
Attachments: SH 2934A FINALIZED.pdf

Dear Mr Chiang

"Without Prejudice"

We will be advising our Principal a cost of repair of Lump S \$9,750.00/- with 6 days of repair, subject to their approval.

Thank you.

Best Regards,

Naz | Technical Investigator

LKK Auto Consultants

Phone: 6841-2157 | Email: Naz@lkkauto.com | Fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chiang Liat Choon <chianglc@cdge.com.sg>
Sent: Thursday, 12 January 2023 11:18 am
To: Naz (LKKAUTO) <Naz@lkkauto.com>
Subject: Fw: SH2934A FINALIZE

Hi Naz,

Attached LTA rebate & book value.

Best Regards
Chiang Liat Choon
Taxi Accident Repair
ComfortDelGro Engineering Pte Ltd
Off: 62148314 Fax: 65468156

Do you really need to print?
Go Digital! Go Paperless!



From: Chiang Liat Choon <chianglc@cdge.com.sg>
Sent: Wednesday, 9 November 2022 2:16 pm
To: Guo Qiang (LKKAUTO) <guoqiang@lkkauto.com>
Subject: Fw: SH2934A FINALIZE

Version: 1.0 (Last Synchronised: 21 Oct 2022)

TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Repairer's

(Price-denominated Standard List)

ComfortDelGro Engineering Pte Ltd/SH2934A/21/10/2022 09:55

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET X	25.00	0.00	*1,117.93 FL
2	1		*Bonnet hinge LH X	25.00	0.00	*87.70 FL
3	1		*Bonnet hinge RH X	25.00	0.00	*87.70 FL
4	1		*Bonnet Rubber X	25.00	0.00	*35.50 FL
5	1		*Bonnet Lock X	25.00	0.00	*132.60 FL
6	1		*Bonnet lock panel X	25.00	0.00	*186.60 FL
7			BMC ✓ *Radiator Grille	25.00	0.00	*438.00 FL ✓
8			*Radiator grille emblem	25.00	0.00	*88.00 FL ✓
9	1		*Radiator grille lower panel X	25.00	0.00	*493.18 FL
10	1		*Radiator Support Upper Panel X	25.00	0.00	*364.98 FL ✓
11	1		*Radiator Support Lower Panel X	25.00	0.00	*145.90 FL ✓
12	1		*Radiator Support RH Panel X	25.00	0.00	*278.68 FL ✓
13	1		*Radiator Support LH Panel X	25.00	0.00	*278.68 FL ✓
14	1		*Head Lamp LH Panel X	25.00	0.00	*240.10 FL
15	1		*Head LAMP LH	25.00	0.00	*2,637.80 FL ✓
16	1		*FOG LAMP LH	25.00	0.00	*920.00 FL ✓
17	1		*Front Bumper	25.00	0.00	*586.18 FL ✓
18	1		*front bumper reinforcement - 7 X SVC	25.00	0.00	*812.89 FL
19	10		*front bumper clips	25.00	0.00	*22.00 FL ✓
20	2		*front bumper side retainer	25.00	0.00	*154.00 FL ✓
21	1		*Front Bumper tow cover	25.00	0.00	*57.76 FL ✓
22	1		*Front Fender Lh	25.00	0.00	*1,111.93 FL ✓
23	1		*Front Fender Housing Lh X	25.00	0.00	*958.30 FL
24	1		*Front Fender Shield Lh	25.00	0.00	*198.50 FL ✓
25	1		*Front Fender Hybrid emblem Lh	25.00	0.00	*86.50 FL
26			*Front Wheel alu Rim Lh	25.00	0.00	*1,570.00 FL ✓
27	1		*Front Wheel Hub/Bearing Lh	25.00	0.00	*560.10 FL ✓
28	1		*Front Steering knuckle Lh	25.00	0.00	*580.80 FL ✓
29	1		*Front Shock absorber Lh	25.00	0.00	*401.80 FL ✓
30	1		*Front Steering ball joint Lh	25.00	0.00	*199.98 FL ✓
31	1		*Front Steering Tie Rod Lh	25.00	0.00	*159.30 FL ✓
32	1		*Front Drive Shaft Lh	25.00	0.00	*1,764.00 FL ✓
33	1		*Front wing Mirror Assy Lh X	25.00	0.00	*1,728.70 FL
34	1		*Front wing Mirror Cover Lh X	25.00	0.00	*141.90 FL
35	1		*Front Door Lh	25.00	0.00	*1,264.00 FL ✓
36	1		*Front Rocker Panel Lh	25.00	0.00	*576.00 FL
37	1		*Front door Comfort Logo Sticker	0	0.00	*75.00 FS
38	1		*Front door Advertisement	0	0.00	*100.00 FS
39	1		*Front Fender Advertisement	0	0.00	*100.00 FS
40	1		*Rear Door Advertisement	0	0.00	*100.00 FS
41	1		*Rear Door Comfort App sticker	0	0.00	*80.00 FS

*Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)

20,622.79

- List Item Discount on L Items (S\$)

5,041.95

ComfortDelGro Engineering Pte Ltd/SH2934A/21/10/2022 09:55. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

aneous Items

Case (Insurer) /

Amount

11.00

Sub Total (S\$)

11.00

Estimates on Labour

No Particulars

11.00

Lab.Type

Amount

Labour Items

1	PANEL BEATING	New	700	1,750.00	60
2	SPRAY PAINTING	New		1,200.00	1
3	REMOVE/REFIX FRONT U/SUSPENSION	New	90	120.00	7
4	REMOVE/ REFIX DOOR PART	New		90.00	60
5	CHECK WIRING & LIGHTING	New		80.00	30
6	RESET FRONT WHEEL ALIGNMENT	New	NN X	80.00	60
7,02	TUFF COATING	New		90.00	60

Gross Labour Cost (S\$)

3,410.00

10,400.

ComfortDelGro Engineering Pte Ltd/SH2834A/21/10/2022 09:55. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

6 Days.

4/5

6mo. Avg.

21/10

8pm.

25/10 start

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modifications is allowed
 - Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: