

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/HLA22010457/ANY3E2**Date:** 20/06/2023REFERENCE

Handling Insurer:	HL Assurance Pte Ltd	Policy No:	MP316483
Claimant Vehicle No :	SLD5082S	Insured Vehicle No :	SLX1942G
Date of Loss:	19/10/2022	Nature of Claim:	TP
		Claim No:	MPC03765

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD5082S	Engine No:	PE20787759
Make & Model:	MAZDA 6, 2.0 (A)	Chassis No:	JM6GJ1072G0239766
Reg. Date:	20/06/2016 (Man. Year: 2016)	Odometer:	126783 km
Colour:	Blue		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,093.82	1,576.48	1,517.34	49.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,670.00	480.00	1,190.00	71.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,763.82	2,056.48	2,707.34	56.83
Approved Total (Overridden) (S\$)		1,600.00		
Nett Amount (S\$)	4,763.82	1,600.00	3,163.82	66.41

INSPECTION

Date of Assignment:	21/10/2022	
Date Inspected:	25/10/2022	Inspected At: Premium Carz Services Pte Ltd (HQ) 1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Singapore 417883
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Jun 2023)
Parts:	143	MAZDA 6 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLD5082S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	993.40 FL	*993.40 FL
2	1		*REAR BUMPER SIDE RETAINER RH	Necessary	57.60 FL	*57.60 FL
3	1		*REAR BUMPER SIDE RETAINER LH	Necessary	57.60 FL	*57.60 FL
4	1		*REAR BUMPER REINFORCEMENT	Dented	574.50 FL	*574.50 FL
5	2		*REAR BUMPER TOW HOOK COVER	Not Necessary	96.00 FL	*- FL
6	1		*BOOT LID (NPA)	Not Necessary	0.00 FL	*- FL
7	1		*BOOT LID MAZDA LOGO	Not Necessary	68.50 FL	*- FL
8	1		*BOOT LID MAZDA 6 LOGO	Not Necessary	53.10 FL	*- FL
9	1		*BOOT LID SKYACTIV LOGO	Not Necessary	76.10 FL	*- FL
10	1		*BOOT LID LOCK	Not Necessary	195.00 FL	*- FL
11	1		*BOOT LID WEATHERSTRIP	Not Necessary	185.00 FL	*- FL
12	1		*REAR END PANEL GARNISH	Not Necessary	271.00 FL	*- FL
13	1		*REAR END PANEL	Repair	457.00 FL	*- FL
14	1		*SET REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
15	10		*REAR BUMPER CLIP	Necessary	45.00 FS	*30.00 FS
16	5		*REAR END PANEL GARNISH CLIP	Not Necessary	22.50 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,402.30	1,913.10
- List Item Discount on L Items 10.00/20.00% (S\$)	308.48	336.62
Total Parts (S\$)	3,093.82	1,576.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	60.00	30.00
2	PANEL BEATING CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD, TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS	New	600.00	250.00
3	SPRAY PAINTING ALL AFFECTED PARTS & AREAS	New	800.00	200.00
4	TO SPRAY ANTI-RUST UNDERCOAT	New	30.00	0.00
5	TO REMOVE AND REFIT REAR SEATS, REAR WHEELHOUSE INNER GARNISH, FLOOR CARPET & UPHOLSTERY TO FACILITATE REPAIRS	New	180.00	0.00
Gross Labour Cost (S\$)			1,670.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >