

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9815R**AAD2210-060***Not Authorized**Return B4 paint**\$ 4299.53*

Vehicle No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

14 OCT 2022**SHD9815R**

200303878K

TOYOTA

PRIUS GEN 4

13/10/2022

PC3816M / CHINA TAIPING

23/12/2020

To Rust-Proofing and apply		PART	LIST
1	COVER, REAR BUMPER	\$	Bulind 485.60 ✓
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	R 332.70 X
1	GUARD, REAR BUMPER, CENTER	\$	Wt R 374.50 ✓
1	SEAL, REAR BUMPER SIDE, RH	\$	Sn 118.30 X
1	RETAINER, REAR BUMPER SIDE, RH	\$	Sn 132.60 X
1	COVER, REAR BUMPER, LOWER	\$	Sn 22.00 X
1	REFLECTOR ASSY, REFLEX, RH	\$	Sn 39.00 X
1	COVER, DECK TRIM, REAR	\$	Sn 126.70 X
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	R B 651.00 X
1	REFLECTOR ASSY, REFLEX, RH	\$	Sn 39.00 X
1	COVER, FLOOR UNDER, NO.2 (RH)	\$	Sn 241.90 X
1	COVER, REAR FLOOR (CTR)	\$	Sn 229.90 X
1	PANEL SUB-ASSY, QUARTER, RH	\$	DD 871.50 ✓
1	LINER, REAR WHEEL HOUSE, RH	\$	Sn 139.80 X
1	HUBCAP	\$	Sn 211.50 X
1	RIM	\$	Wt Sn 1,900.10 ✓
1	LENS & BODY, REAR COMBINATION LAMP, RH (Upper)	\$	Sn 339.60 X
1	LENS & BODY, REAR COMBINATION LAMP, NO.2 RH (Lower)	\$	Bu 261.00 ✓

TOTAL	\$	6,516.70
25%	\$	1,596.58
	\$	4,789.73

Special Nett

1	REAR BUMPER SIDE CLIP	\$	Wt 60.00 ✓
1	FENDER LINER CLIP	\$	Wt 65.00 X
1	REAR BUMPER ADVERTISEMENT	\$	Wt 100.00 X
SET	PARKING AID	\$	Sn 700.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9815R**AAD2210-060**

1SET REAR BUMPER CLIP

\$ 85.00 X

1 REAR BUMPER RETAINER CLIP

\$ 75.00 X

TOTAL \$ 1,085.00**TOTAL PARTS \$ 5,874.73****LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ 240.00 301

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 1001

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 1,750.00 6001

To transfer of rear end panel fittings, attachment to facilitate bodywork repair.

\$ 380.00 X

Putty And Spray Painting Of The Affected Portion.

\$ 1,750.00 4401

To reinstall rear bumper parking sensor.

\$ 170.00 501

To transfer of tire, rim and on wheel balancing.

\$ 170.00 201

To Check Electrical Lighting Concerned.

\$ 170.00 201

To check steering geometry and computer wheel alignment

\$ 220.00 601

To remove and refit of rear fender fittings, attachment and perform water seepage test.

\$ 170.00 X

TOTAL \$ 5,400.00**Over All Total \$ 11,274.73****LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

(PART-BY-PART) Repair Days

7 Days

5 days