SML 5429 A

REG NO.:

MAKE/MODEL:

ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road

#08-1339 Singapore 470130

LKK Auto Consultants hence notify the Repairer of the following:

Tel: 9450 7920 * zooma utowerks@gmail.com

To resurvey before/after spray painting

To display damaged part(s) during resurvey
Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4 November 2022

Not Aprilled 21/10/27 2/5 5 2700 4 days.

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

MERCEDES BENZ A200

SPECIAL NETT ITEMS

ESTIMATED KE	PAIR COST FOR THE VEHICLE WENTIONED ABOVE		C
QTY	DESCRIPTION		AMT(S\$)
	LIST ITEMS		
1	Rear windscreen moulding 1		\$ 112.00 🗡
1	Rear tailgate 🔥 🔨		\$ 2,200.00 💢
1	Rear tailgate rubber		\$ 185.00 📈
1	Rear tailgate logo		\$ 78.00 X
1	Rear tailgate "A200" emblem		\$ 78.00 🗴
1	Rear end panel		\$ 1,248.00 🐰
1	Rear end panel inner garnish 🔥 🔨	. 20-	\$ 165.00 🗴
1	Rear bumper	1 557	\$ 2,085.00
1	Rear bumper reinforcement	465	\$ 817.00
2	Rear bumper reflectors	62	\$ 336.00 1 € €
2	Rear bumper side retainers $\wedge \wedge$		\$ 170.00 X
1	Rear bumper lower diffuser	322.45	\$ 1,280.00
2	Rear bumper PDC sensors 0/5 Shuda	192	\$ 770.00 12 (
2	Rear bumper side sensors	. 10	\$ 770.00 X
1	Rear bumper tow hook cover	_	\$ 28.00 🗸
1	Rear bumper centre chrome moulding	278-25	\$ 325.00
2	Rear bumper side chrome mouldings NL		\$ 392.00 X
1	Rear exhaust chrome tail pipe		\$ 285.00
		102	\$ 11,324.00
		Less 5%	\$ 566.20
		,	\$ 10,757.80

1	Rear windscreen sealant	\$ 80.00
	• • • • • • • • • • • • • • • • • • • •	\$ 80.00
S/N	LABOUR CHARGES	
1	To remove, replaced damaged lamps and check up rear wiring.	\$ 80.00 20
2	To remove and refit inner garnishes.	\$ 180.00 <i>6 o</i>
3	To remove and refit rear reverse sensor.	\$ 180.00 SV
4	To transfer rear tailgate mechanism and wiring assembly.	\$ ハヘ 120.00 X
5	To remove and refit rear windscreen glass.	\$ ∧ 180.00 ×
6	To apply undercoating.	\$ Aへ 200.00 ×
7	Panel beating.	\$ 1,600.00 4 <i>8</i> 9
8	To re-spray painting on the affected areas.	\$ 1,500.00 $\psi_{i2,2}$
		\$ 4,040.00

GRAND TOTAL:

7-26567 2391.03 14,877.80