

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9930R

AAD2210-059

*Not Authorized
Permanently B4 paint**8148610*

Vehicle No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

14 OCT 2022**SHD9930R**

200303878K

TOYOTA

PRIUS GEN 4

13/10/2022

SJU163J / CHINA TAIPING

6/11/2020

PART		LIST	
1	COVER, REAR BUMPER	\$	<i>Bu</i> 485.60 ✓
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	<i>As</i> 332.70 ✓
1	GUARD, REAR BUMPER, CENTER	\$	<i>Not in</i> 374.50 ✓
1	COVER, REAR BUMPER, LOWER	\$	<i>not</i> 22.00 ✓
1	RETAINER, REAR BUMPER SIDE, RH	\$	<i>in</i> 132.60 X
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	<i>in</i> 651.00 X
1	COVER, DECK TRIM, REAR	\$	<i>in</i> 126.70 X
1	COVER, FLOOR UNDER, NO.2 RH	\$	<i>in</i> 241.90 X
1	COVER, FLOOR UNDER, NO.1 LH	\$	<i>in</i> 175.10 X
1	COVER, REAR FLOOR CTR	\$	<i>in</i> 229.90 X
TOTAL		\$	2,772.00
25%		\$	693.00
TOTAL		\$	2,079.00

Special Nett

1SET PARKING AID	\$	<i>Bu</i> 700.00 X
1SET REAR BUMPER CLIP	\$	<i>in</i> 85.00 <i>605N</i>
1 BUMPER CENTRE GUARD CLIP	\$	<i>in</i> 80.00 X
1 REAR BUMPER PROTECTOR	\$	<i>in</i> 180.00 <i>305N</i>
1 REAR BUMPER RETAINER CLIP	\$	<i>in</i> 75.00 X
TOTAL	\$	1,120.00
TOTAL PARTS	\$	3,199.00

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9930R

AAD2210-059

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	<i>nn</i> 240.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00 X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,750.00 <i>200l</i>
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	<i>nn</i> 380.00 X
Putty And Spray Painting Of The Affected Portion.	\$	1,750.00 <i>220l</i>
To Remove And Refit Rear Big & Small W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>nn</i> 300.00 X
To reinstall rear bumper parking sensor.	\$	170.00 <i>50l</i>
To Check Electrical Lighting Concerned.	\$	170.00 <i>15l</i>
TOTAL	\$	5,140.00
Over All Total	\$	8,339.00

(PART-BY-PART) Repair Days*7 Days**2 days***LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: