

ASS. REQ. BY:

Steve

CS/SMR 12010463/43

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
	X

Bas. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

G/A / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Date/Time Action/Instruction

MV-908

Date/Time, File Pass to?

☐ : Prelim. Report☐ : Final Report

Date/Time, File Return to?

2) _____

Report Format: _____

Lump Sum / L.S. (\$) _____

Veh No: SMT 1847H Yr Regn: 3a/3/90

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Ssang Yong Tivoli c.c. 1597

Colour: Black A/C: Insured / Std / Nil / NA

Sp. Reading 176340 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: KPT30A 10SLP3P1749

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55R17

R: 11

ES / DUN / EXNOVA / GY / FS / LIZA / MIO / OHTSU / PIR / SUMI / TOYO / YOKO or

Front R/Bal. 4 mm

U/Bal. 4 mm

D.O.A. 1/5/77

Survey held at Metan-ay

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation

\$ + RS. \$1

Price

Others

TOTAL

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Motorway Car Care Centre Pte Ltd

1094 Lower Delta Road Motorway Building Singapore 169205

TEL: 6468-2200 FAX: 6278-5535

GST:200000606-K RCB NO.200000606-K

M/S : MS FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

TEL: 65073848

ATTN: Motor Claim Department

Estimate No: QT2210645

Date: 19 Oct 2022

Policy No:

Veh Reg No: SMT1847H

Make/Model: SSANGYONG TIVOLI
1.6D STD 6AT 2WD ABS
E6 FL

Chassis No: KPT30A1USLP319749

Engine No: 67391002095582

Reg. Date: 30/03/2020

Your Ref No: SMT1847H

Claim Type: Third Party

Accident Date: 01/05/2022

TP Veh Reg No: SHB1027L

Estimate Repair Cost to Vehicle No :SMT1847H

Description	Quantity	List Price SS	Amount SS
THIRD-PARTY CLAIM			
VEH: SMT1847H & SHB1027L			
DOA: 01 May 2022/12:50:00			
LOCATION: TELOK AYER			
LABOUR: \$400			
SPRAY PAINT: \$450			
Others			
1 REAR BOOT X R	1 PC	1,971.80	
2 REAR BUMPER / 00	1 PC	912.75	
3 REAR BUMPER LWR - (W) ?	1 PC	932.96	
4 REAR BUMPER REINFORCEMENT ?	1 PC	529.68	
5 REAR BUMPER RETAINER RH	1 PC	32.40	
6 REAR TAILLAMP RH X	1 PC	1,515.35	
7 REAR BUMPER REFLECTOR LENS RH - OR	1 PC	43.73	
		5,938.65	
	Less 10%	593.87	5,344.79
8 REAR BUMPER CLIPS (SN)	1 PC	40.00	30
9 TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES	1 SET	180.00	X
10 REMOVE & REFIT REAR WINDSCREEN GLASS	1 SET	120.00	X
11 TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS REVERSE SENSORS	1 SET	120.00	30
12 REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT / WELD, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS.	1 SET	1,600.00	4000 800
13 PUTTY AND SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER)	1 SET	1,400.00	4000 900
		3,460.00	3,460.00