

ASS. REC. BY:

Steve

CS/SMR 12010463/43

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

oi _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
	X

Bd. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

G/A / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMT 18474 Yr Regn: 3a/3/20

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Ssang Yong Tivoli cc 1597

Colour: Black A/C: Insured / Sid / NI / NA

Sp. Reading 176340 T/Radio: Insured / Sid / NI / NA

Eng/No: _____

C/No: KPT30A 10 SLP 3A 1749

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size: F: 215/55R17

R: 11

ES / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIRI / SUMI /

TOYO / YOKO or _____

Front R/Bal. 4 mm

U/Bal. 4 mm

D.O.A. 1/5/77

Survey held at McFarland

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time Action/Instructions

MV-90X

Steve confirmed final fig :\$3460.49 and 4 days

(red 5344.3,61%)

Date/Time, File Pass to?

1) 07/11/22

Date/Time, File Return to?

2) _____

Report Format:

Lump Sum / L.S. (\$) 3460.49

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:

Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Workload (\$)

Survey Fee:

Transportation

S + RS \$

Price

Others

TOTAL

Motorway Car Care Centre Pte Ltd

1094 Lower Delta Road Motorway Building Singapore 169205

TEL: 6468-2200 FAX: 6278-5535

GST:200000606-K RCB NO.200000606-K

M/S : MS FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

TEL: 65073848

ATTN: Motor Claim Department

Estimate No: QT2210645

Date: 19 Oct 2022

Policy No:

Veh Reg No: SMT1847H

Make/Model: SSANGYONG TIVOLI
1.6D STD 6AT 2WD ABS
E6 FL

Chassis No: KPT30A1USLP319749

Engine No: 67391002095582

Reg. Date: 30/03/2020

Your Ref No: SMT1847H

Claim Type: Third Party

Accident Date: 01/05/2022

TP Veh Reg No: SHB1027L

Estimate Repair Cost to Vehicle No :SMT1847H

Description	Quantity	List Price	Amount
		<u>SS</u>	<u>SS</u>
THIRD-PARTY CLAIM			
VEH: SMT1847H & SHB1027L			
DOA: 01 May 2022/12:50:00			
LOCATION: TELOK AYER			
LABOUR: \$400			
SPRAY PAINT: \$450			
Others			
1 REAR BOOT X R	1 PC	1,971.80	X
2 REAR BUMPER / DP	1 PC	912.75	✓
3 REAR BUMPER LWR - CR	1 PC	932.96	✓
4 REAR BUMPER REINFORCEMENT ? X NN	1 PC	529.68	X
5 REAR BUMPER RETAINER RH ? X NN	1 PC	32.40	X
6 REAR TAILLAMP RH X NN	1 PC	1,515.35	X
7 REAR BUMPER REFLECTOR LENS RH - OR	1 PC	43.73	✓
		5,938.65	
	1889.44		
	-10%		
	1700.49		
	Less 10%	593.87	5,344.79
8 REAR BUMPER CLIPS (SN)	1 PC	40.00	3
9 TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES	1 SET	180.00	X
10 REMOVE & REFIT REAR WINDSCREEN GLASS	1 SET	120.00	X
11 TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS REVERSE SENSORS	1 SET	120.00	3
12 REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT / WELD, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS.	1 SET	1,600.00	4,744.79
13 PUTTY AND SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER)	1 SET	1,400.00	4,344.79
	1760	3,460.00	3,460.00
	= 3460.49		