

 PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0861/2022/EQ
DATE : 6-Oct-22
WIP : 44846

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON
YOUR INSURED VEH NO : SNF 349 F**

China Taiping Insurance (S) Pte Ltd

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

Attn: Motor Claims Dept

OWNER'S NAME : MR LIM CHER SHEE DARYL
ADDRESS : 50 LOR 40 GEYLANG
#04-33
SINGAPORE 398074
TELEPHONE : HP +65 96348510
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : DMPCSNW00166672202
VEHICLE NO : **SNG 2082 Y**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 8/8/2017
ENGINE NO : CHZ 399351
CHASSIS NO : WAUZZZ8V9J1003473
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 1-Oct-22
PLACE OF ACCIDENT : MARINA BLVD

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNG 2082 Y

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID.	S/N \$	280.00	X
2	TO RENEW LHS 1/4 GLASS AND REAR WINDSCREEN TO FACILITATE RENEWAL OF LHS REAR FENDER.	S/N \$	600.00	/
3	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND 1/4 GLASS.	S/N \$	400.00	/
4	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$	200.00	/
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,400.00	1 ✓
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,400.00	1 ✓
TOTAL LABOUR CHARGES		:	\$ 4,280.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNG 2082 Y

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 350.00	/
8	TO DISMANTLE AND REINSTALL REAR BUMPER. TO RENEW LHS REAR DOOR. TO CUT OUT AND WELD LHS REAR FENDER AND LHS OUTER WHEEL HOUSING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	S/N \$ 7,700.00	4550
9	TO RESPRAY REAR BUMPER, LHS REAR FENDER, LHS REAR DOOR, DOOR HANDLE, ROOF CHANNEL, LHS SILL PANEL, DRAIN CHANNEL, DOOR ENTRANCES AND REAR END PANELLING.	S/N \$ 6,000.00	3250
10	TO RENEW LHS REAR RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 520.00	280
11	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	/
TOTAL LABOUR CHARGES		: \$ 19,042.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNG 2082 Y

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR SIDE PANEL - LH / <i>OD</i>	1	\$ 4,445.00	✓
2	REAR WINDOW / <i>re</i>	1	\$ 905.00	✓
3	REAR SIDE WINDOW - LH / <i>re</i>	1	\$ 635.00	✓
4	WINDOW PRIMER / <i>re</i>	2	\$ 44.00	43.40 ✓
5	REAR WHEEL HOUSING LINER <i>1</i> X nn	1	\$ 260.00	
6	REAR WHEEL SPOILER - LH <i>1</i> X nn	1	\$ 39.00	
7	REAR WHEEL SPOILER COVER - LH <i>1</i> X nn	1	\$ 4.00	
8	REAR WHEEL HOUSING ATTACHMENT PARTS - LH X nn	1	\$ 673.00	
9	REAR DOOR - LH / <i>re</i>	1	\$ 3,265.00	✓
10	REAR DOOR ATTACHMENT PARTS X nn	1	\$ 134.00	
11	REAR DOOR CATCH - LH <i>1</i> X nn	1	\$ 105.00	
12	REAR DOOR SEAL - LH INNER / <i>re</i>	1	\$ 213.00	178.50 ✓
13	REAR WINDOW REGULATOR - LH <i>1</i> X nn	1	\$ 286.00	
14	REAR WINDOW REGULATOR MOTOR - LH <i>1</i> X nn	1	\$ 300.00	
15	REAR DOOR MOUNTING BAR - LH <i>re</i> X nn	1	\$ 182.00	
16	REAR DOOR BOWDEN CABLE <i>1</i> X nn	1	\$ 58.00	
17	REAR DOOR BOWDEN CABLE HOLDER <i>1</i> X nn	1	\$ 4.00	
18	REAR DOOR INNER PANEL - LH X nn	1	\$ 1,831.00	
19	REAR ALUMINIUM RIM - LH / <i>re</i>	1	\$ 1,303.00	✓
20	REAR ALUMINIUM RIM RUBBER VALVE <i>re</i>	1	\$ 4.00	X nn
SUB TOTAL SPARE PARTS		:	\$ 14,690.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNG 2082 Y

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	ACRYLIC SEALANT / <i>ne</i>	S/N	\$	180.00	✓
22	CAVITY WAX / <i>ne</i>	S/N	\$	140.00	✓
23	STONE CHIP / <i>ne</i>	S/N	\$	180.00	✓
24	METAL FILLER POWDER / <i>ne</i>	S/N	\$	280.00	✓
25	1/4 GLASS SEALANT / <i>ne</i>	S/N	\$	100.00	✓
26	REAR WINDSCREEN SEALANT / <i>ne</i>	S/N	\$	200.00	✓
27	SUNDRIES <i>7</i>		\$	600.00	X <i>nn</i>
TOTAL SPARE PARTS		:	\$	16,370.00	
TOTAL LABOUR CHARGES		:	\$	19,042.00	
GRAND TOTAL		:	\$	35,412.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

21 days