

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/A1522010467/Upa3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Dep 11k.

have video.

frl door 1244 Rear door 936 centre pillar 1486
alignment result out degree front RH NOT centre.

7/11/22 4/5 @ 11.800 in hand Florence.

Veh No: SMJ576SL Yr Regn: 12/03/19
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA
 Make: KIA Stonic c.c 998
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 51833 T/Radio: Insured / Std / NI / NA
 Eng/No:
 C/No: KNAD6811VK6 253060
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or -
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 185/65-15 R:
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front Rear
 R/Bal. 7 mm R/Bal. 7 mm
 L/Bal. 7 mm L/Bal. 7 mm
 D.O.A. 19/10/22 D.O.I. 21/10/22
 Survey held at
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Report Format :

Lump Sum / I.B.I: (\$)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Not Authorized

21/10/22

FC Garage

NO.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #04-03 Singapore 415875

Tel: 90110243

CO. Reg. No.: 53409207A

Model : **Kia Stonic**
 Registraion No : **SMJ 5765 L**
 Chassis No: **KNAD6811VK6253060**

2/5 @ 11,800
 10 days

Year of Manufacturing **2018**

S/No	Qty	Items	Unit Price	Amount
1	1	Front Fender RHS <i>Body DO</i>	\$ 452.30	\$ 452.30 ✓
2	1	Front Fender Shield RHS <i>Top</i>	\$ 85.40	\$ 85.40 ✓
3	1	Front Fender Arch RHS <i>Dis</i>	\$ 78.50	\$ 78.50 ✓
4	1	Front Bumper <i>Dis/Top</i> 493	\$ 626.50	\$ 626.50 ✓
5	1	Front Bumper Retainer RHS <i>cm</i>	\$ 45.60	\$ 45.60 ✓
6	1	Front Bumper Lower Lip <i>11</i>	\$ 382.50	\$ 382.50 X
7	1	Front Bonnet <i>2</i>	\$ 1,002.50	\$ 1,002.50 X
8	1	Front Door RHS <i>Dis</i>	\$ 959.60	\$ 959.60 ✓
9	1	Front Door Weatherstrip RHS <i>Top</i>	\$ 115.20	\$ 115.20 ✓
10	1	Front Door Inner Trim Board RHS <i>Del/Top</i>	\$ 637.20	\$ 637.20 ✓
11	1	Front Door Lock with Actuator RHS <i>Buf/Jm</i>	\$ 225.40	\$ 225.40 ✓
12	1	Front Door Power Window Regulator RHS <i>Buf</i>	\$ 256.70	\$ 256.70 ✓
13	1	Front Door Power Window Regulator Motor RHS <i>Jm</i>	\$ 386.40	\$ 386.40 ✓
14	1	Front Door Channel Assy RHS <i>11</i>	\$ 115.50	\$ 115.50 X
15	1	Front Door Handle RHS <i>cur</i>	\$ 165.40	\$ 165.40 ✓
16	1	Front Door Protector RHS <i>Buf</i>	\$ 95.20	\$ 95.20 ✓
17	1	Front Door Hinge Upper RHS <i>Buf</i>	\$ 59.40	\$ 59.40 ✓
18	1	Front Door Hinge Lower RHS <i>Buf</i>	\$ 59.40	\$ 59.40 ✓
19	1	Front Door Checker RHS <i>Tw</i>	\$ 59.40	\$ 59.40 ✓
20	1	Front Door Cynlinder Key Lock RHS <i>11</i>	\$ 265.40	\$ 265.40 X
21	1	Front Door Outer Moulding RHS <i>Buf</i>	\$ 69.50	\$ 69.50 ✓
22	1	Front Door Sticker HRS <i>neu</i>	\$ 26.50	\$ 26.50 ✓
23	1	Front Support Panel <i>11</i>	\$ 582.60	\$ 582.60 X
24	1	Front Reinforcement <i>11</i>	\$ 582.60	\$ 582.60 X
25	1	Front Side Mirror RHS <i>380</i> 610	\$ 628.50	\$ 628.50 ✓
26	1	Headlamp RHS <i>one</i> 1845	\$ 2,078.90	\$ 2,078.90 ✓
27	1	Rear Door RHS <i>Dis</i>	\$ 859.60	\$ 859.60 ✓
28	1	Rear Door Weatherstrip RHS <i>rec</i>	\$ 187.50	\$ 187.50 ✓
29	1	Rear Door Inner Trim Board RHS <i>Del/Top</i> 365	\$ 423.50	\$ 423.50 ✓
30	1	Rear Door Lock with Actuator RHS <i>Tw/Jm</i>	\$ 212.50	\$ 212.50 ✓
31	1	Rear Door Power Window Regulator RHS <i>Buf</i>	\$ 236.50	\$ 236.50 ✓
32	1	Rear Door Power Window Regulator Motor RHS <i>Jm</i>	\$ 233.20	\$ 233.20 ✓
33	1	Rear Door Handle RHS <i>11</i>	\$ 28.60	\$ 28.60 X
34	1	Rear Door Protector RHS <i>Buf</i>	\$ 105.30	\$ 105.30 ✓
35	1	Rear Door Hinge Upper RHS <i>Buf</i>	\$ 59.40	\$ 59.40 ✓

8584.1

36	1	Rear Door Hinge Lower RHS	Buf	\$	59.40	\$	59.40	/	
37	1	Rear Door Checker RHS	Buf	\$	59.40	\$	59.40	/	
38	1	Rear Door Outer Moulding RHS	Buf	\$	79.50	\$	79.50	/	
39	1	Rear Door Sticker	RHS		\$	26.50	\$	26.50	/
40	1	Rear Fender RHS	body	1066	\$	1,168.50	\$	1,168.50	/
41	1	Rear Fender Shield RHS	de		\$	86.50	\$	86.50	/
42	1	Rear Fender Arch RHS	du		\$	95.60	\$	95.60	/
43	1	Rocket Panel RHS	R		\$	1,311.20	\$	1,311.20	X
44	1	Tail Lamp RHS	^^		\$	287.60	\$	287.60	X
45	1	Front Subframe	^^		\$	736.20	\$	736.20	X
46	2	Front Subframe LHS & RHS Garnish	^^		\$	93.50	\$	187.00	X
47	1	Front RHS Absorber	^^		\$	322.20	\$	322.20	X
48	1	Front RHS Absorber Top Mounting	^^		\$	65.50	\$	65.50	X
49	1	Front RHS Lower Arm	Buf		\$	326.50	\$	326.50	/
50	1	Front RHS Knuckle	Buf		\$	387.90	\$	387.90	/
51	1	Front RHS Knuckle Hub	Buf		\$	212.50	\$	212.50	/
52	1	Front RHS Wheel Bearing	ru		\$	189.50	\$	189.50	/
53	1	Front RHS Stabilizer Link	^^		\$	125.50	\$	125.50	X
54	1	Front RHS Tie Rod	^^		\$	185.20	\$	185.20	X
55	1	Front RHS Tie Rod End	^^		\$	105.60	\$	105.60	X
56	1	Front LHS Absorber	^^		\$	322.20	\$	322.20	X
57	1	Front LHS Absorber Top Mounting	^^		\$	65.50	\$	65.50	X
58	1	Front LHS Lower Arm	^^		\$	326.50	\$	326.50	X
59	1	Front LHS Knuckle	^^		\$	387.90	\$	387.90	X
60	1	Front LHS Knuckle Hub	^^		\$	212.50	\$	212.50	X
61	1	Front LHS Wheel Bearing	^^		\$	189.50	\$	189.50	X
62	1	Front LHS Stabilizer Link	^^		\$	125.50	\$	125.50	X
63	1	Front LHS Tie Rod	^^		\$	185.20	\$	185.20	X
64	1	Front LHS Tie Rod End	^^		\$	105.60	\$	105.60	X
65	1	Front Driveshaft	^^		\$	960.10	\$	960.10	X
66	1	Steering Rack	^^		\$	1,024.50	\$	1,024.50	X
67	1	Rear Axle	^^		\$	1,102.20	\$	1,102.20	X
68	2	Rear Absorber LHS & RHS	^^		\$	264.50	\$	529.00	X
69	2	Rear Absorber Top Mounting LHS & RHS	^^		\$	96.50	\$	193.00	X
70	2	Rear Wheel Bearing RHS & LHS	^^		\$	382.60	\$	765.20	X
71	1	Centre Pillar RHS	DD/Buf		\$	1,455.20	\$	1,455.20	/
72	1	Centre Pillar Garnish RHS	^^		\$	165.20	\$	165.20	X
73	1	Front A Pillar Panel RHS	R		\$	1,184.20	\$	1,184.20	X
74	1	Front A Pillar Panel Inner Garnish RHS	^^		\$	185.60	\$	185.60	X

	<u>\$ 18,300.40</u>
-10%	\$ 1,830.04
Total for spare parts	<u>\$ 16,470.36</u>

Special Nett

1	20/sep	Front Bumper Clips	nee	\$	5.00	\$	50.00	30
2	1	Front Rim RHS	11	\$	800.00	\$	800.00	X
3	1	Front Tyre RHS	11	\$	400.00	\$	400.00	X
4	1	Rear Tyre LHS	11	\$	400.00	\$	400.00	X
5	1	Rear Rim LHS	11	\$	800.00	\$	800.00	X
6	10	Front A Pillar Garnish Clips	11	\$	5.00	\$	50.00	X
7	20/sep	Front Door Inner Trim Board Clips RHS	nee	\$	5.00	\$	50.00	30
8	20/sep	Rear Door Inner Trim Board Clips RHS	nee	\$	5.00	\$	50.00	30
9	20/sep	Front Fender Shield Clips RHS	nee	\$	5.00	\$	50.00	30
10	10	Rear Fender Shiled Clips RHS	11	\$	5.00	\$	50.00	X

Total for SP \$ 2,700.00
Sub-Total for Parts : \$ 19,170.36

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as- mention repair parts, inclusive of replacement parts	\$	1,800.00 1200
2		To putty and spray paint on all accident damage parts and other accident affected areas	\$	2,200.00 1300
3		Apply rust proofing on the adjacent panels	\$	80.00 90
4		To supply under coating / putty on parts replaced	\$	80.00
5		To perform water seepage test after repair	\$ 11	80.00 X
6		Dismantle and transfer front door fittings and mechanism to new front door/facilitate repair	\$	150.00 60
7		Dismantle and transfer rear door fittings and mechanism to new rear door/facilitate repair	\$	150.00 60
8		Disconned and check electrical wiring, harness, wire socket	\$	80.00 20
9		Reset engine management system with diagnostic fault	\$ 11	80.00 X
10		Check and re-adjust wheel alignment	\$	100.00 60

- | | | | | | |
|----|---|----|----|--------|-----|
| 11 | Remove and replace undercarraige (whole rear with axle) | 11 | \$ | 300.00 | X |
| 12 | Remove and replace front undercarraige | | \$ | 250.00 | 120 |
| 13 | Remove and refit window glass (inclusive of sealant and vacuum) | 11 | \$ | 80.00 | X |

TOTAL AMOUNT : \$ 5,430.00
OVERALL COST: \$ 24,600.36

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

P-13028-60

103
 11725.74

120

2810

14755.74

20%

11804