



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL  
50 RAFFLES PLACE #03-03  
SINGAPORE LAND TOWERSINGAPORE 048623

Ref: CS3/SMO22010468/y3

Date: 21/10/2022

Code: SMO

### 1. Policy Particulars :- (THIRD PARTY CLAIM)

<b>Insured Veh.</b>	SJV 5742A	<b>Veh. Inspected</b>	YM 9352K
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	CMTD2203819/SYH	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	GRACE TEO	<b>Assign Date</b>	21/10/2022

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>		<b>c.c</b>	0
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	
<b>Chassis No.</b>		<b>Colour</b>	
<b>Odometer</b>	-	<b>Steering</b>	
<b>Brakes</b>		<b>Modification</b>	
<b>General</b>			

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>			mm
<b>L/H Front Tyre</b>			mm
<b>R/H Rear Tyre</b>			mm
<b>L/H Rear Tyre</b>			mm

### 4. Description of Damages

--

### 5. General Information

<b>Accident Date</b>	20/10/2022	<b>Inspection Date</b>	
<b>Survey held at</b>	38 Woodlands Industries Park E1 #06-03 S 757700		
<b>Repairer</b>	HWA PENG AUTO SERVICE (1996)		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.  
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.