



AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721
TEL: 6456 3637 FAX: 6456 3686 Email: admin@almssm.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S: KARTHIK SEKAR
BLK BISHAN ST 24
#05-164
SINGAPORE 570267

Not Authorised
11 Reg \$2000
Pranny After Paint
4 days

Estimate No: MCS1900736
Date: 14 Oct 2022
Policy No: MA006376
Veh Reg No: SKZ5550D
Make/Model: SUBARU FORESTER

ATTN:
Your Ref No: SKZ5550D
Claim Type: Third Party
Accident Date: 13/10/2022
TP Veh Reg No: SDZ899P

Estimate Repair Cost to Vehicle No: SKZ5550D

Description	Quantity	List Price	Amount
		SS	SS
Nett			
1 FRONT BUMPER	1 PC	600.00	✓
2 FRONT BUMPER CLIP	10 PC	60.00	✓
3 FRONT BUMPER SIDE RETAINER RH	1 PC	22.00	✓
4 FRONT FENDER LH	1 PC	300.00	✓
5 FENDER COWLING CLIP	8 PC	48.00	✓
6 FRONT ALLOY RIM LH	1 PC	850.00	✓
		1,880.00	
	Less 10%	188.00	1,692.00
LABOUR			
7 TO CHECK WIRING AND REFOCUS HEADLAMP	1 PC	20.00	151
8 TO WHEEL ALIGNMENT	1 PC	80.00	601
9 TO DISMANTLE AND REPLACE DAMAGE PARTS, TO KNOCK, ALIGN AND REPAIR FRONT LH AFFECTED AREA	1 PC	500.00	4001
10 TO SPRAY FRONT FENDER LH AND FRONT BUMPER	1 PC	500.00	4001
		1,100.00	1,100.00
Total			SS 2,792.00
Add GST @ 7%			195.44
Total Amount Payable			SS 2,987.44

TOTAL: SINGAPORE DOLLAR TWO THOUSAND NINE HUNDRED EIGHTY SEVEN AND CENTS FORTY FOUR ONLY

For AH LIM MOTOR COMPANY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTHORISED SIGNATURE

