

輝陽汽車有限公司  
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721  
Tel: 64515752 (2 Lines) . Fax: 64514658  
GST & Reg No. 201629438M

AKG  
Kenneth  
17/10/22  
Monday

13/10/2022

Owner: TAN YONG HENG

Not withair  
11 Bay @ 2750p  
Melurray After Paint  
3day

**ESTIMATE TO REPAIR HONDA SHUTTLE HYBRID - SML6902R**

1pc	front LH headlamp	2250	Scr	\$ 2,550.00	✓
1pc	front LH headlamp lower bracket		\$ Pr	68.00	X
1pc	front centre grille base		Pr	495.00	X
1pc	front centre grille outer garnish		Pr	325.50	X
1pc	front centre grille "H" logo		nn	58.50	X
1pc	front centre grille lower chrome		Pr	215.00	X
1pc	front bumper	1050	Br/Pr	1,150.50	✓
10 20 pcs	front bumper clip @\$5.00		Pr	100.00	✓ 50
1pc	front bumper LH side retainer		Pr	55.00	✓
1pc	front bumper LH fog lamp		Pr	385.50	X
1pc	front bumper LH fog lamp garnish		Pr	185.50	X
1pc	front bumper LH fog lamp garnish top cover		Pr	78.50	X
1pc	front LH fender		Pr	598.50	X
1pc	front LH fender inner shield		Pr	235.20	X
10 pcs	front LH fender inner shield clip @\$5.00		nn	50.00	X

less 20%  
\$ 6,550.70  
\$ 1,310.14  
\$ 5,240.56

wiring \$ 60.00 152  
tuffkote nn \$ 60.00 X  
spray painting \$ 1,000.00 400  
labour charges \$ 1,000.00 300  
Total \$ 7,360.56



**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: