

ASS. REC. BY:

REF:

AIG/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

864084h

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

14

days

Res.:

Yes or No

Lum Sum:

1731 %

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHC 50484

Yr Regn:

11, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Puv

c.c

1798

Colour

m.p. white / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTOK B31FU 303 092766

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

17/10/22

D.O.I.

20/10/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

FR O/S

The UIC / Chassis frame / Body Structure affected due to collision. ✓

Date / Time

Action / Instruction

1 Got BT, Battery flat

Date/Time, File Pass to?

☐

Prell. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. \$

F.P. \$

Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5048U

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

20 OCT 2022*Not Authored
Penang B4 Point***AAD2210-****SHC5048U**

JTDKB3FU303092766

200303878K

TOYOTA

PRIUS GEN 4

17/10/2022

SLA7604P/AIG

20/11/2020

PART

- 1 COVER SUB-ASSY, FRONT PILLAR, UPR RH
- 1 FENDER SUB-ASSY, FRONT RH
- 1 LINER, FRONT FENDER, RH
- 1 EMBLEM, SIDE PANEL
- 1 FENDER SUB-ASSY, FRONT LH
- 1 LINER, FRONT FENDER, LH
- 1 EMBLEM, SIDE PANEL
- 1 HUB CAP
- 1 RIM
- 1 SUPPORT SUB-ASSY, RADIATOR, RH
- 1 SUPPORT SUB-ASSY, RADIATOR, LH
- 1 SUPPORT SUB-ASSY, RADIATOR, UPPER
- 1 COVER, RADIATOR SUPPORT OPENING
- 1 BAR, STABILIZER, FRONT
- 1 COVER, FRONT BUMPER
- 1 MOULDING, FRONT BUMPER SIDE, RH
- 1 MOULDING, FRONT BUMPER SIDE, LH
- 1 BRACKET, FRONT BUMPER EXTENSION MOUNTING
- 1 REINFORCEMENT SUB-ASSY, FRONT BUMPER
- 1 REINFORCEMENT, FRONT BUMPER, NO.2
- 1 ABSORBER, FRONT BUMPER, LOWER
- 1 ABSORBER, FRONT BUMPER ENERGY
- 1 SUPPORT, FRONT BUMPER SIDE, LH
- 1 SUPPORT, FRONT BUMPER SIDE, RH
- 1 COVER, ENGINE UNDER, NO.1
- 1 COVER SUB-ASSY, ENGINE UNDER, NO.2
- 1 EXTENSION, FRONT BUMPER, LH

LIST

\$	100.40	?
\$	<i>B</i> 977.80	✓
\$	<i>CM</i> 202.50	✓
\$	<i>MC</i> 54.60	✓
\$	<i>Bu</i> 977.80	✓
\$	<i>Bu</i> 210.30	X
\$	<i>MC</i> 54.60	✓
\$	<i>Bu</i> 211.50	X
\$	<i>Bu</i> 1,900.10	X
\$	<i>B</i> 245.10	✓
\$	<i>B</i> 245.10	✓
\$	<i>B</i> 377.10	✓
\$	211.50	?
\$	353.60	?
\$	<i>B</i> 521.00	✓
\$	<i>CM</i> 95.60	✓
\$	<i>Bu</i> 95.60	X
\$	<i>DIT</i> 110.50	✓
\$	<i>B</i> 716.60	✓
\$	246.10	?
\$	<i>CM</i> 132.70	✓
\$	<i>CM</i> 80.20	✓
\$	82.30	?
\$	<i>CM</i> 80.10	✓
\$	472.40	?
\$	241.90	?
\$	<i>MC</i> 120.10	X

Trans-cab Auto Services Pte Ltd

AAD2210-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5048U

- 1 EXTENSION, FRONT BUMPER, RH
- 1 STAY SUB-ASSY, FRONT BUMPER, RH
- 1 STAY SUB-ASSY, FRONT BUMPER, LH
- 1 BRACKET, FRONT BUMPER SIDE, LH
- 1 BRACKET, FRONT BUMPER SIDE, RH
- 1 COVER, FRONT BUMPER HOLE, RH
- 1 COVER, FRONT BUMPER HOLE, LH
- 1 BRACKET, HEADLAMP, RH
- 1 BRACKET, HEADLAMP, LH
- 1 LAMP ASSY, FOG, LH
- 1 LAMP ASSY, FOG, RH
- 1 UNIT ASSY, HEADLAMP, LH
- 1 COMPUTER SUB-ASSY, HEADLAMP, LH NO.1
- 1 UNIT ASSY, HEADLAMP, RH
- 1 COMPUTER SUB-ASSY, HEADLAMP, RH NO.1
- 1 GRILLE SUB-ASSY, RADIATOR
- 1 EMBLEM ASSY, MOULDING
- 1 GRILLE, RADIATOR, LOWER NO.1
- 1 EMBLEM ASSY, RADIATOR GRILLE
- 1 HOOD SUB-ASSY
- 1 LOCK ASSY, HOOD
- 1 HINGE ASSY, HOOD, LH
- 1 HINGE ASSY, HOOD, RH
- 1 INSULATOR, HOOD
- 1 BRACE, HOOD LOCK SUPPORT
- 1 LOCK ASSY, HOOD
- 1 WIRE, ENGINE ROOM MAIN
- 1 CLEANER ASSY, AIR
- 1 INLET, AIR CLEANER, NO.1
- 1 INLET, AIR CLEANER, NO.3
- 1 INLET, AIR CLEANER, NO.2
- 1 HOSE, AIR CLEANER, NO.1
- 1 JAR ASSY, WINDSHIELD WASHER
- 1 MOTOR AND PUMP ASSY, WINDSHIELD WASHER
- 1 INLET SUB-ASSY, WASHER
- 1 CONDENSER ASSY, COOLER
- 1 HOSE SUB-ASSY, SUCTION

\$	DIT	120.10	✓
\$	Bt	47.50	✓
\$	Sm	47.50	X
\$	Ln	59.30	X
\$	Q11	59.30	✓
\$	M11	30.20	✓
\$	M11	30.20	✓
\$	CM1	34.80	✓
\$	Sm	34.80	X
\$		237.10	?
\$	M11	237.10	✓
\$	M11 CM	2,637.60	✓
\$		3,772.50	?
\$	Bt	2,637.60	✓
\$		3,772.50	?
\$	CM	422.50	✓
\$	Ln	160.50	✓
\$	CM	178.60	✓
\$	CM1	105.80	✓
\$	Bt	983.10	✓
\$	Bt	135.00	✓
\$	Bt	58.90	✓
\$	Bt	58.90	✓
\$	Refum	410.90	✓
\$	Bt	78.30	✓
\$	Refum	135.00	X
\$		7,323.90	?
\$	CM	1,147.00	✓
\$		155.60	?
\$		42.10	?
\$		112.70	?
\$		74.00	?
\$	Ref	219.10	✓
\$		292.40	?
\$		67.00	?
\$	Bt	1,783.20	✓
\$		646.80	?

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2210-**SHC5048U**

1	HOSE SUB-ASSY, DISCHARGE	\$	402.90	7
1	PIPE SUB-ASSY, SUCTION	\$	465.80	7
1	SENSOR, AIRCONDITIONER PRESSURE	\$	342.80	7
1	TUBE & ACCESSORY ASSY, AIR CONDITIONER	\$	691.00	7
1	COMPRESSOR ASSY, W/MOTOR	\$	4,771.60	7
1	RADIATOR ASSY	\$	<i>Rs</i> 2,218.00	✓
1	TANK ASSY, INVERTER RESERVE	\$	443.00	7
1	COCK ASSY, RESERVE TANK	\$	139.00	7
1	INVERTER WATER PUMP ASSY(W/MOTOR)	\$	518.60	7
1	MOTOR, COOLING FAN, LH	\$	655.10	7
1	MOTOR, COOLING FAN, RH	\$	535.50	7
1	COOLER, MOTOR COOLING	\$	297.20	7
1	WIRE, ENGINE ROOM MAIN	\$	7,323.90	7
1	CLAMP SUB-ASSY, BATTERY	\$	<i>Rs</i> 115.50	X
1	BATTERY	\$	1,584.90	7
1	JAR ASSY, WINDSHIELD WASHER	\$	219.10	7
1	AIR BAG ASSY, INSTRUMENT PANEL PASSENGER W/O DOOR	\$	<i>Rs</i> 3,869.30	✓
1	AIR BAG ASSY, INSTRUMENT PANEL, LOWER NO.1	\$	✓ 1,907.00	✓
1	AIR BAG ASSY, CURTAIN SHIELD, LH	\$	✓ 1,748.10	✓
1	AIR BAG ASSY, CURTAIN SHIELD, RH	\$	✓ 1,748.10	✓
1	AIR BAG ASSY, FRONT SEAT, RH	<i>Rs</i> \$	<i>Rs</i> 1,008.80	+
1	AIR BAG ASSY, FRONT SEAT, LH	<i>Rs</i> \$	<i>Rs</i> 1,008.80	+
1	SENSOR ASSY, SIDE AIR BAG, LH, NO.2	\$	<i>Rs</i> 709.30	✓
1	SENSOR ASSY, SIDE AIR BAG, RH, NO.2	\$	<i>Rs</i> 709.30	✓
1	COMPUTER ASSY, AIR BAG	\$	<i>Rs</i> 1,546.00	✓
1	SENSOR, AIR BAG, FRONT LH	\$	<i>Rs</i> 373.90	✓
1	SENSOR, AIR BAG, FRONT RH	\$	<i>Rs</i> 373.90	✓
1	HEADLINING ASSY, ROOF	\$	<i>Rs</i> 2,125.70	✓
1	BELT ASSY, FRONT SEAT OUTER, RH	\$	<i>Rs</i> 995.10	✓
1	BELT ASSY, FRONT SEAT OUTER, LH	\$	<i>Rs</i> 995.10	✓
1	BELT ASSY, REAR SEAT 3 POINT TYPE, OUTER LH	\$	<i>Rs</i> 995.10	✓
1	BELT ASSY, REAR SEAT 3 POINT TYPE, OUTER RH	\$	<i>Rs</i> 995.10	✓
TOTAL		\$	56,270.90	
25%		\$	14,067.73	
		\$	42,203.18	

Special Nett

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2210-

SHC5048U

- 1 FRT NUMBER PLATE WITH HOLDER
- 1SET BUMPER CLIP FRT
- 1 TYRE
- 1SET FRNT BUMPER RETAINER CLIP
- 4L Radiator Coolant
- 1 HOOD INSULATOR CLIP
- 1 Engine Under Cover Clip
- 2 FRT FENDER LINER CLIP

\$	mil	140.00	45m
\$	mm	95.00	60m
\$	sm	350.00	X
\$	mm	85.00	λ
\$	mm	120.00	30m
\$	mm	55.00	✓
\$		60.00	?
\$	Nec	130.00	✓
TOTAL		\$	905.00

TOTAL PARTS	\$	43,108.18
--------------------	-----------	------------------

LABOUR

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$	mm	380.00	X
----	----	--------	---

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$		4,500.00	100d
----	--	----------	------

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$	mm	380.00	X
----	----	--------	---

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$	mm	180.00	X
----	----	--------	---

To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.

\$		480.00	5d
----	--	--------	----

To transfer of Fender fittings, attachments and perform water seepage test.

\$	mm	480.00	X
----	----	--------	---

To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.

\$		380.00	100d
----	--	--------	------

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$		380.00	?
----	--	--------	---

Trans-cab Auto Services Pte Ltd

AAD2210-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5048U

To check steering geometry and computer wheel alignment	\$	220.00	601
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	1201
Towing Fees	\$	150.00	601
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00	13201
To reinstall rear bumper parking sensor.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn 220.00	X
To replace, refix and top up coolant for radiator	\$	170.00	501
To lift-up / out engine with gear box and refit.	\$	440.00	?
To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.	\$	380.00	?
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	nn 380.00	X
TOTAL		\$	12,290.00
Over All Total		\$	55,398.18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

(PART-BY-PART) Repair Days

25 DAYS

14 days

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Actual Driver**
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 18/10/2022 16:43 (SGT)
Reported by Driver
Date of Accident 17/10/2022 06:30 (SGT)
Exact Location of Accident Singapore
Additional Location Information ALONG ANG MO KIO AVE 6 BEFORE ANG MO KIO AVE 9
JUNCTION TOWARDS LENTOR
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHC5048U

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner TRANS-CAB SERVICES PTE LTD
Company Reg No 2XXXXX878K
Email Address claims@transcab.com.sg
Mobile Phone No (Phone) +65-62876666
Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Toyota
Model Prius
Variant -
Exact purpose for which vehicle was being used at time of accident Private hire
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Taxi
Transmission Auto
CC 1798

INSURANCE COMPANY

Name of Insurance Company AXA Insurance Pte Ltd
Policy Number / Cover Note Number VFX/P2413997

DRIVER

Name of Driver TONG CHEE HIONG
NRIC No SXXXX990B
Date Of Birth 24/09/1957

Occupation	Outdoor
Date Of Driving Pass	23/08/1979
Driving experience	43 YEARS AND 2 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96693067
Alt. Phone Number	-
Email Address	Claims@transcab.com.sg
Address	HDB Hougang, 165 Hougang Avenue 1
Address complement	-
Postcode	530165
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Cross Junction
Weather Conditions	Raining
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	Yes
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Ang Mo Kio North Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18004849999
Alt. Police Station Phone No	(Fax) +65-62181399
Police Station Address	51 Ang Mo Kio Avenue 9 Singapore 569784
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO POLICE REPORT NO.T/20221018/2063

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLA7604P
Vehicle Manufacturer	Kia
Vehicle Model	Forte

Vehicle Variant	-
Vehicle Colour	Black
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	2

PASSENGER 1

Name	P1
Gender	Female

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	TONG CHEE HIONG
Gender	Male
Phone No	(Phone) +65-96693067
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	-
Were seat belts worn?	SHC5048U
Was this injured conveyed to hospital by ambulance?	Yes


INJURED 2

Name of injured person	MALE DRIVER
Gender	Male
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	-
Were seat belts worn?	SLA7604P
Was this injured conveyed to hospital by ambulance?	Yes

INJURED 3

Name of injured person	FEMALE PASSENGER
Gender	Female
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	-
Were seat belts worn?	SLA7604P
Was this injured conveyed to hospital by ambulance?	Yes

ACCIDENT DIAGRAM



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed By Reporting Officer
Ang Qi Hao, Victor
Witnessed by Reporting Centre
Personnel



**SINGAPORE
POLICE FORCE**



T/20221018/2063

1 of 3

Report No. T/20221018/2063

Police Station Of Origin:
Ang Mo Kio North N.P.C
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No: 1800-4849999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:
18/10/2022 15:11

Vide Report No.:

Station Diary No.:
34

Informant's Particulars

Name of Informant:
TONG CHEE HIONG

Address:
APT BLK 165 HOUGANG AVENUE 1 #05-1608 SINGAPORE
530165

ID Type / ID No.:
NRIC NO / S1263990B

Contact No.:
Home/Office: Mobile: 96693067

Nationality:
SINGAPORE CITIZEN

Email:

Sex: Male Age: 65 Date of Birth: 24/09/1957

Type of Informant:
Driver

Race:
Chinese

Language:
English

Institution / School Name:

Occupation:
Taxi driver

Driving Licence Information:
Class: Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 17/10/2022 06:30	Type of Location: Straight Road
Location: ANG MO KIO AVENUE 6				
Weather: Raining	Road Surface: Wet	Road Speed Limit:		
Traffic Flow: One Way	Traffic Control: Not Controlled	Traffic Volume: Light		
Type of Collision: Between Moving Vehicles - Head On				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHC5048U	Car					0
SLA7804P	Car					0



**SINGAPORE
POLICE FORCE**



T/20221018/2063

2 of 3

Report No. T/20221018/2063

Police Station Of Origin:
Ang Mo Kio North N.P.C
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No: 1800-4849999

CONTINUATION OF REPORT

Brief Details.

Reference to report number F/20221017/0040

On 17/10/2022 at about 0630hrs I was traveling along ang Mo Kio Ave 6 towards Lentor.

I was at the junction between the Ang Mo Kio Ave 6 and the road from the bus interchange where the buses come out .

Suddenly I saw two headlights coming towards me from the opposite direction. I quickly pressed the brakes to avoid the impact.

Unfortunately the car (SLA 7604P) directly banged onto my car at the front .

After few seconds I came out of my car and saw a motor cycle at the center of the junction. Th motorcyclist then pointed me to a car (SLA7604P) .

I then approached the car and the driver was inspecting his car. He admitted that he drove into my lane accidently and banged onto my car .

Ambulance came and conveyed me and the motorcyclist to KTPH .

I was given 7 days of medical leave.

damage to my car :

- 1) the front portion completely damaged
- 2) the rear tyres were punctured

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

878K

Vehicle Details

Vehicle No.:

SHC5048U

Vehicle to be Exported:

Yes

Intended Deregistration Date:

19 Oct 2022

Vehicle Make:

TOYOTA

Vehicle Model:

PRIUS 5DR HATCHBACK (AUTO)

Primary Colour:

Red

Manufacturing Year:

2020

Engine No.:

2ZR2H21048

Chassis No.:

JTDKB3FU303092766

Maximum Power Output:

90.0 kW (120 bhp)

Open Market Value:

\$26,807.00

Original Registration Date:

20 Nov 2020

First Registration Date:

20 Nov 2020

Transfer Count:

0

Actual ARF Paid:

\$14,530.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

19 Nov 2028

PARF Rebate Amount:

\$10,897.00

Intended COE Rebate Details

COE Expiry Date:

19 Nov 2028

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

8

PQP Paid:

\$29,180.00

COE Rebate Amount:

\$22,188.00

Total Rebate Amount:

\$33,085.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 19 Oct 2022

OK