

MBM WHEELPOWER PTE. LTD.

YOUR REF.: GX9023R
 OUR REF.: SMG921B

*Not Authorized
 Murray B4 pair
 4 days
 11 Sep @ 3750h*



TO: CHINA TAIPING
 CC: MOTOR CLAIMS DEPARTMENT

DATE: 1/11/2022
 FROM: Lee Shirley
 FAX: 64525333
 CONTACT: 86865188
 MAKE & MODEL: MERCEDES GLA180 SE A
 CHASSIS NO.: WDC1569422J465656
 ENGINE NO.: 27091031514350
 YEAR MADE: 2018
 ACCIDENT DATE: 12 October 2022

STIMATE FOR VEHICLE NO.: SMG921B

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	TAILGATE <i>1907.90</i>		1	\$ <i>21</i> 2,168.00 ✓
2	TAILGATE WEATHERSTRIP		1	\$ <i>Sm</i> 237.00 X
3	TAILGATE HINGE LH		1	\$ <i>R</i> 99.00 X
4	TAILGATE HINGE RH		1	\$ <i>R</i> 99.00 X
5	TAILGATE STAY LH		1	\$ <i>Sm</i> 703.00 X
6	TAILGATE STAY RH		1	\$ <i>Sm</i> 297.00 X
7	TAILGATE LOCK		1	\$ <i>R</i> 297.00 X
8	TAILGATE REVERSE CAMERA		1	\$ <i>NIP</i> 2,158.00 X
9	TAILGATE LICENSE PLATE		1	\$ <i>Sm</i> 103.00 X
10	TAILGATE MERCEDES LOGO		1	\$ <i>Ne</i> 52.00 ✓
11	TAILGATE TRIM STRIP		1	\$ <i>Sm</i> 148.00 X
12	TAILGATE "GLA180" EMBLEM		1	\$ <i>Ne</i> 91.00 ✓
13	TAILGATE LAMP LH		1	\$ <i>Sm</i> 505.00 X
14	TAILGATE LAMP RH		1	\$ <i>Sm</i> 505.00 ↑
15	REAR BUMPER		1	\$ <i>Red/Blue</i> 1,228.00 ✓
16	REAR BUMPER REINFORCEMENT		1	\$ <i>R</i> 650.00 X
7	REAR BUMPER SENSOR		4	\$ <i>Sm</i> 1,000.00 X
8	REAR BUMPER CLIP		10	\$ <i>Ne</i> 80.00 ✓
9	REAR BUMPER LOWER SPOILER <i>605</i>		1	\$ <i>Red</i> 680.00 ✓
10	REAR BUMPER SIDE RETAINER LH		1	\$ <i>Sm</i> 75.00 X
	REAR BUMPER SIDE RETAINER RH		1	\$ <i>Sm</i> 75.00 ↑
	REAR BUMPER TOWING COVER		1	\$ <i>Sm</i> 91.00 X
	REAR BUMPER BRACKET		1	\$ <i>R</i> 75.00 X
	TAIL LAMP LH		1	\$ <i>Sm</i> 760.00 X
	TAIL LAMP RH		1	\$ <i>Sm</i> 760.00 X
	END PANEL		1	\$ <i>R</i> 1,400.00 X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

MBM WHEELPOWER PTE. LTD.
 160 SIN MING DRIVE, #06-02
 SIN MING AUTOCITY
 t 6262 8888 f 6452 5333
 COMPANY REG. NO.: 200204110W

27 END PANEL TOP GARNISH

1	\$	<i>Sn</i>	130.00	X
TOTAL:		\$	14,466.00	
LESS 10%:		\$	(1,446.60)	
PARTS TOTAL:		\$	13,019.40	

SPECIAL NETT

NUMBER PLATE & HOLDER
BODY SEALANT

1	\$	<i>Sn</i>	50.00	X
1	\$	<i>nn</i>	50.00	X

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS
TO CHECK & RECONNECT ALL NECESSARY WIRING
TO REMOVE & REFIT ALL SENSOR
TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)
TO APPLY ANTI RUST COATING
TO SPRAY PAINT ON THE AFFECTED AREAS

	\$	<i>50d</i>	1,400.00	
	\$	<i>2d</i>	150.00	
	\$	<i>6d</i>	80.00	
	\$	<i>nn</i>	250.00	X
	\$	<i>3d</i>	80.00	
	\$	<i>50d</i>	1,200.00	
TOTAL:		\$	16,279.40	
7% GST:		\$	1,139.56	
GRAND TOTAL:		\$	17,418.96	

MBM WHEELPOWER PTE. LTD.

160 SIN MING DRIVE, #06-02

SIN MING AUTOCITY

t 6262 8888 f 6452 5333

COMPANY REG. NO.: 200204110W