



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile CS3/ASM21008468/Tvy3-1

AXA INSURANCE PTE LTD

8 SHENTON WAY #24-01 AXA TOWER
SINGAPORE 068811

ATTN: TAN JUN HONG

Ref: ~~CS3/ASM21008468/Tvy3-1~~

Date: ~~10/08/2021~~ 21/10/2022

Code: ASM

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SHA 1277L	Veh. Inspected	SMV 2820S
Policy No.		Coverage (\$)	0.00
Claim No.	S1M03FFG	Excess (\$)	0.00
Assign From	TAN JUN HONG HENG XINYI (SEAH ONG)	Assign Date	10/08/2021 21/10/2022

2. Vehicle Particulars & Condition

Make & Model	TOYOTA NOAH HYBRID	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	ZWR800434571	Colour	WHITE
Odometer	70644 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	DAVANTI	6 mm
L/H Front Tyre	195/65 R15	DAVANTI	6 mm
R/H Rear Tyre	195/65 R15	DAVANTI	6 mm
L/H Rear Tyre	195/65 R15	DAVANTI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.
--

5. General Information

Accident Date	11/08/2021	Inspection Date	13/08/2021
Survey held at	APEX MOTORING 25 KAKI BUKIT ROAD 4 #01-55 SYNERGY @ KB SINGAPORE 417800		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$7,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------