

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance
(Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 26 Oct 2022

Preliminary Advice

Vehicle No	: SMH7887R	Accident Date	: 03/10/2022
Make	: NISSAN SYLPHY	Policy No.	: DMPCSNW00009672201
Assignment Date	: 21/10/2022	Excess	: S\$1,000.00
Date of Inspection	: 25/10/2022	Est. Duration of Repair	: 5
Inspection At	: AP AUTOMOTIVE SERVICES PTE LTD (HQ) BLK 9006 TAMPINES STREET 93, #01-202 SINGAPORE 528840		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,571.12
Revised Amount	:S\$	7,343.34
Check Items (Estimated)	:S\$	2,620.08
Total	:S\$	9,963.42

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	70,000.00
COE / PARF Rebate	:S\$	28,284.00

Salvage Value	:S\$
Margin for Repair	:S\$ 41,716.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

- (X) Other comments :
kindly advise the repairer whether can using the list prices instead of cost plus as repairer is not authorise workshop.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.