





not Authorized  
 LLL  
 Meray  
 HP 90096608  
 S455591000  
 25/10/22

AP AUTOMOTIVE SERVICES PTE LTD  
 ROC / GST REG NO : 202022890H  
 BLOCK 9006  
 TAMPINES STREET 93 #01-202  
 SINGAPORE 528840  
 TEL: 6784 4465  
 FAX: 6787 4886

ESTIMATION

2/5 # 6800  
 5 days

DATE :  
 VEHICLE : SMH7887R  
 MAKE / MODEL : NISSAN SYLPHY 1.6 CVT

Not item

No.	Description	Unit	Unit Price	Amount
<b>PART REPLACEMENT</b>				
	FRONT BUMPER	1	\$ 598.00	\$ 598.00
	FRONT BUMPER FOGLAMP	2	\$ 258.00	\$ 516.00
	FRONT BUMPER FOGLAMP GARNISH	2	\$ 124.00	\$ 248.00
	FRONT BUMPER TOW HOOK COVER	1	\$ 29.00	\$ 29.00
	FRONT BUMPER LOWER GRILLE	1	\$ 290.00	\$ 290.00
	FRONT BUMPER SPONGE	1	\$ 234.00	\$ 234.00
	FRONT BUMPER REINFORCEMENT	1	\$ 572.00	\$ 572.00
	FRONT BUMPER ABSORB BRACKET LH	1	\$ 216.20	\$ 216.20
	FRONT BUMPER SIDE RETAINER	2	\$ 24.10	\$ 48.20
	FRONT BUMPER UNDERCOVER GARNISH	1	\$ 202.00	\$ 202.00
	HEADLAMP	2	\$ 815.00	\$ 1,630.00
	HEADLAMP INNER LOWER BRACKET	2	\$ 29.00	\$ 58.00
	HEADLAMP LOWER BRACKET	2	\$ 30.00	\$ 60.00
	CENTRAL GRILLE	1	\$ 250.00	\$ 250.00
	CENTRAL GRILLE TOP SUPPORT BRACKET	2	\$ 20.00	\$ 40.00
	CENTRAL GRILLE LOGO	1	\$ 65.00	\$ 65.00
	CENTRAL GRILLE CHROME	1	\$ 765.00	\$ 765.00
	BONNET	1	\$ 911.40	\$ 911.40
	BONNET HINGE	2	\$ 45.00	\$ 90.00
	BONNET INSULATOR	1	\$ 168.00	\$ 168.00
	BONNET STOPPER	2	\$ 19.00	\$ 38.00
	BONNET LOCK	1	\$ 42.00	\$ 42.00
	FRONT SUPPORT PANEL (TOP CENTRE)	1	\$ 155.00	\$ 155.00
	FRONT SUPPORT PANEL (LOWER CENTRE)	1	\$ 435.00	\$ 435.00
	FRONT SUPPORT PANEL (SIDE)	2	\$ 83.00	\$ 166.00
	FRONT SUPPORT PANEL TOP GRANISH	1	\$ 404.00	\$ 404.00
	FRONT SUPPORT BRACE PANEL	1	\$ 87.00	\$ 87.00
	RADIATOR	1	\$ 970.00	\$ 970.00
	RADIATOR SPARE TANK	1	\$ 254.00	\$ 254.00
	RADIATOR FAN COWLING	1	\$ 232.00	\$ 232.00
	AIR CONDENSOR	1	\$ 823.00	\$ 823.00
	AIR CON CONDENSOR SIDE GARNISH	1	\$ 196.00	\$ 196.00
	HORN	2	\$ 101.00	\$ 202.00

✓ 577.90  
 X  
 X  
 ✓ 20.00  
 X  
 ✓ 202.40  
 ✓ 561.90  
 X  
 ✓  
 X  
 ✓ 50  
 X  
 X  
 ✓ 48  
 ✓ 891.20  
 X  
 X  
 ✓ 125  
 ✓ 785  
 X  
 X  
 ✓ 148  
 X

TEMPERATURE SENSOR	17	1	\$ 138.00	\$ 138.00
FRONT FUSE BOX	17	1	\$ 150.00	\$ 150.00
FRONT FENDER	ntsr obsuc	2	\$ 722.00	\$ 1,444.00
FRONT FENDER INNER COWLING	17	2	\$ 115.00	\$ 230.00
			<b>Total</b>	\$ 12,956.80
			<b>Less 10%</b>	\$ 1,295.68
			<b>Sub Total</b>	\$ 11,661.12

X  
X  
120  
X

S/NETT ITEMS				
FRONT NUMBER PLATE	net	1	\$ 120.00	\$ 120.00
FRONT BUMPER CLIP (SET)	net	1	\$ 80.00	\$ 80.00
FRONT BUMPER UNDERCOVER GARNISH CLIP (SET)	17	1	\$ 80.00	\$ 80.00
CENTRAL GRILLE CLIP (SET)	17	1	\$ 60.00	\$ 60.00
BONNET INSULATOR CLIP (SET)	17	1	\$ 60.00	\$ 60.00
FRONT SUPPORT PANEL TOP GRANISH CLIP (SET)	net	1	\$ 60.00	\$ 60.00
AIR CON CONDENSOR SIDE GARNISH CLIP (SET)	17	1	\$ 60.00	\$ 60.00
FRONT FENDER COWLING CLIP (SET)	17	2	\$ 80.00	\$ 160.00
RADIATOR COOLANT	net	1	\$ 120.00	\$ 120.00
			<b>Total</b>	\$ 120.00

40  
30  
X  
X  
X  
30  
X  
X  
20

**LABOUR**

PANEL BEATING ON AFFECTED AREAS		1	\$ 1,600.00	\$ 1,600.00
SPRAY PAINTING ON AFFECTED AREAS		1	\$ 1,400.00	\$ 800.00
CHECK WIRING AND HEAD LAMP FUNCTIONS		1	\$ 120.00	\$ 120.00
REMOVE AND REFIT A/C CONDESER AND REFILL A/C GAS		1	\$ 120.00	\$ 120.00
REMOVE AND REFIT REVERSE SENSOR AND CHECK FUNCTIONS		1	\$ 260.00	\$ 260.00
REMOVE AND REFIT RADIATOR AND CONDUCT PRESSURE TEST		1	\$ 350.00	\$ 350.00
COMPUTERISED DIAGNOSTIC TEST AND CLEAR FAULT CODES		1	\$ 300.00	\$ 300.00
TO APPLY RUST PROOFING		1	\$ 240.00	\$ 240.00
			<b>Part Replacement Amount</b>	\$ 11,781.12
			<b>Total Amount For Labour</b>	\$ 3,790.00
			<b>Total Amount</b>	\$ 15,571.12

600  
750  
20  
100  
17X  
17X  
17X  
17X

7-7811-6  
102  
7030-44  
120  
1470  
8620-44  
202  
6896

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: