

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 25 Oct 2022

Preliminary Advice

Vehicle No	: SFL963L	Accident Date	: 15/10/2022
Make	: MAZDA CX-30	Policy No.	: SP2002660176
Assignment Date	: 21/10/2022	Excess	: S\$700.00
Date of Inspection	:	Est. Duration of Repair	: 3 DAYS
Inspection At	:		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,607.50
Revised Amount	:S\$	3,634.00
Check Items (Estimated)	:S\$	2,037.00
Total	:S\$	5,671.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	122,000.00
COE / PARF Rebate	:S\$	47,728.00
Salvage Value	:S\$	
Margin for Repair	:S\$	74,272.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments : Part by Part repair.

Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.