

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	M6508
Policy No:	SP2002660176	Date of Loss:	15/10/2022
Vehicle Reg. No.:	SFL963L	Driveable?	YES
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	AWANG BIN HAMID		
Driver:	AWANG BIN HAMID		
Make/Model:	MAZDA CX-30, 2.0 ELEGANCE (A)	Vehicle Reg. Date:	24/08/2020
Vehicle Colour:	Metallic Dark Grey	Gen Condition:	Fair
Engine No:	PE31574512	Chassis No:	JM6DM2W7AL010110
Odometer:	55145 KM		
Paint Type:	Metallic 2K		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	AUTO INSURE PTE LTD (HQ) (WOODLANDS)		

COST OF CLAIMS	Amount
Parts	5,307.50
Miscellaneous Items	300.00
Labour	1,200.00
Paintwork Labour	800.00
Towing	0.00
Calculated Gross Total (S\$)	7,607.50
- Excess (S\$)	700.00
(S\$)	6,907.50
+ GST 7.00% (S\$)	483.53
Nett Amount (S\$)	7,391.03

This claim is handled by: **MARVYN CHUA HONG LENG**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Oct 2022)
Parts:	M1-SUV	MAZDA CX-30 2.0 ELEGANCE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Auto Insure Pte Ltd (HQ)/SFL963L/21/10/2022 12:27	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR WINDSCREEN	0.00	0.00	*520.00 F
2	1		*REAR TAILGATE	0.00	0.00	*820.00 F
3	1		*REAR BUMPER	0.00	0.00	*580.00 F
4	1		*REAR WINDSCREEN MOULDING	0.00	0.00	-
5	1		*REAR TAILGATE UPPER MOULDING	0.00	0.00	-
6	1		*REAR TAILGATE CENTER MOULDING	0.00	0.00	*420.00 F
7	1		*REAR TAILGATE HINGE RH	0.00	0.00	*35.00 F
8	1		*REAR TAILGATE HINGE LH	0.00	0.00	*35.00 F
9	1		*REAR TAILGATE LOCK	0.00	0.00	*540.00 F
10	1		*REAR TAILLAMP OUTER LH	0.00	0.00	*280.00 F
11	1		*REAR TAILLAMP INNER LH	0.00	0.00	*420.00 F
12	1		*REAR TAILLAMP INNER RH	0.00	0.00	*420.00 F
13	1		*REAR TAILLAMP OUTER RH	0.00	0.00	*280.00 F
14	1		*REAR BUMPER REFLECTOR RH	0.00	0.00	*45.00 F
15	1		*REAR BUMPER REFLECTOR LH	0.00	0.00	*45.00 F
16	1		*REAR BUMPER REINFORCEMENT	0.00	0.00	*385.00 F

F=Franchise part.

Sub Total (S\$)	4,825.00
+ Margin on L,N Items 10.00% (S\$)	482.50
Total Parts (S\$)	5,307.50

Auto Insure Pte Ltd (HQ)/SFL963L/21/10/2022 12:27. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	REAR BUMPER CLIPS	50.00
2	1	REAR PARKING SENSORS	250.00
Sub Total (\$\$)			300.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	LABOUR FOR SPRAY PAINTING	New	800.00
<u>Labour Items</u>			
2	LABOUR FOR PANEL BEATING	New	800.00
3	LABOUR TO REMOVE & REFIT REAR TAILGATE MECHANISM	New	200.00
4	LABOUR TO REMOVE & REFIT REAR PARKING SENSORS	New	200.00
Gross Labour Cost (\$\$)			2,000.00

Auto Insure Pte Ltd (HQ)/SFL963L/21/10/2022 12:27. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >