

Celine Fong (LKKAUTO)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Friday, 10 February 2023 3:11 PM
To: Taufikh (LKKAUTO); SUR; Celine Fong (LKKAUTO); Carrine Leong;
jiayee.yap@premiumauto.com.sg; Chang Chee Sing;
glory.tan@premiumauto.com.sg
Subject: FINAL REVISION - SLU7364B - OD AIG - SURVEYED 21 OCT 22
Attachments: PA09072022 - SLU 7364 B - AUDI A3 SEDAN 1.0 TFSI 8V - FRONT & REAR - AIG
(OD) + SUPP.xlsx; RESURVEY SLU7364B.pdf

H Taufikh and all,

Revised estimate, re-survey docs attached. Photographs will be forwarded from Benoi - Glory Tan.

Pls confirm repair cost of \$67,713.60 @ 37 days exclude 6 Sunday. (Limit Repair 52K)

Your early closure is appreciated.

ASIDE GLORY - Pls assist to forward photos to Taufikh - LKK

Best regards - Johnny Boo

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0907/2022/EQ
DATE : 19-Oct-22
WIP : 46713

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 20/10/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Taufikh

27 ~~37~~ days exclude 6

Johnny Boo 10 Feb

OWNER'S NAME : MR CHONG MINGYONG
ADDRESS : BLK 167C SIMEI LANE
#07-28
SINGAPORE 523167
TELEPHONE : HP +65 90108531
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO :
VEHICLE NO : **SLU 7364 B**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 12/12/2017
ENGINE NO : CHZ 584011
CHASSIS NO : WAUZZZ8V9J1024727
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-Oct-22
PLACE OF ACCIDENT : PIE (TOWARDS TUAS), AFTER STEVENS EXIT,
LAMP POST 929

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLU 7364 B - FRONTAL

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00	\$	360.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	700.00	\$	500.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$	1,400.00	\$	1,400.00
4	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR.	S/N \$	280.00	\$	280.00
5	TO RENEW FRONT WINDSCREEN.	S/N \$	480.00		
TOTAL LABOUR CHARGES		:	\$ 3,220.00	\$	2,540.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLU 7364 B - FRONTAL

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>c/f</i>		\$ 2,540.00
6	TO INSTALL SOLAR FILM FOR ALL AFFECTED GLASSES.	S/N \$	400.00	
7	TO CARRY OUT WATER SEEPAGE TEST FOR ALL THE AFFECTED WINDSCREEN.	S/N \$	200.00	
8	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	5,600.00	\$ 2,750.00
9	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, HINGES, LHS FRONT DOOR AND LHS UPPER A-PILLAR.	\$	5,500.00	\$ 2,300.00
TOTAL LABOUR CHARGES		:	\$ 14,920.00	\$ 7,590.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLU 7364 B - REAR

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
	<i>c/f</i>			\$ 7,590.00
1	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR O-LINER.	S/N \$	800.00	\$ 800.00
2	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION.	S/N \$	280.00	\$ 280.00
3	TO RENEW RHS 1/4 GLASS AND REAR WINDSCREEN TO FACILLITATE FENDER RENEWAL.	S/N \$	600.00	na
4	TO REMOVE AND REINSTALL REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$	280.00	\$ 280.00
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,400.00	\$ 1,400.00
TOTAL LABOUR CHARGES		:	\$ 6,580.00	\$ 10,350.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLU 7364 B - REAR

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>c/f</i>		\$ 10,350.00
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,400.00	\$ 1,400.00
7	TO DISMANTLE AND REINSTALL CENTER CONSOLE. RENEW AIRBAG CONTROL UNIT AND BOTH FRONT SEATBELT.	S/N \$	1,800.00	\$ 1,800.00
8	TO REMOVE AND REINSTALL EXHAUST SYSTEM AND REAR SUSPENSION ASSEMBLY. RENEW ACCORDINGLY.	S/N \$	2,800.00	\$ 2,800.00
9	TO REMOVE AND REINSTALL FUEL TANK ASSY.	S/N \$	600.00	\$ 600.00
10	TO SETUP VEHICLE ON CAR-O-LINER FOR REPAIR.	S/N \$	2,400.00	\$ 2,400.00
TOTAL LABOUR CHARGES		:	\$ 12,220.00	\$ 19,350.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLU 7364 B - REAR

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
	<i>c/f</i>		\$ 19,350.00
11	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. CUT OUT AND WELD REAR END PANELLING, SPARE WHEEL HOUSING AND RHS REAR FENDER. RE-ALIGN RHS REAR CHASSIS FRAME INTO POSITION. REPAIR LHS REAR FENDER. RE-ORGANIZE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 11,900.00	\$ 5,500.00
12	TO CARRY OUT STONE CHIP PRIMER WORK ON REAR PANELLING AND SPARE WHEEL HOUSING.	S/N \$ 780.00	\$ 780.00
13	TO RESPRAY REAR BUMPER, REAR LID, HINGES, BOTH REAR FENDER, RHS SILL PANEL, DRAIN PANEL, ROOF CHANNEL, DOOR ENTRANCES, END PANELLING AND SPARE WHEEL HOUSING. TO CARRY OUT STONE CHIP TREATMENT, CAVITY PRESERVATION AND JOINT SEALER WORKS.	\$ 7,500.00	\$ 2,850.00
14	TO CARRY OUT WHEEL ALIGNMENT.	S/N \$ 240.00	\$ 240.00
15	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	\$ 384.00
TOTAL LABOUR CHARGES - FRONT & REAR		\$ 57,744.00	\$ 29,104.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 7364 B - FRONT

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,432.00	\$	1,945.60
2	FRONT BUMPER FIXING PARTS	1	\$ 195.00		
3	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 86.00	\$	34.24
4	FRONT BUMPER GRILLE - CENTER	1	\$ 179.00		
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 571.00		
6	FRONT BUMPER CLOSING ELEMENT - LH / RH	2	\$ 636.00	\$	254.40
7	FRONT BUMPER TRIM COVER - LH / RH	2	\$ 364.00		
8	FRONT WHEEL HOUSING LINER ADAPTER - LH / RH	2	\$ 84.00		
9	RADIATOR GRILLE	1	\$ 1,578.00	\$	1,262.40
10	RADIATOR GRILLE CLOSING ELEMENT	1	\$ 210.00	\$	168.00
11	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 420.00		
12	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 847.00	\$	677.20
13	FRONT BUMPER FOAM FILLER PIECE	1	\$ 211.00	\$	168.80
14	FRONT BUMPER REINFORCEMENT BEAM COVER	1	\$ 136.00	\$	108.80
15	HORN HIGH TONE - LH	1	\$ 213.00	\$	170.00
16	HORN LOW TONE - RH	1	\$ 213.00		
17	AIR CONDITIONER STICKER	1	\$ 9.00	\$	6.64
18	CAUTION SIGN STICKER	1	\$ 16.00	\$	12.40
19	FRONT FENDER - LH / RH	2	\$ 1,908.00	\$	763.20
20	FRONT FENDER ATTACHMENT PARTS	1	\$ 75.00		
SUB TOTAL SPARE PARTS		:	\$ 10,383.00	\$	5,571.68

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 7364 B - FRONT

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		c/f		\$	5,571.68
21	FRONT FENDER BRACKET - LH / RH	2	\$ 92.00	\$	36.40
22	FRONT FENDER RIVET	11	\$ 42.00	\$	33.44
23	FRONT FENDER BRACE	1	\$ 107.00	\$	85.60
24	FRONT WHEEL HOUSING LINER - LH / RH	2	\$ 366.00	\$	146.40
25	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 93.00		
26	BONNET	1	\$ 3,348.00	\$	2,678.40
27	BONNET ATTACHMENT PARTS	1	\$ 172.00		
28	BONNET HINGE - LH / RH	2	\$ 136.00	\$	108.48
29	BONNET EDGE PROTECTION	1	\$ 31.00	\$	24.72
30	BONNET CATCH HOOK	1	\$ 100.00	\$	79.44
31	BONNET STRIKER - LH / RH	2	\$ 246.00	\$	196.00
32	BONNET SIDE SEAL - LH	1	\$ 46.00		
33	BONNET CATCH HOOK	1	\$ 71.00	\$	56.32
34	BONNET LOCK - LH / RH	2	\$ 455.00	\$	364.00
35	BONNET BOWDEN CABLE - CENTER	1	\$ 64.00	\$	50.56
36	BONNET BOWDEN CABLE COVER	1	\$ 11.00		
37	BONNET LOCK CABLE	1	\$ 82.00		
38	EXHAUST SOUND ABSORBER	1	\$ 244.00		
39	PLENUM CHAMBER COVER	1	\$ 199.00	\$	159.20
40	HEADLIGHT - LH / RH	2	\$ 11,758.00	\$	9,406.40
SUB TOTAL SPARE PARTS		:	\$ 17,663.00	\$	18,997.04

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 7364 B - FRONT

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		c/f		\$	18,997.04
41	LIFT CYLINDER - LH / RH	2	\$	312.00	
42	LIFT CYLINDER HOSE	1	\$	78.00	
43	LOCK CARRIER	1	\$	806.00	\$ 644.80
44	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$	21.00	\$ 16.32
45	A/C CONDENSER	1	\$	570.00	\$ 456.00
46	A/C CONDENSER REFRIGERATN LINE	1	\$	500.00	
47	A/C CONDENSER REFRIGERANT LINE	1	\$	570.00	
48	A/C CONDENSER REFRIGERANT LINE	1	\$	623.00	
49	RADIATOR ADDITIONAL COOLER	1	\$	961.00	\$ 768.00
50	RADIATOR	1	\$	1,064.00	
51	READY-MIX COOLANT	6	\$	297.00	\$ 237.12
52	RADIATOR FAN WITH FAN RING	1	\$	1,617.00	
53	RADIATOR AIR GUIDE - LH / RH	2	\$	56.00	\$ 44.32
54	RADIATOR OUTER SEAL - RH	1	\$	9.00	\$ 7.12
55	RADIATOR AIR GUIDE - UPPER CENTRE	1	\$	14.00	\$ 10.88
56	RADIATOR COVER	1	\$	30.00	\$ 23.84
57	RADIATOR AIR GUIDE	1	\$	59.00	\$ 46.56
58	RADIATOR WATER DRAINAGE HOSE	1	\$	37.00	
59	RADIATOR AIR GUIDE	1	\$	21.00	
60	RADIATOR AIR GUIDE	1	\$	69.00	
SUB TOTAL SPARE PARTS		:	\$	7,714.00	\$ 21,252.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 7364 B

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		c/f		\$	21,252.00
61	RADIATOR AIR FILTER	1	\$ 337.00		
62	RADIATOR INTAKE MANIFOLD	1	\$ 788.00		
63	FRONT WINDSCREEN	1	\$ 1,206.00		
64	FRONT WINDSCREEN RAIN SENSOR GEL FOIL	1	\$ 131.00		
65	SPRING CLIP	1	\$ 23.00		
66	WINDSCREEN PRIMER	1	\$ 22.00		
67	WINDSCREEN WATER DEFLECTOR STRIP - LH	1	\$ 104.00	\$	82.80
68	WINDOW SLOT SEAL TRIM STRIP - LH	1	\$ 346.00		
69	WINDOW GUIDE TRIM STRIP - LH	1	\$ 287.00		
70	FRONT NO PLATE	S/N	\$ 60.00	\$	60.00
71	FRONT WINDSCREEN SEALANT	S/N	\$ 200.00		
TOTAL SPARE PARTS - FRONT		:	\$ 39,264.00	\$	21,394.80

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 7364 B - REAR

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		c/f		\$	21,394.80
1	REAR BUMPER	1	\$ 2,317.00	\$	1,853.60
2	REAR BUMPER FIXING PARTS	1	\$ 201.00		
3	REAR WHEEL HOUSING LINER ADAPTER - LH / RH	2	\$ 84.00	\$	33.60
4	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 36.00	\$	28.80
5	REAR BUMPER LOCKING MECHANISM - LH / RH	2	\$ 67.00	\$	26.48
6	REAR BUMPER SPOILER	1	\$ 264.00	\$	210.80
7	REAR BUMPER REFLECTOR - LH / RH	2	\$ 92.00	\$	36.48
8	REAR OUTER TAIL LIGHT - LH / RH	2	\$ 1,948.00	\$	778.80
9	REAR OUTER TAIL LIGHT TRIM - LH / RH	2	\$ 68.00	\$	52.96
10	REAR INNER TAIL LIGHT - LH / RH	2	\$ 1,948.00	\$	778.80
11	REAR INNER TAIL LIGHT TRIM - LH / RH	2	\$ 68.00		
12	REAR LICENCE PLATE LIGHT - LH / RH	2	\$ 210.00		
13	REAR BUMPER REINFORCEMENT BEAM	1	\$ 642.00	\$	513.20
14	REAR BUMPER BRACKET - LH / RH	2	\$ 63.00	\$	49.84
15	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 149.00		
16	REAR PARKING AID SENSOR - INNER / OUTER	4	\$ 1,062.00	\$	424.00
17	REAR PARKING AID SEAL RING	4	\$ 10.00	\$	8.00
18	REAR BUMPER WIRING SET	1	\$ 572.00	\$	457.20
19	REAR BUMPER AERIAL KEY ACCESS	1	\$ 79.00	\$	62.88
20	REAR LID	1	\$ 3,657.00	\$	2,925.60
SUB TOTAL SPARE PARTS		:	\$ 13,537.00	\$	29,635.84

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 7364 B - REAR
DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		c/f	\$	29,635.84
21	REAR LID ATTACHMENT PARTS	1 \$	308.00	
22	REAR LID HINGE - LH / RH	2 \$	570.00	\$ 456.00
23	REAR LID FLAP GASKET	1 \$	229.00	\$ 182.80
24	REAR LID LOCK STRIKER	1 \$	56.00	\$ 44.40
25	REAR LID LOCK	1 \$	211.00	\$ 168.80
26	REAR LID LOCK COVER	1 \$	8.00	\$ 6.32
27	REAR LID LOCK ACTUATOR PUSH BUTTON	1 \$	1,478.00	
28	REAR LID LOCK ACTUATOR COVER	1 \$	18.00	
29	PACKING ADHESIVE	1 \$	21.00	\$ 16.80
30	AUDI EMBLEM	1 \$	144.00	\$ 114.80
31	"A3" INSCRIPTION	1 \$	104.00	\$ 82.80
32	"TFSI" INSCRIPTION	1 \$	104.00	\$ 82.80
33	REAR SIDE PANEL - RH	1 \$	4,445.00	
34	REAR WINDOW	1 \$	905.00	
35	REAR QUARTER WINDOW - RH	1 \$	635.00	
36	WINDOW PRIMER	2 \$	44.00	
37	REAR FUEL POCKET	1 \$	100.00	
38	REAR FUEL POCKET HOSE	1 \$	20.00	
39	REAR WHEEL HOUSING LINER - LH / RH	2 \$	520.00	\$ 208.00
40	REAR VENT TRIM	1 \$	75.00	
SUB TOTAL SPARE PARTS		:	\$ 9,995.00	\$ 30,999.36

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 7364 B - REAR

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT		REMARKS	
		<i>c/f</i>		\$		30,999.36
41	REAR CROSS PANEL	1	\$	379.00	\$	303.20
42	REAR CROSS PANEL REINFORCEMENT	1	\$	773.00	\$	618.00
43	REAR CROSS PANEL CONNECTING PLATE - LH / RH	2	\$	322.00	\$	256.80
44	REAR CROSS PANEL BOTTOM PLATE	1	\$	737.00	\$	589.20
45	REAR CROSS PANEL MOUNT BRACKET	1	\$	91.00	\$	72.40
46	REAR CROSS PANEL TRIM	1	\$	171.00	\$	136.80
47	REAR LUGGAGE COMPARTMENT FLOOR COVERING	1	\$	602.00	\$	481.20
48	REAR LUGGAGE COMPARTMENT TRIM - RH	1	\$	841.00		
49	REAR LID TRIM PANEL	1	\$	345.00	\$	276.00
50	REAR STOWAGE COMPARTMENT	1	\$	105.00	\$	84.00
51	REAR SILENCER	1	\$	825.00		
52	EXHAUST SYSTEM RETAINER	2	\$	95.00		
53	EXHAUST HEAT SHIELD	1	\$	180.00		
54	THREE-POINT AUTOMATIC SEAT BELT - LH / RH	2	\$	2,454.00	\$	1,963.20
55	SEAT BELT HEIGHT ADJUSTER - LH / RH	2	\$	430.00	\$	344.00
56	AIRBAG CONTROL UNIT	1	\$	1,923.00	\$	1,585.60
57	REAR FUEL POCKET	1	\$	100.00		
58	REAR FUEL POCKET HOSE	1	\$	20.00		
59	REAR WHEEL HOUSING LINER - LH / RH	2	\$	520.00		
60	REAR VENT TRIM	1	\$	75.00		
SUB TOTAL SPARE PARTS			:	\$	10,988.00	\$ 37,709.76

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 7364 B - REAR

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		c/f		\$	37,709.76
61	REAR NO PLATE	S/N	\$ 60.00		
62	REAR WINDSCREEN SEALANT	S/N	\$ 200.00		
63	ACRYLIC SEALANT	S/N	\$ 180.00	\$	180.00
64	CAVITY WAX	S/N	\$ 140.00	\$	140.00
65	STONE CHIP	S/N	\$ 180.00	\$	180.00
66	METAL FILLER POWDER	S/N	\$ 280.00	\$	280.00
67	ADD PARTS		\$ 26.00	\$	20.24
68	SUNDRIES		\$ 1,000.00	\$	99.60
TOTAL SPARE PARTS - FRONT & REAR			\$ 75,850.00	\$	38,609.60
TOTAL LABOUR CHARGES - FRONT & REAR			\$ 57,744.00	\$	29,104.00
GRAND TOTAL			\$ 133,594.00	\$	67,713.60

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-03/01/23

**Supplementary Estimate-1**

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0907/2022/EQ 21-Nov-22 CHANG 1 of 1 SLU 7364 B AUDI A3 SEDAN 1.0 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	LASHING EYE - LOWER 1	\$ 26.00	\$ 20.24
	GRAND TOTAL	\$ 26.00	\$ 20.24

For Premium Automobiles Pte Ltd

Authorised Signature