

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0907/2022/EQ
DATE : 19-Oct-22
WIP : 46713

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 20/10/2022

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR CHONG MINGYONG
ADDRESS : BLK 167C SIMEI LANE
#07-28
SINGAPORE 523167
TELEPHONE : HP +65 90181837
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO :
VEHICLE NO : SLU 7364 B
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 12/12/2017
ENGINE NO : CHZ 584011
CHASSIS NO : WAUZZZ8V9J1024727
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-Oct-22
PLACE OF ACCIDENT : PIE (TOWARDS TUAS), AFTER STEVENS EXIT,
LAMP POST 929

PREMIUM AUTOMOBILES




55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLU 7364 B - FRONTAL

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00 ✓	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 700.00 250 500	
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00 ? ✓	
4	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR.	S/N \$ 280.00 ✓	
5	TO RENEW FRONT WINDSCREEN.	S/N \$ 480.00 ? X m	
TOTAL LABOUR CHARGES		: \$ <u>3,220.00</u>	

PREMIUM AUTOMOBILES




55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLU 7364 B - FRONTAL

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO INSTALL SOLAR FILM FOR ALL AFFECTED GLASSES.	S/N \$ 400.00	? X m
7	TO CARRY OUT WATER SEEPAGE TEST FOR ALL THE AFFECTED WINDSCREEN.	S/N \$ 200.00	? X m
8	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,600.00	1500 + 1250 ²⁷⁵⁰
9	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, HINGES, LHS FRONT DOOR AND LHS UPPER A-PILLAR. <i>24 LH fender</i>	\$ 5,500.00	23.00
TOTAL LABOUR CHARGES		\$ 14,920.00	

PREMIUM AUTOMOBILES




55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLU 7364 B - REAR

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR O-LINER.	S/N \$ 800.00	? <i>pink</i> ✓
2	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION.	S/N \$ 280.00	✓
3	TO RENEW RHS 1/4 GLASS AND REAR WINDSCREEN TO FACILLITATE FENDER RENEWAL.	S/N \$ 600.00	X <i>mm</i>
4	TO REMOVE AND REINSTALL REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$ 280.00	✓
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$ 1,400.00	✓ <i>HSE</i>
TOTAL LABOUR CHARGES		\$ 6,580.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLU 7364 B - REAR

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$ 1,400.00	? /
7	TO DISMANTLE AND REINSTALL CENTER CONSOLE. RENEW AIRBAG CONTROL UNIT AND BOTH FRONT SEATBELT.	S/N \$ 1,800.00	✓ /
8	TO REMOVE AND REINSTALL EXHAUST SYSTEM AND REAR SUSPENSION ASSEMBLY. RENEW ACCORDINGLY.	S/N \$ 2,800.00	? /
9	TO REMOVE AND REINSTALL FUEL TANK ASSY.	S/N \$ 600.00	? /
10	TO SETUP VEHICLE ON CAR-O-LINER FOR REPAIR.	S/N \$ 2,400.00	? /
TOTAL LABOUR CHARGES		\$ 12,220.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLU 7364 B - REAR

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
11	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. CUT OUT AND WELD REAR END PANNELLING, SPARE WHEEL HOUSING AND RHS REAR FENDER. RE-ALIGN RHS REAR CHASSIS FRAME INTO POSITION. REPAIR LHS REAR FENDER. RE-ORGANIZE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	S 11,900.00	2500 + 2500. (spare tire housing) + 1000 \$00 (chassis frame) = 5500 3000
12	TO CARRY OUT STONE CHIP PRIMER WORK ON REAR PANNELLING AND SPARE WHEEL HOUSING.	S/N S 780.00	✓
13	TO RESPRAY REAR BUMPER, REAR LID, HINGES, BOTH REAR FENDER, RHS SILL PANEL, DRAIN PANEL, ROOF CHANNEL, DOOR ENTRANCES, END PANNELLING AND SPARE WHEEL HOUSING. TO CARRY OUT STONE CHIP TREATMENT, CAVITY PRESERVATION AND JOINT SEALER WORKS.	S 7,500.00	2850
14	TO CARRY OUT WHEEL ALIGNEMENT.	S/N S 240.00	✓
15	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N S 384.00	✓
TOTAL LABOUR CHARGES - FRONT & REAR		\$ 57,744.00	

EXTRA - 14 days
 Rane

PREMIUM AUTOMOBILES




55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 7364 B - FRONT

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	S	2,432.00 <i>de</i> ✓ 1945.60
2	FRONT BUMPER FIXING PARTS	1	S	195.00 <i>X nn</i>
3	FRONT BUMPER GUIDE SECTION - LH / RH <i>cm</i>	2	S	85.00 <i>?</i> ✓ 34.24
4	FRONT BUMPER GRILLE - CENTER	1	S	179.00 <i>X nn</i>
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	S	571.00 <i>X nn</i>
6	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>cm</i>	2	S	635.00 <i>?</i> ✓ 254.40
7	FRONT BUMPER TRIM COVER - LH / RH	2	S	364.00 <i>X nn</i>
8	FRONT WHEEL HOUSING LINER ADAPTER - LH / RH	2	S	84.00 <i>X nn</i>
9	RADIATOR GRILLE	1	S	1,578.00 <i>cm</i> ✓ 126.40
10	RADIATOR GRILLE CLOSING ELEMENT <i>cm</i>	1	S	210.00 <i>?</i> ✓ 168.00
11	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	S	420.00 <i>X nn</i>
12	FRONT BUMPER REINFORCEMENT BEAM <i>bl</i>	1	S	847.00 <i>?</i> ✓ 677.20
13	FRONT BUMPER FOAM FILLER PIECE	1	S	211.00 <i>de</i> ✓ 168.80
14	FRONT BUMPER REINFORCEMENT BEAM COVER	1	S	136.00 <i>de</i> ✓ 108.80
15	HORN HIGH TONE - LH <i>cm</i>	1	S	213.00 <i>?</i> ✓ 170.00
16	HORN LOW TONE - RH	1	S	213.00 <i>X nn</i>
17	AIR CONDITIONER STICKER	1	S	9.00 <i>rec</i> ✓ 6.64
18	CAUTION SIGN STICKER	1	S	16.00 <i>rec</i> ✓ 12.40
19	FRONT FENDER - LH / RH	2	S	1,908.00 <i>LH bt</i> ✓, <i>RH X</i> #63.20
20	FRONT FENDER ATTACHMENT PARTS	1	S	75.00 <i>X nn</i>
SUB TOTAL SPARE PARTS			\$	10,383.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES




55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 7364 B - FRONT

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	FRONT FENDER BRACKET - LH / RH	2	\$	RHx ⁿⁿ 92.00	LH bt 36.40
22	FRONT FENDER RIVET	11	\$	42.00	new 33.44
23	FRONT FENDER BRACE	1	\$	107.00	2 85.60
24	FRONT WHEEL HOUSING LINER - LH / RH	2	\$	366.00	2 146.40
25	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$	93.00	X nn
26	BONNET	1	\$	3,348.00	bt 2678.40
27	BONNET ATTACHMENT PARTS	1	\$	172.00	X nn
28	BONNET HINGE - LH / RH	2	\$	136.00	bt photo 108.48
29	BONNET EDGE PROTECTION	1	\$	31.00	new 24.72
30	BONNET CATCH HOOK	1	\$	100.00	2 79.44
31	BONNET STRIKER - LH / RH	2	\$	246.00	2 196.00
32	BONNET SIDE SEAL - LH	1	\$	46.00	X nn
33	BONNET CATCH HOOK	1	\$	71.00	2 56.32
34	BONNET LOCK - LH / RH	2	\$	455.00	2 364.00
35	BONNET BOWDEN CABLE - CENTER	1	\$	64.00	2 50.56
36	BONNET BOWDEN CABLE COVER	1	\$	11.00	X 7
37	BONNET LOCK CABLE	1	\$	82.00	X nn
38	EXHAUST SOUND ABSORBER	1	\$	244.00	X
39	PLENUM CHAMBER COVER	1	\$	199.00	cut 159.20
40	HEADLIGHT - LH / RH	2	\$	11,758.00	RH LH cut 9406.40
SUB TOTAL SPARE PARTS			\$	17,663.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 7364 B - FRONT

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	LIFT CYLINDER LH RH X	2	\$ 312.00	? X un
42	LIFT CYLINDER HOSE	1	\$ 78.00	? X un
43	LOCK CARRIER	1	\$ 806.00	? 644.80
44	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 21.00	? 16.32
45	A/C CONDENSER	1	\$ 570.00	? 456.00
46	A/C CONDENSER REFRIGERANT LINE	1	\$ 500.00	X } un
47	A/C CONDENSER REFRIGERANT LINE	1	\$ 570.00	X }
48	A/C CONDENSER REFRIGERANT LINE	1	\$ 623.00	X }
49	RADIATOR ADDITIONAL COOLER	1	\$ 961.00	? 768.00 bt
50	RADIATOR	1	\$ 1,064.00	X un
51	READY-MIX COOLANT	6	\$ 297.00	? 237.12
52	RADIATOR FAN WITH FAN RING	1	\$ 1,617.00	X un
53	RADIATOR AIR GUIDE LH RH	2	\$ 56.00	? 44.32
54	RADIATOR OUTER SEAL - RH	1	\$ 9.00	? 7.12
55	RADIATOR AIR GUIDE - UPPER CENTRE	1	\$ 14.00	? 10.88
56	RADIATOR COVER	1	\$ 30.00	? 23.84
57	RADIATOR AIR GUIDE	1	\$ 59.00	? 46.56
58	RADIATOR WATER DRAINAGE HOSE	1	\$ 37.00	X }
59	RADIATOR AIR GUIDE	1	\$ 71.00	X }
60	RADIATOR AIR GUIDE	1	\$ 69.00	X }
SUB TOTAL SPARE PARTS		:	\$ 7,714.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55, UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 7364 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	RADIATOR AIR FILTER	1 \$	337.00	X
62	RADIATOR INTAKE MANIFOLD	1 \$	788.00	X
63	FRONT WINDSCREEN	1 \$	1,206.00	X
64	FRONT WINDSCREEN RAIN SENSOR CEL FOIL	1 \$	131.00	X
65	SPRING CLIP	1 \$	23.00	X
66	WINDSCREEN PRIMER	1 \$	22.00	X
67	WINDSCREEN WATER DEFLECTOR STRIP - LH	1 \$	104.00	de ✓ 82.80
68	WINDOW SLOT SEAL TRIM STRIP - LH	1 \$	346.00	X un
69	WINDOW GUIDE TRIM STRIP - LH	1 \$	287.00	X un
70	FRONT NO PLATE	S/N \$	60.00	b/v 60.00
71	FRONT WINDSCREEN SEALANT	S/N \$	200.00	X un
TOTAL SPARE PARTS - FRONT		:	\$ 39,264.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 7364 B - REAR


S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	REAR BUMPER	1	\$	2,317.00 <i>de</i>	1853.60
2	REAR BUMPER FIXING PARTS	1	\$	201.00 <i>X nn</i>	
3	REAR WHEEL HOUSING LINER ADAPTER - LH / RH	2	\$	<i>LH X nn</i> 84.00 <i>RH X nn</i> 33.60	
4	REAR BUMPER GUIDE SECTION - LH / RH <i>1 pc</i>	2	\$	<i>LH X nn</i> 36.00 <i>RH X nn</i> 28.80	
5	REAR BUMPER LOCKING MECHANISM - LH / RH	2	\$	<i>LH X nn</i> 67.00 <i>RH X nn</i> 26.48	
6	REAR BUMPER SPOILER	1	\$	264.00 <i>de</i>	210.80
7	REAR BUMPER REFLECTOR - LH / RH	2	\$	<i>RH X nn</i> 92.00 <i>LH X nn</i> 36.48	
8	REAR OUTER TAIL LIGHT - LH / RH <i>cut</i>	2	\$	<i>RH X nn</i> 1,948.00 <i>LH cut</i> 778.80	
9	REAR OUTER TAIL LIGHT TRIM - LH / RH <i>cut</i>	2	\$	68.00 <i>cut</i>	50.96
10	REAR INNER TAIL LIGHT - LH / RH <i>cut</i>	2	\$	1,948.00 <i>cut</i>	778.80
11	REAR INNER TAIL LIGHT TRIM - LH / RH <i>X nn</i>	2	\$	68.00 <i>X nn</i>	
12	REAR LICENCE PLATE LIGHT - LH / RH	2	\$	210.00 <i>X nn</i>	
13	REAR BUMPER REINFORCEMENT BEAM	1	\$	642.00 <i>bt - photo</i>	513.20
14	REAR BUMPER BRACKET - LH / RH	2	\$	63.00 <i>bt</i>	49.84
15	REAR BUMPER GUIDE SECTION - LH / RH	2	\$	149.00 <i>X nn</i>	
16	REAR PARKING AID SENSOR - INNER / OUTER	2	\$	1,062.00 <i>mis</i>	424.00
17	REAR PARKING AID SEAL RING	4	\$	10.00 <i>nn</i>	8.00
18	REAR BUMPER WIRING SET	1	\$	572.00 <i>7</i>	457.20 <i>nn</i>
19	REAR BUMPER AERIAL KEY ACCESS	1	\$	79.00 <i>7 mis</i>	62.88
20	REAR LID	1	\$	3,657.00 <i>bt</i>	2925.60

SUB TOTAL SPARE PARTS

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

\$ 13,537.00

PREMIUM AUTOMOBILES




55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 7364 B - REAR

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR LID ATTACHMENT PARTS	1	\$ 308.00	<i>308.00</i>
22	REAR LID HINGE - LH / RH	2	\$ 570.00	<i>456</i>
23	REAR LID FLAP CASKET	1	\$ 229.00	<i>182.80</i>
24	REAR LID LOCK STRIKER	1	\$ 56.00	<i>44.40</i>
25	REAR LID LOCK <i>cut</i>	1	\$ 211.00	<i>168.80</i>
26	REAR LID LOCK COVER <i>cut</i>	1	\$ 8.00	<i>6.32</i>
27	REAR LID LOCK ACTUATOR PUSH BUTTON	1	\$ 1,478.00	<i>X nn</i>
28	REAR LID LOCK ACTUATOR COVER	1	\$ 18.00	<i>X nn</i>
29	PACKING ADHESIVE	1	\$ 21.00	<i>16.80</i>
30	AUDI EMBLEM	1	\$ 144.00	<i>114.80</i>
31	"A3" INSCRIPTION	1	\$ 104.00	<i>82.80</i>
32	"TFSI" INSCRIPTION	1	\$ 104.00	<i>82.80</i>
33	REAR SIDE PANEL - RH	1	\$ 4,445.00	<i>X</i>
34	REAR WINDOW	1	\$ 905.00	<i>X</i>
35	REAR QUARTER WINDOW - RH	1	\$ 635.00	<i>X</i>
36	WINDOW PRIMER	2	\$ 44.00	<i>X nn</i>
37	REAR FUEL POCKET	1	\$ 100.00	<i>X</i>
38	REAR FUEL POCKET HOSE	1	\$ 20.00	<i>X</i>
39	REAR WHEEL HOUSING LINER - LH / RH	2	\$ 520.00	<i>208.00 de</i>
40	REAR VENT TRIM	1	\$ 75.00	<i>X nn</i>
SUB TOTAL SPARE PARTS			\$ 9,995.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 7364 B - REAR

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	REAR CROSS PANEL	1	\$ 379.00	bt 303.20
✓ 42	REAR CROSS PANEL REINFORCEMENT	1	\$ 773.00	? 618.00 bt
✓ 43	REAR CROSS PANEL CONNECTING PLATE - LH/RH	2	\$ 322.00	? 256.80 bt
✓ 44	REAR CROSS PANEL BOTTOM PLATE	1	\$ 737.00	? 589.20 bt
✓ 45	REAR CROSS PANEL MOUNT BRACKET	1	\$ 91.00	? 73.40 bt
46	REAR CROSS PANEL TRIM	1	\$ 171.00	del 136.80
47	REAR LUGGAGE COMPARTMENT FLOOR COVERING	1	\$ 602.00	2na 481.20
48	REAR LUGGAGE COMPARTMENT TRIM - RH	1	\$ 841.00	X un
49	REAR LID TRIM PANEL	1	\$ 345.00	fn 276.00
✓ 50	REAR STOWAGE COMPARTMENT	1	\$ 105.00	? 84.00 de
51	REAR SILENCER	1	\$ 825.00	X un
52	EXHAUST SYSTEM RETAINER	2	\$ 95.00	X un
53	EXHAUST HEAT SHIELD	1	\$ 180.00	X un
54	THREE-POINT AUTOMATIC SEAT BELT - LH / RH	2	\$ 2,454.00	act 1963.20
✓ 55	SEAT BELT HEIGHT ADJUSTER - LH/RH	2	\$ 430.00	? 344.00 act
56	AIRBAG CONTROL UNIT	1	\$ 1,923.00	new 1585.60 act
57	REAR FUEL POCKET	1	\$ 100.00	X
58	REAR FUEL POCKET HOSE	1	\$ 20.00	X
59	REAR WHEEL HOUSING LINER - LH / RH	2	\$ 520.00	X
60	REAR VENT TRIM	1	\$ 75.00	X
SUB TOTAL SPARE PARTS			\$ 10,988.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 7364 B - REAR

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
61	REAR NO PLATE	S/N S	60.00	ent ✓ X an
62	REAR WINDSCREEN SEALANT	S/N S	200.00	X an
63	ACRYLIC SEALANT	S/N S	180.00	an ✓ 180.00
64	CAVITY WAX	S/N S	140.00	an ✓ 140.00
65	STONE CHIP	S/N S	180.00	an ✓ 180.00
66	METAL FILLER POWDER	S/N S	280.00	an ✓ 280.00
67	SUNDRIES	S	1,000.00	an ✓ 99.60
TOTAL SPARE PARTS - FRONT & REAR			\$ 75,824.00	
TOTAL LABOUR CHARGES - FRONT & REAR			\$ 57,744.00	
GRAND TOTAL			\$ 133,568.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Tanflm 97495749
WPS Not Authorise Ex to be release
tanflm@khairto.com
17 days
Resurvey before paint
4 21/10/27 @ 330pm

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT




PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

GST Reg No. 19-9902271-W


AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0907/2022/EQ
21-Nov-22
CHANG
1 of 1
SLU 7364 B
AUDI A3 SEDAN 1.0 TFSI

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	LASHING EYE - LOWER <i>cm</i>	\$ 26.00	20.24
GRAND TOTAL		\$ 26.00	

For Premium Automobiles Pte Ltd



Authorised Signature