

Vehicle Damage Assessment Report for [SKA9191L]

Estimate Created: 25/10/2022 14:52 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 19/12/2022 05:59 by Insurlogic 1 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	iii	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Nissan	Model	Kicks
Engine Type			
License Plate Number	SKA9191L	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
FRONT DOOR RH		1	978.30	0.00 %	978.30
FRONT DOOR OUTER HANDLE RH		1	121.50	0.00 %	121.50
FRONT DOOR HANDLE KNOB RH		1	35.00	0.00 %	35.00
FRONT DOOR OUTER PROTECTOR RH		1	241.00	0.00 %	241.00
FRONT DOOR INNER LOCK RH		1	166.50	0.00 %	166.50
FRONT DOOR INNER RUBBER RH		1	122.80	0.00 %	122.80
FRONT DOOR INNER HANDLE BRACKET RH		1	145.50	0.00 %	145.50
FRONT DOOR INNER LOWER RUBBER RH		1	60.00	0.00 %	60.00
FRONT DOOR INNER TRIM RH		1	482.00	0.00 %	482.00
FRONT DOOR HINGE RH		1	180.00	0.00 %	180.00
FRONT DOOR CHECKER RH		1	108.00	0.00 %	108.00
FRONT DOOR GLASS OUTER MOULDING RH		1	115.00	0.00 %	115.00
FRONT DOOR GLASS REGULATOR AND MOTOR		1	260.50	0.00 %	260.50
ROCKER PANEL GARNISH RH		1	485.00	0.00 %	485.00
FRONT DOOR RH		1	978.30	0.00 %	978.30
FRONT DOOR OUTER PROTECTOR RH		1	240.00	0.00 %	240.00
FRONT DOOR INNER RUBBER RH		1	122.80	0.00 %	122.80
FRONT DOOR INNER TRIM BOARD RH		1	455.00	0.00 %	455.00
REAR DOOR HINGE RH		1	180.00	0.00 %	180.00
REAR DOOR CHECKER RH		1	108.00	0.00 %	108.00
REAR DOOR GLASS OUTER MOULDING RH		1	108.90	0.00 %	108.90
REAR DOOR GLASS REGULATOR AND MOTOR		1	260.50	0.00 %	260.50
REAR DOOR SPEAKER RH		1	165.00	0.00 %	165.00

REAR FENDER OUTER PROTECTOR RH	1	420.00	0.00 %	420.00
-----------------------------------	---	--------	--------	--------

Parts Subtotal 6,539.60

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
REAR SPORT RIM		1.0	550.00	0.00 %	550.00
REAR DOOR FRAME BLACK TAPE		1.0	60.00	0.00 %	60.00
REAR DOOR VISOR RH		1.0	40.00	0.00 %	40.00
REAR DOOR INNER TRIMBOARD CLIP		1.0	30.00	0.00 %	30.00
FRONT DOOR VISOR RH		1.0	40.00	0.00 %	40.00
FRONT DOOR INNER TRIMBOARD CLIP		1.0	30.00	0.00 %	30.00
FRONT DOOR FRAME BLACK TAPE		1.0	60.00	0.00 %	60.00

Materials Subtotal 810.00

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
CHECK WIRING	RnR	20.00	0.00 %	20.00
WHEEL ALIGNMENT	RnR	60.00	0.00 %	60.00
REPLACE/ REPAIR ACCIDENT AFFECTED ITEMS AND AREAS	RnR	600.00	0.00 %	600.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
PAINT ON ACCIDENT AFFECTED AREAS	Full spray	800.00	0.00 %	800.00

Labor Rate	S\$ 50 / Hour	General Labor Subtotal	680.00
		Paint Labor Subtotal	800.00
		Labor Subtotal	1,480.00

Summary

Repair Cost	8,829.60
Discount(10 %)	(872.68)
	7,956.92

Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	7,956.92