

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Cecilia Lee

Date: 09 Nov 2022

Preliminary Advice

Vehicle No	: SMH5851G	Accident Date	: 20/10/2022
Make	: KIA CERATO	Policy No.	: DMPCSNW00031962200
Assignment Date	: 25/10/2022	Excess	: S\$500.00
Date of Inspection	: 09/11/2022	Est. Duration of Repair	: 4
Inspection At	: DING AUTO PTE LTD (HQ) 176 SIN MING DRIVE #04-06, SIN MING AUTOCARE SINGAPORE 575721		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,850.07
Revised Amount	:S\$	2,075.07
Check Items (Estimated)	:S\$	2,605.00
Total	:S\$	4,680.07
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	85,000.00
COE / PARF Rebate	:S\$	29,039.00
Salvage Value	:S\$	
Margin for Repair	:S\$	55,961.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.