

AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721
TEL: 6456 3637 FAX: 6456 3686 Email: admin@almsm.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : TAN CHOON HUAT ALLAN
BLK 407A FERNVALE ROAD
#15-15
SINGAPORE 791407

Claim No: MCS1900740
Ref No: MFS1900730
Date: 13 Mar 2023
Policy No: D22MTPV0101
Veh Reg No: SLS3377B
Make/Model: BMW 520I
Chassis No: WBA5A32000D333564
TP Ins Co: SOMPO

ATTN:
Your Ref No: SLS3377B
Claim Type: Third Party
Accident Date: 18/10/2022
TP Veh Reg No: YP8157Z

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization): SLS3377B

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
SPARE PARTS				
1 REAR BUMPER		1 PC	1,550.00	
2 REAR BUMPER CENTRE CHROME MOULDING		1 PC	175.00	
			1,725.00	
	Add 25%		431.25	2,156.25
LABOUR				
3 TO CHECK WIRING		1 PC	20.00	
4 TO DISMANTLE AND REPLACE DAMAGE PARTS, TO KNOCK, ALIGN AND REPAIR REAR AFFECTED AREA		1 PC	200.00	
5 TO SPRAY REAR BUMPER		1 PC	250.00	
				470.00
Total				S\$ 2,626.25
Lump Sum Less 20%				-525.25
Amount Before Excess				S\$ 2,101.00
Less Rounding				-1.00
Amount Before Excess				S\$ 2,100.00
Add GST @ 8%				168.00
Total Amount payable				<u>S\$ 2,268.00</u>

TOTAL: SINGAPORE DOLLAR TWO THOUSAND TWO HUNDRED SIXTY EIGHT ONLY

The above vehicle was surveyed by ADRIAN - LKK on 25/10/2022

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY
(SIN MING BRANCH)
176, Sin Ming Drive, #05-12
Sin Ming Autocare, Singapore 575721
Tel: 6456 3637 Fax: 6456 3686
Authorised Signature

AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721
TEL: 6456 3637 FAX: 6456 3686 Email: admin@almsm.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : TAN CHOON HUAT ALLAN
BLK 407A FERNVALE ROAD
#15-15
SINGAPORE 791407

Estimate No: MCS1900740
Date: 19 Oct 2022
Policy No: D22MTPV0101
Veh Reg No: SLS3377B
Make/Model: BMW 520I

ATTN: Motor Claim Department
Your Ref No: SLS3377B
Claim Type: Third Party
Accident Date: 18/10/2022
TP Veh Reg No: YP8157Z

Estimate Repair Cost to Vehicle No : SLS3377B

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
SPARE PARTS				
1 REAR BUMPER <i>Def d</i>		1 PC	1,550.00	✓
2 REAR BUMPER CENTRE CHROME MOULDING <i>Cut</i>		1 PC	175.00	✓
			1,725.00	
	Add 25%		431.25	2,156.25
LABOUR				
3 TO CHECK WIRING		1 PC	20.00	✓
4 TO DISMANTLE AND REPLACE DAMAGE PARTS, TO KNOCK, ALIGN AND REPAIR REAR AFFECTED AREA		1 PC	350.00	250
5 TO SPRAY REAR BUMPER		1 PC	300.00	250
				670.00
			Repair Amount	S\$ 2,826.25
			Add GST @ 7%	197.84
			Total Amount payable	<u>S\$ 3,024.09</u>

TOTAL: SINGAPORE DOLLAR THREE THOUSAND TWENTY FOUR AND CENTS NINE ONLY

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

Admin Lj
H/S 25/10/22
02 Days
96893735