



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22010499/Aqy3q2 Date: 07/06/2023 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YP 8157Z	Veh. Inspected	SLS 3377B
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2203830/RUC	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	25/10/2022
2. Vehicle Particulars & Condition				
	Make & Model	B.M.W. 520i	c.c	1997
	Engine No.	HIDDEN	Year of Reg.	2013
	Chassis No.	WBA5A32000D333564	Colour	WHITE
	Odometer	149166 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	285/30 R20	PIRELLI	6 mm
	L/H Front Tyre	285/30 R20	PIRELLI	6 mm
	R/H Rear Tyre	285/30 R20	PIRELLI	6 mm
	L/H Rear Tyre	285/30 R20	PIRELLI	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	18/10/2022	Inspection Date	25/10/2022
	Survey held at	AH LIM MOTOR COMPANY 176 SIN MING DRIVE #05-12 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	