

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22010506/UQY3Q2**Date:** 14/11/2022REFERENCE

Insured/Claimant: SYED AHMAD AL_SHIHAB BIN SYED OSMAN

Policy No: DMPCSNW0014136200

Date of Loss: 21/10/2022

Nature of Claim: OD

Claim No: SNM22D207556/C01/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKB3506Y**

Make & Model: BMW 523i, 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A) Engine No: 10157744N52B25AF

Reg. Date: 20/05/2011 (Man. Year: 2011)

Chassis No: WBAFP32020C866167

Colour: White

Odometer: 122763 km

Engine Capacity: 2497 cc

Market Value/New Car Price: S\$85,000.00

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R18

Rear Tyre Size: 225/55 R18

Front Left Side: Hankook 6 mm

Rear Left Side: Hankook 6 mm

Front Right Side: Hankook 6 mm

Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,295.30	7,965.00	1,330.30	14.31
Miscellaneous Items	800.00	400.00	400.00	50.00
Labour	479.97	465.97	14.00	2.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,575.27	8,830.97	1,744.30	16.49
Approved Total (Overridden) (S\$)		7,000.00		
(S\$)	10,575.27	7,000.00	3,575.27	33.81
+ GST 7.00/7.00% (S\$)	740.27	490.00	250.27	33.81
Nett Amount (S\$)	11,315.54	7,490.00	3,825.54	33.81

INSPECTION

Date of Assignment: 25/10/2022 Present Location: Car City Auto Centre Pte Ltd (HQ)
Car City Auto Centre Pte Ltd (HQ)
Date Inspected: 26/10/2022 Inspected At: Blk 9006 #01-198, Tampines Street 93
Singapore 528840
Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Nov 2022)
Parts:	143	BMW 523I 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKB3506Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PARTS		9,295.30 F	*7,965.00 F
F=Franchise part.						
Total Parts (S\$)					9,295.30	7,965.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	EXTRA	800.00	400.00
Sub Total (\$\$)			800.00	400.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	241.50	227.50
2	SPRAY PAINTING	New	238.47	238.47
Gross Labour Cost (\$\$)			479.97	465.97

Report was unsubmitted during this print-out.

< END OF ESTIMATES >