

INSMART AUTOCARE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SKS8831K

Vehicle Model : HONDA JAZZ

Chassis Number : JHMGD18508S216476

Estimated Repair Cost

S/N	Parts Description	Qty	Cost Price
1	BONNET	1	\$ 450.00 <i>bt</i>
2	BONNET LOCK	1	\$ 40.00 <i>bt</i>
3	BONNET STAND	1	\$ 20.00 <i>x</i>
4	BONNET STAND CLIP	1	\$ 5.00 <i>x</i>
5	BONNET HINGES (LH & RH)	2	\$ 50.00 <i>?</i>
6	FRONT BUMPER	1	\$ 350.00 <i>de</i>
7	FRONT BUMPER CLIPS	10	\$ 30.00 <i>na</i>
8	FRONT BUMPER RETAINER (LH & RH)	2	\$ 20.00 <i>de</i>
9	FRONT BUMPER REINFORCEMENT	1	\$ 150.00 <i>bt</i>
10	FRONT BUMPER LOWER GRILLE	1	\$ 120.00 <i>de</i>
11	FRONT GRILLE	1	\$ 130.00 <i>de</i>
12	FRONT GRILLE CLIPS	10	\$ 30.00 <i>na</i>
13	FRONT GRILLE "H" LOGO	1	\$ 25.00 <i>na</i>
14	HEADLAMP (LH & RH)	2	\$ 900.00 <i>na</i>
15	HEADLAMP LOWER BRACKET (LH & RH)	2	\$ 40.00 <i>?</i>
16	FRONT FENDER (LH & RH)	2	\$ <i>RHR</i> 500.00 <i>LHbt</i>
17	SUPPORT PANEL	1	\$ 280.00 <i>bt</i>
18	A/C CONDENSER	1	\$ 380.00 <i>bt</i>
19	RADIATOR	1	\$ 480.00 <i>?</i>
20	FAN COWLING	1	\$ 80.00 <i>?</i>
21	FAN MOTOR	1	\$ 290.00 <i>?</i>
22	FAN BLADE	1	\$ 50.00 <i>?</i>
23	FRONT SPLASH SHIELD (LH & RH)	2	\$ 140.00 <i>?</i>
24	FRONT SPLASH SHIELD CLIPS	30	\$ 90.00 <i>?</i>
25	DASHBOARD AIRBAG	1	\$ 950.00 <i>air</i>
26	DASHBOARD	1	\$ 800.00 <i>air</i>
27	STEERING WHEEL AIRBAG	1	\$ 1200.00 <i>air</i>
28	AIRBAG MODULE	1	\$ 750.00 <i>air</i>
29	CLOCK SPRING	1	\$ 380.00 <i>air</i>
30	AIRCON SUCTION PIPE	1	\$ 150.00 <i>?</i>
31	AIRCON DISCHARGE PIPE	1	\$ 180.00 <i>?</i>
32	AIRCON LIQUID PIPE	1	\$ 100.00 <i>?</i>
33	FRONT SEAT BELT (LHS & RHS)	2	\$ 800.00 <i>air</i>
34	FRONT SEAT BELT BUCKLE (LHS & RHS)	2	\$ 200.00 <i>?</i>
35	HORN	1	\$ 50.00 <i>?</i>

INSMART AUTOCARE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

	\$	10210.00
Cost price +10%	\$	1021.00
Cost Prices Total	\$	11,231.00

Special Nett Items:		Qty		
1	FRONT NUMBER PLATE WITH HOLDER	1SET	\$	60.00 <i>45 cm</i>
	Special Nett Total		\$	60.00
	Spare Part's Total Price		\$	11291.00

INSMART AUTOCARE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SKS8831K

Vehicle Model : HONDA JAZZ

Chassis Number : JHMGD18508S216476

S/N	Labour Descriptions	Charges
1	LABOUR CHARGES TO REMOVE & INSTALL FRONT END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; TO STRAIGHTEN & REPAIR FRONT SUPPORT PANEL, TO REPLACE DAMAGED PARTS AS LISTED ABOVE.	\$ 2000.00 800
2	TO SPRAY PAINTING ON: FRONT BUMPER, BONNET (INNER & OUTER), FRONT BOTH FENDER, FRONT LH & RH DOOR, SUPPORT PANEL, FRONT BOTH "A" PILLAR.	\$ 1800.00 1000
3	TO REMOVE & INSTALL A/C CONDENSER & RECEIVER DRYER, TO ENABLE REPAIRS; TO VACUUM & CHARGE UP GAS	\$ 150.00 100
4	TO REMOVE & INSTALL RADIATOR & HOSES TO ENABLE REPAIRS, INCLUDING PRESSURIZE COOLING SYSTEM.	\$ 150.00 100?
5	TO CHECK ELECTRICAL WIRINGS & LIGHTS FUNCTION, INCLUSIVE FOCUS HEADLIGHTS.	\$ 200.00 40
6	CHECK & CLEAR FAULT CODES AFTER NECESSARY ACCIDENT REPAIRS.	\$ 280.00 100?
7	REMOVE & INSTALL DASHBOARD	\$ 600.00 200
8	REMOVE & INSTALL FRONT LH & RH AIRBAG	\$ 600.00 100

Labour Total \$ 5780.00

Parts & Labour Total \$ 17071.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

known/aged by Repairer
nature:

Tanfah 97445749
Not Authorise 26/10/22
EX: 2400
8 days - 9 days.
45 Resurvey after repair
Tanfah e (lkkauto.com)