

INSMART AUTOCARE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SKS8831K

Vehicle Model : HONDA JAZZ

Chassis Number : JHMGD18508S216476

Estimated Repair Cost

S/N	Parts Description	Qty	Cost Price
1	BONNET	1	\$ 450.00 bt-
2	BONNET LOCK	1	\$ 40.00 bt-
3	BONNET STAND	1	\$ 20.00 x un
4	BONNET STAND CLIP	1	\$ 5.00 x un
5	BONNET HINGES (LH & RH)	2	\$ 50.00 x un
6	FRONT BUMPER	1	\$ 350.00 de-
7	FRONT BUMPER CLIPS	10	\$ 30.00 ne-
8	FRONT BUMPER RETAINER (LH & RH)	2	\$ 20.00 de-
9	FRONT BUMPER REINFORCEMENT	1	\$ 150.00 bt-
10	FRONT BUMPER LOWER GRILLE	1	\$ 120.00 de-
11	FRONT GRILLE	1	\$ 130.00 de-
12	FRONT GRILLE CLIPS	10	\$ 30.00 ne-
13	FRONT GRILLE "H" LOGO	1	\$ 25.00 ne-
14	HEADLAMP (LH & RH)	2	\$ 900.00 and
15	HEADLAMP LOWER BRACKET (LH & RH)	2	\$ 40.00 x un
16	FRONT FENDER (LH & RH)	2	\$ RH&R 500.00 LH&R 250
17	SUPPORT PANEL	1	\$ 280.00 bt-
18	A/C CONDENSER	1	\$ 380.00 bt-
19	RADIATOR	1	\$ 480.00 x un
20	FAN COWLING	1	\$ 80.00 x un
21	FAN MOTOR	1	\$ 290.00 x un
22	FAN BLADE	1	\$ 50.00 x un
23	FRONT SPLASH SHIELD (LH & RH)	2	\$ 140.00 x un
24	FRONT SPLASH SHIELD CLIPS	30	\$ 90.00 x un
25	DASHBOARD AIRBAG	1	\$ 950.00 act-
26	DASHBOARD	1	\$ 800.00 act-
27	STEERING WHEEL AIRBAG	1	\$ 1200.00 act-
28	AIRBAG MODULE	1	\$ 750.00 act-
29	CLOCK SPRING	1	\$ 380.00 act-
30	AIRCON SUCTION PIPE	1	\$ 150.00 x un
31	AIRCON DISCHARGE PIPE	1	\$ 180.00 x un
32	AIRCON LIQUID PIPE	1	\$ 100.00 x un
33	FRONT SEAT BELT (LHS & RHS)	2	\$ 800.00 act-
34	FRONT SEAT BELT BUCKLE (LHS & RHS)	2	\$ 200.00 x un
35	HORN	1	\$ 50.00 x un

INSMART AUTOCARE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

	\$	10210.00
Cost price +10%	\$	1021.00
Cost Prices Total	\$	11,231.00

Special Nett Items:	Qty	
1 FRONT NUMBER PLATE WITH HOLDER	1SET	\$ 60.00 <i>45 cur ✓</i>
Special Nett Total		\$ 60.00
Spare Part's Total Price		\$ 11291.00

882

Supplementary

- 1) Radiator (Fan blade) - \$80 *cur ✓*
- 2) Radiator (Fan motor) - \$280 *dis ✓*
- 3) Alternator - \$850. *cur ✓*

9770

INSMART AUTOCARE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SKS8831K

Vehicle Model : HONDA JAZZ

Chassis Number : JHMGD18508S216476

S/N	Labour Descriptions	Charges
1	LABOUR CHARGES TO REMOVE & INSTALL FRONT END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; TO STRAIGHTEN & REPAIR FRONT SUPPORT PANEL, TO REPLACE DAMAGED PARTS AS LISTED ABOVE.	\$ 2000.00 800
2	TO SPRAY PAINTING ON: FRONT BUMPER, BONNET (INNER & OUTER), FRONT BOTH FENDER, FRONT LH & RH DOOR, SUPPORT PANEL, FRONT BOTH "A" PILLAR.	\$ 1800.00 1000
3	TO REMOVE & INSTALL A/C CONDENSER & RECEIVER DRYER, TO ENABLE REPAIRS; TO VACUUM & CHARGE UP GAS	\$ 150.00 100
4	TO REMOVE & INSTALL RADIATOR & HOSES TO ENABLE REPAIRS, INCLUDING PRESSURIZE COOLING SYSTEM.	\$ 150.00 100✓
5	TO CHECK ELECTRICAL WIRINGS & LIGHTS FUNCTION, INCLUSIVE FOCUS HEADLIGHTS.	\$ 200.00 40
6	CHECK & CLEAR FAULT CODES AFTER NECESSARY ACCIDENT REPAIRS.	\$ 280.00 100✓ run
7	REMOVE & INSTALL DASHBOARD	\$ 600.00 200
8	REMOVE & INSTALL FRONT LH & RH AIRBAG	\$ 600.00 100

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Knownledged by Repairer
Signature:

Labour Total \$ 5780.00

Parts & Labour Total \$ 17071.00

Tan Jiah - 97495749

Not Authorise 26/10/22

EX: 2400

8 days - 9 days.

45 Resurvey after repair
tanjiah@lkkauto.com

9770

2340

12110

20% - 9688

4/5 of 8200

800

2340

9 days