



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0910/2022/EQ
DATE : 20-Oct-22
WIP : 46928

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 21/10/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR ZHANG QUN
ADDRESS : 46 FABER WALK
#04-24, WATERFRONT @ FABER
SINGAPORE 128992
TELEPHONE : HP +65 83868708
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900018296-01
VEHICLE NO : **SMJ 465 K**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI 8W
MODEL YEAR : 20/2/2019
ENGINE NO : CVK 075692
CHASSIS NO : WAUZZZF48KN006725
MILEAGE : 7,064
DATE IN : 19-Oct-22
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 19-Oct-22
PLACE OF ACCIDENT : 60 CHESTNUT AVENUE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMJ 465 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	/
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	X <i>WAT</i> ✓
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,100.00	1000
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$ 2,000.00	1100
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	/
TOTAL LABOUR CHARGES		: \$ 5,122.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 465 K

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	S/NETT	REMARKS
1	FRONT BUMPER / <i>Cut</i>	1	\$	2,377.00	1901.60
2	FRONT BUMPER FIXING PARTS <i>X</i>	1	\$	612.00	
3	FRONT BUMPER SECURING STRIP - LH / RH <i>X GNN</i>	2	\$	79.00	
4	FRONT BUMPER GRILLE - CENTER <i>X</i>	1	\$	219.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>?</i>	1	\$	254.00	203.20
6	FRONT BUMPER AIR GUIDE - RH <i>mis</i>	1	\$	72.00	57.20
7	RADIATOR GRILLE <i>X NN mis</i>	1	\$	1,478.00	
8	FRONT BUMPER AIR GUIDE GRILLE - RH <i>mis</i>	1	\$	151.00	120.40
9	FRONT BUMPER GUIDE SECTION - RH <i>?</i>	1	\$	41.00	32.24
10	FRONT BUMPER FOAM FILLER PIECE <i>X</i>	1	\$	139.00	
11	FRONT BUMPER REINFORCEMENT BEAM <i>X NN</i>	1	\$	899.00	
12	FRONT BUMPER TOP COVER <i>X</i>	1	\$	143.00	
13	CAUTION SIGN STICKER <i>X</i>	1	\$	16.00	
14	AIR CONDITIONER STICKER <i>X</i>	1	\$	9.00	
15	FRONT BUMPER BRACKET <i>X</i>	1	\$	154.00	
16	FRONT BUMPER SUPPORT - LH / RH <i>X</i>	2	\$	64.00	
17	FRONT PARKING AID SENSOR - INNER / OUTER <i>X</i>	2	\$	531.00	
18	FRONT PARKING AID SEAL RING <i>X</i>	4	\$	10.00	
19	HORN LOW TONE - RH <i>X GNN</i>	1	\$	139.00	
20	HORN BRACKET - RH <i>X</i>	1	\$	33.00	
SUB TOTAL SPARE PARTS		:	\$	7,420.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 465 K

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS		
21	FRONT FENDER - RH <i>Buc</i>	1	\$	861.00	688.80	
22	FRONT FENDER ATTACHMENT PARTS <i>X NN</i>	1	\$	225.00		
23	FRONT FENDER CLOSING ELEMENT - RH <i>?</i>	1	\$	81.00	64.40	
24	FRONT FENDER BRACKET - RH <i>?</i>	1	\$	41.00	32.72	
25	FRONT FENDER RIVET <i>ML</i>	7	\$	27.00	21.28	
26	FRONT FENDER DEFORMATION ELEMENT BRACKET - RH <i>X NN</i>	1	\$	55.00		
27	FRONT FENDER BRACE - RH <i>X</i>	1	\$	132.00	105.20	
28	FRONT WHEEL HOUSING LINER - RH <i>TN</i>	1	\$	262.00	209.60	
29	FRONT WHEEL SPOILER <i>Dis</i>	1	\$	82.00	65.12	
30	FRONT BUMPER SPOILER - RH <i>Dis</i>	1	\$	40.00	32.00	
31	FRONT FENDER LEDGE COVER - RH OUTER <i>X</i>	1	\$	35.00		
32	FRONT FENDER LEDGE COVER - RH <i>?</i>	1	\$	26.00	20.16	
33	HEADLIGHT - RH <i>?</i>	1	\$	8,294.00	6635.20	
34	HEADLIGHT HOSE - RH <i>X</i>	1	\$	42.00		
35	LIFT CYLINDER - RH <i>X</i>	1	\$	231.00		
36	LIFT CYLINDER BRACKET <i>X</i>	1	\$	7.00		
37	LIFT CYLINDER CORRUGATED PIPE <i>X</i>	1	\$	107.00		
38	LIFT CYLINDER CORRUGATED PIPE <i>X</i>	1	\$	45.00		
39	OUTSIDE TEMPERATURE SENSOR BRACKET <i>X</i>	1	\$	21.00		
40	RADIATOR AIR GUIDE - RH INNER <i>X</i>	1	\$	32.00		
SUB TOTAL SPARE PARTS				\$ 10,646.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL 6366 2323 FAX 6841 1183

EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 465 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	RADIATOR AIR GUIDE - RH OUTER X	1	\$	14.00
42	RADIATOR AIR GUIDE - UPPER CENTER X	1	\$	19.00
43	RADIATOR AIR GUIDE - LH OUTER X	1	\$	14.00
44	FRONT NO PLATE X	S/N	\$	60.00
45	SUNDRIES ?		\$	400.00
TOTAL SPARE PARTS		:	\$	18,573.00
TOTAL LABOUR CHARGES		:	\$	5,122.00
GRAND TOTAL		:	\$	23,695.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.