

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0910/2022/EQ
DATE : 20-Oct-22
WIP : 46928

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 21/10/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Guo Qiang
4 days - ok - Johnny Boo
29-Nov-22

OWNER'S NAME : MR ZHANG QUN
ADDRESS : 46 FABER WALK
#04-24, WATERFRONT @ FABER
SINGAPORE 128992
TELEPHONE : HP +65 83868708
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900018296-01
VEHICLE NO : **SMJ 465 K**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI 8W
MODEL YEAR : 20/2/2019
ENGINE NO : CVK 075692
CHASSIS NO : WAUZZZF48KN006725
MILEAGE : 7,064
DATE IN : 19-Oct-22
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 19-Oct-22
PLACE OF ACCIDENT : 60 CHESTNUT AVENUE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMJ 465 K

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	\$	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,100.00	\$	1,000.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$	2,000.00	\$	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 5,122.00	\$	3,022.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 465 K

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,377.00	\$	1,901.60
2	FRONT BUMPER FIXING PARTS	1	\$ 612.00		
3	FRONT BUMPER SECURING STRIP - LH / RH	2	\$ 79.00		
4	FRONT BUMPER GRILLE - CENTER	1	\$ 219.00		
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 254.00	\$	203.20
6	FRONT BUMPER AIR GUIDE - RH	1	\$ 72.00	\$	57.20
7	RADIATOR GRILLE	1	\$ 1,478.00		
8	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 151.00	\$	120.40
9	FRONT BUMPER GUIDE SECTION - RH	1	\$ 41.00	\$	32.24
10	FRONT BUMPER FOAM FILLER PIECE	1	\$ 139.00		
11	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 899.00		
12	FRONT BUMPER TOP COVER	1	\$ 143.00		
13	CAUTION SIGN STICKER	1	\$ 16.00		
14	AIR CONDITIONER STICKER	1	\$ 9.00		
15	FRONT BUMPER BRACKET	1	\$ 154.00		
16	FRONT BUMPER SUPPORT - LH / RH	2	\$ 64.00		
17	FRONT PARKING AID SENSOR - INNER / OUTER	2	\$ 531.00		
18	FRONT PARKING AID SEAL RING	4	\$ 10.00		
19	HORN LOW TONE - RH	1	\$ 139.00		
20	HORN BRACKET - RH	1	\$ 33.00		
SUB TOTAL SPARE PARTS			\$ 7,420.00	\$	2,314.64

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 465 K

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		C/F		\$	2,314.64
21	FRONT FENDER - RH	1	\$ 861.00	\$	688.80
22	FRONT FENDER ATTACHMENT PARTS	1	\$ 225.00		
23	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 81.00	\$	64.24
24	FRONT FENDER BRACKET - RH	1	\$ 41.00	\$	32.72
25	FRONT FENDER RIVET	7	\$ 27.00	\$	21.28
26	FRONT FENDER DEFORMATION ELEMENT BRACKET - RH	1	\$ 55.00		
27	FRONT FENDER BRACE - RH	1	\$ 132.00	\$	105.20
28	FRONT WHEEL HOUSING LINER - RH	1	\$ 262.00	\$	209.60
29	FRONT WHEEL SPOILER	1	\$ 82.00	\$	65.12
30	FRONT BUMPER SPOILER - RH	1	\$ 40.00	\$	32.00
31	FRONT FENDER LEDGE COVER - RH OUTER	1	\$ 35.00		
32	FRONT FENDER LEDGE COVER - RH	1	\$ 26.00	\$	20.16
33	HEADLIGHT - RH	1	\$ 8,294.00	\$	6,635.20
34	HEADLIGHT HOSE - RH	1	\$ 42.00		
35	LIFT CYLINDER - RH	1	\$ 231.00		
36	LIFT CYLINDER BRACKET	1	\$ 7.00		
37	LIFT CYLINDER CORRUGATED PIPE	1	\$ 107.00		
38	LIFT CYLINDER CORRUGATED PIPE	1	\$ 45.00		
39	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 21.00		
40	RADIATOR AIR GUIDE - RH INNER	1	\$ 32.00		
SUB TOTAL SPARE PARTS			:	\$ 10,646.00	\$ 10,188.96

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 465 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		C/F		\$ 10,188.96
41	RADIATOR AIR GUIDE - RH OUTER	1	\$ 14.00	
42	RADIATOR AIR GUIDE - UPPER CENTER	1	\$ 19.00	
43	RADIATOR AIR GUIDE - LH OUTER	1	\$ 14.00	
44	FRONT NO PLATE	S/N	\$ 60.00	
45	SUNDRIES		\$ 400.00	
TOTAL SPARE PARTS		:	\$ 18,573.00	\$ 10,188.96
TOTAL LABOUR CHARGES		:	\$ 5,122.00	\$ 3,022.00
GRAND TOTAL		:	\$ 23,695.00	\$ 13,210.96

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-29/11/22

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT