

Auto Insure Pte. Ltd
6 Marsiling Lane
739145



Insurer Reference: GBE6203S
Repairer Reference: M6568/GBE6203S
Date calculated: 21/10/2022 4:01 PM

Full Report
Registration: GBE6203S
Printed: 21/10/2022 4:02 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Marvyn Chua	Currency:	SGD
Claim Reference:	GBE6203S	Date of Incident:	20/10/22
Estimated Repair Time:	4	Hire Car Start:	
Actual Repair Days:	4	Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	FUSO
Model:	CANTER (FB/FE/FG)
Sub Model:	BASE MODEL
Model Sheet Number:	32 87 01
Registration:	GBE6203S
VIN number:	FEA01BA20026
Odometer:	0

Model Specs

SINGLE CAB	TWO COAT METALLIC	PREPARE OFF VEHICLE
------------	-------------------	---------------------


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Tyres Condition

Tyre Brand	Tread (Left Middle), mm	Tread (Left Outer), mm	Tread (Left Inner), mm	Tread (Right Inner), mm	Tread (Right Outer), mm	Tread (Right Middle), mm	Condition
------------	-------------------------	------------------------	------------------------	-------------------------	-------------------------	--------------------------	-----------

Spare Tyre Brand	Tread (Spare), mm
------------------	-------------------

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
NO NUMBER	RENEW FRONT MANUFACTURER BADGE		3.0	12.60
NO NUMBER	R + R L/WING COVER		2.0	8.40
NO NUMBER	RENEW L/F DOOR		69.0	289.80
	INCLUDES: R + R DOOR, CONVERT ATTACHED PARTS, RENEW IF NECESSARY			
1487	L/UPPER DOOR HINGE REPAIR		10.0*	42.00
1495	L/LOWER DOOR HINGE REPAIR		10.0*	42.00
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		9.40	94.0	394.80
Total of Labour				394.80

Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h	
Code	Description - TWO COAT METALLIC		WU	Price SGD
	LEFT FRONT DOOR NEW PART PAINTING		15.0	

Paint Material Per Part

Code	Description	Price SGD
1481	LEFT FRONT DOOR NEW PART PAINTING	39.22

Labour Cost - Paint

	Factor	42.00 SGD/h	Hrs	WU	Price SGD
	Time Paint			15.0	
	Preparation Main Work Metal		2.50	25.0	105.00
Total		10 WU/h	4.00	40.0	168.00

Material Cost - Paint

	Price SGD
New Part Painting	39.22
Material-constant Metal Preparation	28.60
Total	67.82

Spare Parts

				prices as at 2015-06-01
Code	Description	Part Number	Part Source	Price SGD
0435	N/A L/BADGE	MK676977		0.00
1505	L/F DOOR CHECK	MK403138	Original	55.00
1711	L/F DOOR TRIM	MK580881	Original	700.00
1519	SM L/F DOOR WINDOW	MK580871	Original	340.00
1625	LA L/F OUT WINDOW SEAL	MK580488	Original	100.00
1547	L/F WINDOW	MK581271	Original	660.00
	? REGULATOR			
1715	ms L/UPP DOOR PNL EDGE	ML231889	Original	300.00
2445	? L/WING TRIM	MK403145	Original	70.00
1481	BT LEFT FRONT DOOR	MK702223	Original	1,140.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			3,365.00
u: Used parts	Total			3,365.00

	SGD	SGD
Parts		
Total Parts	3,365.00	3,365.00
Labour Time Base 10 WU/h		
Total 94.0 WU X 42.00 SGD/h		
Total of Labour	394.80	394.80
Paint Work Time Base 10 WU/h		
Labour Cost 40.0 WU X 42.00 SGD/h		
Material Cost	168.00	
Total Paint Including Material	67.82	235.82
Repair Cost Excludes GST		3,995.62
GST (+7.00%)		279.69
Repair Cost Included GST		4,275.31
Deductions (Excludes GST)		
Deduction For Excess		
Total Of Deductions (Excludes GST)	-500.00	-500.00
Grand Total Excludes GST		3,495.62
GST (+7.00%)		244.69
Grand Total Included GST		3,740.31

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

No assessment notes entered.

3 Days.
Lump sum repair
After repair photos.
EXCESS : 500
Not Authorized
Gino Q. Corp. 82880282
28/10/22

LKK Auto Consultants hence notify the Repairer of the following:

- To display "before/after spray painting"
- Full name of the repairer
- Telephone number
- Name of the repairer on "face" basis
- Signature of the repairer

15.5.2015

Acknowledged by: _____
Signature: _____
Date: _____