ASS. REG. BY: REF: QQ CT12201	0521 Acus
<u> 458</u>	IGNMENT
From: Date:	Veh No: SMU3724K- Yr Regn: 2017, Augwi
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Toyola Harries c.c 1886
at Workshop m/s	Colour Maroon . A/C: Insured / Std / NI / NA
of	Sp.Reading 92793 T/Radio: Insured / Std / NI / NA
insured:	Eng/No:
Policy No.	C/No: ZSU 600068907
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: norder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modí: Nil (S/Rim / STD A/Rim or
	Tyre Size: F: 285/.55 R18 -
(Policy Condition)	R: 285/55R18
Remark: The veh had commenced its N/S O/S repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
Bal. or Market Value:	TOYO /(YOKO) OF
IDAC Accident Rport: Consistent?: Yes or No	Front Rear
GIA / PR Seen: Consistent? : Yes or No	R/Bal.
Est. Repairs: 4 days Res.: Yes or No	D.O.A. D.O.I. 75/0/22
Lum Sum: % 3 Val.: Yes or No	Survey held at HD lesfect
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT	Reas N/s
Date:Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
	ays with repairer. (Red. 20,930.01,75%)
THE SHALL SO TOUGH, TO	aus with repairer. Chia. 20, 430.01, 45%
mv ;	
PV:	
Nett:	
Date Till Date of the Control of the	·
	Days-Of Repair:
1) Final Report Date/Time, File Return to?	Resurvey No. of Trip: Survey Fee:
Add Fee	Transportation:
1.00×4年日 利 日本大手	//
emore comme	Tech Inve (3) Photos

Beerrage France & B Re De / fe

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars				
Owner ID Type:	Singapore NRIC			
Owner ID: Vehicle Details	9841			
Vehicle No.:	SMU3724K			
Vehicle to be Exported:	No			
Intended Deregistration Date:	20 Dec 2022			
Vehicle Make:	TOYOTA			
Vehicle Model:	HARRIER PREMIUM 2.0 A			
Primary Colour:	Red			
Manufacturing Year:	2015			
Engine No.:	3ZRB703424			
Chassis No.:	ZSU600068907			
Maximum Power Output:	111.0 kW (148 bhp)			
Open Market Value:	\$30,374.00			
Original Registration Date:	12 Aug 2017			
First Registration Date:	12 Aug 2017			
Transfer Count:	1			
Actual ARF Paid: Intended PARF Rebate Details	\$29,524.00			
PARF Eligibility:	Yes			
PARF Eligibility Expiry Date:	11 Aug 2027			
PARF Rebate Amount: Intended COE Rebate Details	\$20,666.00			
COE Expiry Date:	11 Aug 2027			
COE Category:	E - Open - all except motorcycle			
COE Period(Years):	10			
QP Paid:	\$52,751.00			
COE Rebate Amount:	\$24,489.00			
Total Rebate Amount:	\$45,155.00			

The information contained herein is correct as at 20 Dec 2022

SA1822AP0001 / Abwin Service Pte Ltd ENTRY DATE & TIME: 25/10/2022 10:16 (SGT) SUBMITTED BY: Claims VERSION: 1 (25/10/2022 10:16 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Actual Driver

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 25/10/2022 10:16 (SGT) Reported by Date of Accident 21/10/2022 19:30 (SGT) Exact Location of Accident Tampines Ave 9, Singapore Additional Location Information TAMPINES AVE 9 HEAVY VEHICLE CARPARK Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

1986

Vehicle Registration Number SMU3724K INSURED/POLICYHOLDER Is company? No Name Of Registered Owner **DU YIJUN** NRIC No SXXXX9841 Email Address DUYIJUN1974@GMAIL.COM Mobile Phone No (Phone) +65-81680784 Alternative Phone No

VEHICLE PARTICULARS

Manufacturer Toyota Model Harrier Variant Exact purpose for which vehicle was being used at time of Private use Are you claiming under your own insurance policy for repair to

No - Claiming third party your vehicle? Vehicle Category Private car Transmission Auto CC

INSURANCE COMPANY

Name of Insurance Company Income Insurance Limited Policy Number / Cover Note Number 5118811201-02

DRIVER

Name of Driver **DU YIJUN** NRIC No SXXXX9841 Date Of Birth 23/07/1974 Occupation Indoor



Date Of Driving Pass 27/12/2002 Driving experience 19 YEARS AND 10 MONTHS Gender Male Mobile Number (Phone) +65-81680784 Alt. Phone Number Email Address DUYIJUN1974@GMAIL.COM Address 19 TAMPINES AVENUE 8 Address complement #16-32 Postcode 529603 Is the driver the policyholder? Yes If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Hit and run / Vandalism / Damaged whilst parked Weather Conditions DRIZZLING Road Surface Wet OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER TO SKECH PLAN ATTACHED ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No **DETAILS OF OTHER VEHICLE PROPERTY 1** Vehicle Registration Number XE2620L Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour

Commercial vehicle

Vehicle Category

Name of Driver Contact Number

Address	-
Address complement	-
Postcode	
Insurance Company Name	
Nature Of Damage	-
Details of property damaged in accident	
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- 3. Information provided must be as <u>Inutiful</u> and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiale policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
- 5. Any false reporting may be referred to the Traffic Police Department for Investigation.
- This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (SIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
- By the ladgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8 Consent under the Personal Data Protection Act (PDPA)

l understand, acknowledge, agree and consent that

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:

- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me:
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers lawyers/law firms, may/are permitted to collect

use, disclose and/or process my Personal Information for one or more of the above Purposes, and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service provide (including their lawyers/law firms), which may be seed outside of Singapore, for one or more of the above Purposes

IN A. SMETTHY

Describe Circumstance of the Accident	
	and the second s
	s. A
Table 1-134-	
	10
	V
	\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.
X	
4.	
7 \	
X(-1	
178	
/	
	1
Declaration We declare the foregoing protocolars are are true in every respect.	/
a series of the sea sea sea seaten	A WILL
201/A- 201/A-	Z Co PAS NO IT
In African Art Jan	Z (20 Title 20)
	1

SKETCH PLAN #3

On the stated date and time. I, Vehicle A (SMU3724K) was stationary on Tampines Avenue 9 Heavy Vehicle Parking at carpark lot near 49,51,53. I was in the car waiting for my friend. Suddenly I felt a huge impact from the rear portion of my stationary vehicle. After I alighted I then realise that is Vehicle B (XE2620L) reversing and collided onto my vehicle.

Vehicle A: SMU3724K

Vehicle B: XE2620L

In 4 From

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit Singapore 415875

Tel: 6341 6789 Fax: 6341 6778

E-mail:jlperfectautowork@gmail.com



HD PERFECT AUTOWORK PTE LTD

Coline.

DATE: 22.10.2022

TO

: CHINA TAIPING MOTOR CLAIMS DEPTS

ZSU600068907

VEHICLE NO

: SMU3724K

MODEL

: TOYOTA HARRIER

DATE OF ACCIDENT

: 21.10.2022

TIME OF ACCIDENT

: 19:30 HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIN	M DETAIL : PARTS		Ш	NIT LIST	TOTAL LIST	for L
S/N	DESCRIPTION	QTY		PRICE		
1	TAILGATE DEVILO	1	\$	2,378.60	\$ 2,378.60) 100
	TAILGATE SPOILER Could	1	\$	3,937.40	\$ (3,937.40)	(Aud sh)
	TAILGATE HINGE Nu	2	\$	89.30	\$ 178.60	+
4	TAIL GATE WIPER BLADE MA	1	\$	97.60	\$ 97.60	1.
5	TAIL GATE LAMP LH Cut	1	\$	494.40	\$ 494.40	4811
6	TAIL GATE APRON GARNISH CMLd	1	\$	1,120.60	\$ 1,120.60	Pillo
7	TAILGATE LOGO NL	1	\$	85.00	\$ 85.00	
8	TAILGATE EMBLEM 'HARRIER'	1	\$	75.00	\$ 75.00	
9	TAILGATE INNER LOCK	1	\$	954.40	\$ 954.40	+
	TAILGATE WEATHER STRIP	1	\$	353.40	\$ 353.40	t .
11	TAILGATE INNER TOP TRIM > ~~	1	\$	269.80	\$ 269.80	X
12	TAILGATE INNER SIDE TRIM LH AT	2	\$	198.60	\$ 397.20	198.60
13	TAILGATE INNER TRIM (LOWER) at	1	\$	1,075.00	\$ 1,075.00	58
-	TAILGATE WIREHARNESS	1	\$	2,688.20	\$ 2,688.20	
15	TAILGATE WINDSCREEN GLASS Shattered	1	\$	1,498.80	\$ 1,498.80	
16	TAILGATE WINDSCREEN MOULDING HER	1	\$	298.00	\$ 298.00	-
17	TAIL GATE DAMPER AUTO LH DEALE	1	\$	586.30	\$ 586.30	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
18	TAILGATE COMPUTER , MULTI NETWORK (UNIT)	1	\$	1,619.30	\$ 1,619.30	
19	TAILGATE SIDE SENSOR LH ME M	1	\$	1,327.60	\$ 1,327.60	12 280
20	REAR BUMPER	1	\$	1,381.75		
2	REAR BUMPER CORNER RETAINER LH		\$	95.00		- y
-	REAR BUMPER SIDE RETAINER LH	1	\$	55.00	\$ 55.00	17
	TAIL LAMP LH CX	1	\$	689.60	\$ 689.60	

TO

: CHINA TAIPING MOTOR CLAIMS DEPTS

VEHICLE NO

: SMU3724K

MODEL

: TOYOTA HARRIER

DATE OF ACCIDENT

: 21.10.2022

TIME OF ACCIDENT

: 19:30 HRS

24	REAR FENDER Reis	2	\$ 1,792.60	\$ 3,585.20	1
25	REAR FENDER DRAIN PANL LH	1	\$ 139.20	\$ 139.20	1
	REAR FENDER QUARTER GLASS C/W MOULDING LH	1	\$ 472.40	\$ 472.40] +

6951.40 TOTAL PRICE
LESS 25%
SUB TOTAL PRICE

\$ 25,853.35

\$ 6,463.34

19,390.01

DESCRIPTION	QTY	UNI	T S/NETT	тот	AL S/NETT
REAR BUMPER CLIP (SET)	1	\$	80.00	\$	80.00
TAILGATE SEALANT	1	\$	150.00	\$	150 .00
TAILGATE WINDSCREEN SEALANT M	1	\$	80.00	\$	80.00
TAILGATE WINDSCREEN INNER SHIELD Ken	1	\$	60.00	\$	60.00
TAILGATE WINDSCREEN SOLAR FILM	1	\$	550.00	\$	550.00
TAILLAMP CLIP (SET)	1	\$	30.00	\$	30.00
TAIL DRAIN PANEL SEALANT LH 2 20 M	1	\$	120.00	\$	120.00
REAR FENDER SEALANT	2	\$	80.00	\$	160.00
IREAR FENDER INNER IRIM CLIP (SET)	1	\$	60.00	\$	60.00
FIL	1	\$	60.00	\$	60.00
7	2	\$	60.00	\$	120.00
I M	2	\$	60.00	\$	120.00
	2	\$	250.00	\$	500.00
	REAR BUMPER CLIP (SET) TAILGATE SEALANT TAILGATE WINDSCREEN SEALANT TAILGATE WINDSCREEN INNER SHIELD TAILGATE WINDSCREEN SOLAR FILM TAILLAMP CLIP (SET) TAIL DRAIN PANEL SEALANT LH REAR FENDER SEALANT REAR FENDER INNER TRIM CLIP (SET) REAR FENDER INNER COWLING CLIP (SET) REAR FENDER QUARTER GLASS SEALANT THE SEALANT TO THE S	REAR BUMPER CLIP (SET) TAILGATE SEALANT TAILGATE WINDSCREEN SEALANT TAILGATE WINDSCREEN INNER SHIELD TAILGATE WINDSCREEN SOLAR FILM TAILGATE WINDSCREEN SOLAR FILM TAILLAMP CLIP (SET) TAIL DRAIN PANEL SEALANT LH REAR FENDER SEALANT REAR FENDER INNER TRIM CLIP (SET) REAR FENDER INNER COWLING CLIP (SET) REAR FENDER QUARTER GLASS SEALANT 2 REAR FENDER QUARTER GLASS INNER SEAL 2	REAR BUMPER CLIP (SET) TAILGATE SEALANT TAILGATE WINDSCREEN SEALANT TAILGATE WINDSCREEN INNER SHIELD TAILGATE WINDSCREEN INNER SHIELD TAILGATE WINDSCREEN SOLAR FILM TAILLAMP CLIP (SET) TAIL DRAIN PANEL SEALANT LH REAR FENDER SEALANT REAR FENDER INNER TRIM CLIP (SET) REAR FENDER INNER COWLING CLIP (SET) REAR FENDER QUARTER GLASS SEALANT REAR FENDER QUARTER GLASS SEALANT REAR FENDER QUARTER GLASS INNER SEAL TO SEAL AND TO	REAR BUMPER CLIP (SET) TAILGATE SEALANT TAILGATE WINDSCREEN SEALANT TAILGATE WINDSCREEN INNER SHIELD TAILGATE WINDSCREEN INNER SHIELD TAILGATE WINDSCREEN SOLAR FILM TAILLAMP CLIP (SET) TAILLAMP CLIP (SET) TAIL DRAIN PANEL SEALANT LH REAR FENDER SEALANT REAR FENDER INNER TRIM CLIP (SET) REAR FENDER INNER TRIM CLIP (SET) REAR FENDER UARTER GLASS SEALANT TO SEAL SEAL SEAL SEALANT TO SEAL SEAL SEAL SEAL SEALANT TO SEAL SEAL SEAL SEAL SEAL SEAL SEAL SEAL	REAR BUMPER CLIP (SET) TAILGATE SEALANT TAILGATE WINDSCREEN SEALANT TAILGATE WINDSCREEN INNER SHIELD TAILGATE WINDSCREEN INNER SHIELD TAILGATE WINDSCREEN SOLAR FILM TAILLAMP CLIP (SET) TAILLAMP CLIP (SET) TAIL DRAIN PANEL SEALANT LH REAR FENDER SEALANT REAR FENDER INNER TRIM CLIP (SET) REAR FENDER INNER COWLING CLIP (SET) REAR FENDER QUARTER GLASS SEALANT REAR FENDER QUARTER GLASS INNER SEAL TENDER SEALANT REAR FENDER QUARTER GLASS INNER SEAL TO SEAL SEALANT TO SEAL SEAL SEALANT TO SEAL SEALANT TO SEAL SEAL SEALANT TO SEAL SEAL SEALANT TO SEAL SEALANT TO SEAL SEALANT TO SEAL SEAL SEAL SEALANT TO SEAL SEAL SEAL SEALANT TO SEAL SEAL SEALANT TO SEAL SEAL SEALANT TO SEAL SEAL SEAL SEALANT TO SEAL SEAL SEALANT TO SEAL SEAL SEAL SEAL SEALANT TO SEAL SEAL SEAL SEAL SEALANT TO SEAL SEAL SEAL SEAL SEAL SEAL SEAL SEAL

330 TOTAL

\$ 2,090.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION		PRICE	ADJUSTED COST		
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$	2,200,00	600		
2	TO SPRAY PAINT AFFECTED AREA	\$	1,500.00	7 00.		
	TUFF COAT	\$	350.00	60.		
4	WIRING AND BULB CHECK	\$	280.00	30'		
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILIATE REPAIR	\$	300.00	40.		

TO

: CHINA TAIPING MOTOR CLAIMS DEPTS

VEHICLE NO

: SMU3724K

MODEL

: TOYOTA HARRIER

DATE OF ACCIDENT

: 21.10.2022

TIME OF ACCIDENT

- 19-30 HRS

TIME	OF ACCIDENT : 19:30 HRS	 	
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	80
8	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.96	50
9	REINSTALL AND RESET AUTO SYSTEM SENSOR	\$ 350.00	X
10	TRANFER TAILGATE MECHANISM	\$ 80.00	80
11	CONDUCT WATER LEAKAGE TEST	\$ 180.00	X
12	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	/
13	REMOVE AND REFIX REAR FENDER QUARTER GLASS LH	\$ 100.00	X
14	REMOVE AND REFIX PETROL TANK TO FACILIATATE FENDER REPLACEMENT	\$ 100.00	×
15	VACCUM AND CLEAN TAIL GATE AND QUARTER GLASS GLASS SPLINTER	\$ 250.00	8O.
16	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 480.00	×

TOTAL

6,450.00

ESTIMATE REPORT

TOTAL PARTS COST

: \$

21,480.01

TOTAL LABOUR COST

6,450.00

TOTAL REPAIR COST

27,930.01

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

SERVICE ADVISOR IRENE

HP: 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- · To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:

Adrian Ly NS 25/10/22, 04 Pays, total. 8733.55 1/81 7K