

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance
(Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jacqueline Tan

Date: 29 Nov 2022

Preliminary Advice

Vehicle No	: SKF5225Z	Accident Date	: 17/10/2022
Make	: MERCEDES-BENZ	Policy No.	:
	E250		DMPCSNW00172422201
Assignment Date	: 25/10/2022	Excess	: S\$750.00
Date of Inspection	: 26/10/2022	Est. Duration of Repair	: 5
Inspection At	: GARAGE 13 PTE LTD - KAKI BUKIT (HQ) 8 KAKI BUKIT AVENUE 4, #02-54/55 PREMIER @ KB SINGAPORE 415875		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 16,406.34	(Estimate \$15,446.09 + Supplementary \$960.25)
Revised Amount	:S\$ 8,328.32	
Check Items (Estimated)	:S\$ 6,508.02	
Total	:S\$ 14,836.34	
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	99,000.00
COE / PARF Rebate	:S\$	54,592.00
Salvage Value	:S\$	
Margin for Repair	:S\$	44,408.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.