

GARAGE 13 PTE LTD

8 KAKI BUKIT AVE 3 #02-55 PREMIER@KB SINGAPORE 415875

TEL: 9091 0013

Vehicle No: SKF5225Z

Model No. Mercedes E250

Chassis no. WDD2074472F139793

Accident Date : 17/10/2022

Owner : Ng Yu Hui (Huang Yuhui)

Date of Estimate : 19/10/2022

Estimate for Accident Vehicle No. SKF5225Z

List Items:	Qty	Unit Price	Total Amount
1 Bonnet	1	\$1,610.00	\$1,610.00 / Deny
2 Bonnet hinge	2	\$92.00	\$184.00 ?
3 Bonnet logo	1	\$43.70	\$43.70 / missing
4 Front bumper	1	\$1,109.75	\$1,109.75 / crn
5 Front bumper side bracket	2	\$11.50	\$23.00 / PANEL
6 Front bumper reinforcement	1	\$201.25	\$201.25 ?
7 Front bumper sponge side	2	\$46.00	\$92.00 / crn
8 Front bumper fog lamp garnish	2	\$55.20	\$110.40 ?
9 Front bumper fog lamp	2	\$299.00	\$598.00 / BR
10 Front bumper parking sensor	6	\$115.00	\$690.00 / BR
11 Front bumper nozzle	2	\$126.50	\$253.00 / BR
12 Front bumper nozzle cover	2	\$40.25	\$80.50 / missing
13 Front bumper clips	set	\$50.00	\$50.00 / NEL
14 Front bumper grille	1	\$80.50	\$80.50 / missing
15 Headlamp	2	\$1,897.50	\$3,795.00 ? crn
16 Headlamp panel	2	\$189.75	\$379.50 ?
17 Front fender rh	1	\$667.00	\$667.00 / BUC
18 Front fender inner shield - front rh	1	\$224.25	\$224.25 ?
20 Front fender inner shield - rear rh	1	\$224.25	\$224.25 ?
21 Front fender inner shield clips	set	\$40.00	\$40.00 / NEL
22 Front radiator grille assy	1	\$540.50	\$540.50 ?
Sub-Total Amount =			\$10,996.60
Add 15%			\$1,649.49
Sub-Total =			<u>\$12,646.09</u>

Labour charges

1 Panel beating for replace and repair affected parts	\$1,100.00 600
2 Spray painting	\$1,200.00 600
3 Apply putty and anti-corrosion to affected parts.	\$100.00 X
4 Wiring / bulb checking	\$50.00 X
5 Remove / replace front bumper sensor & conduct distance safety setting	\$100.00 30

6 Check / Diagnostic and reprogramming

\$250.00 X

\$2,800.00


Total parts = \$12,646.09

Total labour = \$2,800.00

Total Amount = \$15,446.09

4 days

ON EX\$750/-

Infer  26 Oct, 1540

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: