

Infan - parts prices.

OD -

GARAGE 13 PTE LTD

8 KAKI BUKIT AVE 3 #02-55 PREMIER@KB SINGAPORE 415875

TEL: 9091 0013

Vehicle No: SKF5225Z
Model No: Mercedes E250
Chassis no: WDD2074472F139793

Accident Date : 17/10/2022
Owner : Ng Yu Hui (Huang Yuhui)
Date of Estimate : 19/10/2022

Estimate for Accident Vehicle No. SKF5225Z

List Items:	Qty	Unit Price	Total Amount
1 Bonnet	1	\$1,610.00	\$1,610.00 / dent 1,385
2 Bonnet hinge	2	\$92.00	\$184.00 ? XNN
3 Bonnet logo	1	\$43.70	\$43.70 / missing NEC
4 Front bumper	1	\$1,109.75	\$1,109.75 / crn
5 Front bumper side bracket	2	\$11.50	\$23.00 / panel
6 Front bumper reinforcement	1	\$201.25	\$201.25 ? SLR Repair
7 Front bumper sponge side	2	\$46.00	\$92.00 / LRA
8 Front bumper fog lamp garnish	2	\$55.20	\$110.40 / crn & missing
9 Front bumper fog lamp RH	2	\$299.00	\$598.00 / BR ✓
10 Front bumper parking sensor	3	\$115.00	\$345.00 / BR ✓
11 Front bumper nozzle	2	\$126.50	\$253.00 / BR ✓
12 Front bumper nozzle cover	2	\$40.25	\$80.50 / missing ✓
13 Front bumper clips	set	\$50.00	\$50.00 / new
14 Front bumper grille	1	\$80.50	\$80.50 / missing
15 Headlamp RH	2	\$1,897.50	\$3,795.00 / crn ✓
16 Headlamp panel RH	2	\$189.75	\$379.50 / crn
17 Front fender rh	1	\$667.00	\$667.00 / BU ✓
18 Front fender inner shield - front rh	1	\$224.25	\$224.25 / crn ✓
20 Front fender inner shield - rear rh	1	\$224.25	\$224.25 / crn ✓
21 Front fender inner shield clips	set	\$40.00	\$40.00 / new
22 Front radiator grille assy	1	\$540.50	\$540.50 / mis ✓
Sub-Total Amount =			\$10,996.60
With Supplementing			
Total Parts = 11442			
+ 10% = 1144			
Total = 12586			
Labour charges			
1 Panel beating for replace and repair affected parts			\$1,100.00 600
2 Spray painting			\$1,200.00 600
3 Apply putty and anti-corrosion to affected parts.			\$100.00 X
4 Wiring / bulb checking			\$50.00 X
5 Remove / replace front bumper sensor & conduct distance safety setting			\$100.00 30
Add			\$1,649.49
Sub-Total =			\$12,646.09

28/10/2022 - Audit, remarks - parts prices & marking.

10% + Total Parts = 8,381.01

Total = 9611.01

20% = 1922.20

ET = 7688.81



GARAGE 13 PTE LTD
8 KAKI BUKIT AVE 4 #02-54/55
PREMIER @ KAKI BUKIT S415875
TEL: 9666 4445
EMAIL: Claims@garage13.com.sg

SUPPLEMENTARY

VEHICLE NO.: SKF5225Z
MODEL: MERC E250
CHASSIS NO: WDD2074472F139793

ACCIDENT DATE: 17 10 2022
OWNER: NG YU HUI (HUANG YUHUI)
ESTIMATE DATE: 19 10 2022

S/N	DESCRIPTION	QTY	UNIT PRICE	TOTAL AMOUNT
LIST ITEMS				
1	INTERCOOLER	1	\$ 630.00	\$ 630.00
2	ENGINE COVER	1	\$ 85.00	\$ 85.00
3	FRONT BUMPER UNDER COVER	1	\$ 120.00	\$ 120.00
4				\$ -
5				\$ -
6				\$ -
7				\$ -
8				\$ -

TOTAL PARTS: \$ 835.00

ADD 15% \$ -

LIST TOTAL: \$ 835.00

notify
g:
ay painting
part(s) during resurvey
subject to confirmation
survey is on a "Without Prejudice" basis
modification(s) is allowed
mentary item(s) must be resurveyed and
ect to final approval from Insurance Company
ged by Repairer

LIK Auto Consultants

the Repairer of the following

- To resurvey before/after repair
- To display damaged parts
- Parts prices are suit
- Third party survey
- No illegal modifica
- Supplementary th
- is subject to final approval

Acknowledged by Repairer