



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

4 November 2022

REG NO.: SMK 5369 S
MAKE/MODEL: MITSUBISHI LANCER

not Authorised
25/10/22
2/5 @ 5200/
6 days

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
1	Front bonnet <i>Best</i>	\$ 777.00 ✓
1	Front bonnet hinge <i>11</i>	\$ 55.00 X
1	Front bonnet lock <i>11</i>	\$ 58.00 X
1	Front bonnet front rubber <i>11</i>	\$ 37.00 X
1	Front bonnet rear rubber <i>11</i>	\$ 27.00 X
1	Front headlamp -RH <i>520</i>	\$ 1,891.00 ✓
1	Front bumper <i>Dis</i>	\$ 825.00 ✓
1	Front bumper bracket <i>11</i>	\$ 28.00 X
1	Front bumper centre grille <i>11</i>	\$ 75.00 X
1	Front bumper fog lamp <i>11</i>	\$ 486.00 X
1	Front bumper fog lamp grille <i>11</i>	\$ 38.00 X
1	Front bumper lower spoiler <i>2</i>	\$ 409.00 X
1	Front bumper reinforcement <i>11</i>	\$ 329.00 X
2	Front bumper side retainers <i>one/ner</i>	\$ 56.00 ✓
1	Front bumper top beam <i>11</i>	\$ 86.00 X
1	Front bumper top seal rubber <i>ner</i>	\$ 68.00 ✓
1	Front fender -RH <i>Dis</i>	\$ 491.00 ✓
1	Front fender inner shield <i>to in</i>	\$ 118.00 ✓
1	Front wheel hub <i>Best</i>	\$ 264.00 ✓
1	Front wheel bearing <i>ner</i>	\$ 128.00 ✓
1	Front shock absorber <i>Best</i>	\$ 383.00 ✓
1	Front knuckle arm <i>Best</i>	\$ 284.00 ✓
1	Front lower arm <i>Best</i>	\$ 268.00 ✓
1	Front tie rod <i>11</i>	\$ 105.00 X
1	Steering rack <i>ner</i>	\$ 1,685.00 X
1	Steering rack cross member <i>11</i>	\$ 1,138.00 X
1	Front drive shaft -RH <i>11</i>	\$ 998.00 X
1	Front wiper tank <i>Dis</i>	\$ 86.00 ✓
		\$ 11,193.00
	Less 10%	\$ 1,119.30
		\$ 10,073.70

SPECIAL NETT ITEMS

1	Front bumper clip (1 set)	net	\$	45.00	40
1	Front fender inner shield clip (1 set)	net	\$	50.00	40
1	Front tyre	su	\$	500.00	X
1	Front wheel rim -RH	waged	\$	900.00	400
			\$	1,495.00	

S/N

LABOUR CHARGES

1	To check wiring and reset headlamps focusing.		\$	80.00	20
2	To remove and refit front undercarriage.		\$	500.00	150
3	To conduct wheel alignment.		\$	180.00	100
4	To remove, refit air-con condenser, refill gas & conduct leakage test.	11	\$	180.00	X
5	To apply undercoating.		\$	200.00	60
6	Panel beating.		\$	1,600.00	600
7	To re-spray painting on the affected areas.		\$	1,500.00	1000
			\$	4,240.00	

GRAND TOTAL :**\$ 15,808.70**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

9-4598
 102
 4138.2
 480
 1930
 6548.20
 202
 5238