

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22010531/TVY3Q2**Date:** 11/04/2023**REFERENCE**Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00155422100

**Claimant Vehicle  
No :** SNG1340J**Insured Vehicle  
No :** GBD1224U

Date of Loss: 13/10/2022

Nature of Claim: TP

Claim  
No: SNM22D207508/C02/IRENE**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SNG1340J**

Make &amp; Model: TOYOTA PRIUS, 1.8 (A)

Engine No: 2ZR2N27077

Reg. Date: 13/07/2022 (Man. Year: 2021)

Chassis No: JTDZS3EU50J068206

Colour: Silver

Odometer: 15146 km

Engine Capacity: 1798 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre tread depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 3,894.25          | 2,968.12          | 926.13            | 23.78         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 1,620.00          | 760.00            | 860.00            | 53.09         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>5,514.25</b>   | <b>3,728.12</b>   | <b>1,786.13</b>   | <b>32.39</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>3,000.00</b>   |                   |               |
| <b>(S\$)</b>                             | 5,514.25          | 3,000.00          | 2,514.25          | 45.60         |
| <b>+ GST 8.00/8.00% (S\$)</b>            | 441.14            | 240.00            | 201.14            | 45.60         |
| <b>Nett Amount (S\$)</b>                 | <b>5,955.39</b>   | <b>3,240.00</b>   | <b>2,715.39</b>   | <b>45.60</b>  |

**INSPECTION**

Date of Assignment: 25/10/2022

Date Inspected: 26/10/2022 Inspected At:

My Car Consultant Pte Ltd ( Jalan Lam Huat ) (HQ)  
60 Jalan Lam Huat, Carros Centre #05-21  
Singapore 737869

Estimated Period of Repair: 3.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

|               |                                                                                                                                                                              |                                                        |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------|
| Reference     |                                                                                                                                                                              |                                                        |
| Part Source:  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 10 Apr 2023)          |
| Parts:        | 144                                                                                                                                                                          | TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour:       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                      |
| Print Code:   | (Unsubmitted, no print-code for SNG1340J)                                                                                                                                    |                                                        |
| Validity:     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                        |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                        |

Recommended Parts

| No. | Qty | Part No. | Particulars                         | Condition     | Repairer's                                          | Amount                                       |
|-----|-----|----------|-------------------------------------|---------------|-----------------------------------------------------|----------------------------------------------|
| 1   | 1   |          | *FRT BUMPER                         | Deformed      | 798.00 FL                                           | *798.00 FL                                   |
| 2   | 1   |          | *FRT BUMPER DAY LIGHT RH            | Cut           | 321.00 FL                                           | *271.50 FL                                   |
| 3   | 1   |          | *FRT BUMPER DAY LIGHT COVER RH      | Not Necessary | 68.00 FL                                            | *- FL                                        |
| 4   | 1   |          | *FRT BUMPER SIDE RETAINER RH        | Not Necessary | 58.00 FL                                            | *- FL                                        |
| 5   | 1   |          | *FRT HEADLAMP RH                    | Cut           | 2,259.00 FL                                         | *2,259.00 FL                                 |
| 6   | 1   |          | *FRT HEADLAMP LOWER BRACKET         | Not Necessary | 112.00 FL                                           | *- FL                                        |
| 7   | 1   |          | *WIPER WASHER TANK                  | Not Necessary | 359.00 FL                                           | *- FL                                        |
| 8   | 1   |          | *FRONT FENDER RH                    | Bent          | 698.00 FL                                           | *521.00 FL                                   |
| 9   | 2   |          | *FRONT FENDER COWLING RH            | Not Necessary | 318.00 FL                                           | *- FL                                        |
| 10  | 1   |          | *FRONT FENDER EMBLEM HYBRID         | Necessary     | 68.00 FL                                            | *68.00 FL                                    |
| 11  | 1   |          | *SET FRT BUMPER CLIP                | Necessary     | 50.00 FS                                            | *30.00 FS                                    |
| 12  | 1   |          | *FRT FENDER INNERSHIELD CLIP FRT LH | Not Necessary | 50.00 FS                                            | *- FS                                        |
|     |     |          |                                     |               |                                                     | F=Franchise part. S=SpcNett. L=ListItemDisc. |
|     |     |          |                                     |               | Sub Total (\$\$)                                    | 5,159.00 3,947.50                            |
|     |     |          |                                     |               | - List Item Discount on L Items 25.00/25.00% (\$\$) | 1,264.75 979.38                              |
|     |     |          |                                     |               | Total Parts (\$\$)                                  | 3,894.25 2,968.12                            |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                              | Particulars      | Lab.Type | Repairer's      | Amount        |
|---------------------------------|------------------|----------|-----------------|---------------|
| <b>Labour Items</b>             |                  |          |                 |               |
| 1                               | CHECK WIRING     | New      | 100.00          | 30.00         |
| 2                               | REALIGN HEADLAMP | New      | 120.00          | 30.00         |
| 3                               | PANEL BEAT       | New      | 600.00          | 300.00        |
| 4                               | SPRAY PAINT      | New      | 800.00          | 400.00        |
| <b>Gross Labour Cost (\$\$)</b> |                  |          | <b>1,620.00</b> | <b>760.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >