

SERVICE ESTIMATE

- C00001 SL: SERVICE SALES - PC

Ms Yuhong Dai Bayraktar
57 West Coast Way
#12-11

Singapore 127018

Closed by : Paul Ong Qing Yong
Svc Consultant :
Remarks : Ms Yuhong Dai Bayrak

GST Reg.No: M28920628X
0 Page 1

Inv.No. . : B&P
Inv.date. : 25/10/2022
WIP No. . : 46811
Veh.In/Out:
*Tel.No. . : Mobile: 91762378
Reg.No. . : SKN6966U
Reg.date . : 28/05/2019
Mileage ... : 0
Chassis No: SADCB2AX7JA321158

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER, BOOTLID, REFLECTOR, ETC	0	3900.00	0		3,900.00	S
800	TO SPRAYPAINT ON BOOTLID, REAR BUMPER, ETC	0	3000.00	0		3,000.00	S
802	TO REPLACE REAR WINDSCREEN	0	650.00	0		650.00	S
0080	TO INSTALL REAR WINDSCREEN FIL	0	280.00	0		280.00	S
802	TO REMOVE, REFIT & TRANSFER REAR BOOTLID COMPONENTS	0	650.00	0		650.00	S
280	TO CHECK WIRING INCLUDE RESETTNG OF ALL ELECTRICAL MODULES	0	621.00	0		621.00	S
	COVER-BUMPER <i>de-</i>	1.0 EA	2065.50			2,065.50	S
	LAMP-FOG RH <i>com</i>	1.0 EA	336.00			336.00	S
	MOULDING RH <i>xn</i>	1.0 EA	136.50			136.50	S
	BRACKET-BUMPER RH <i>? com</i>	1.0 EA	129.50			129.50	S
	MOUNTING-BRACKET RH <i>? ca</i>	1.0 EA	147.20			147.20	S
	SENSOR <i>? xn</i>	4.0 EA	449.50			1,798.00	S

SERVICE ESTIMATE

- C00001 SL: SERVICE SALES - PC
 Ms Yuhong Dai Bayraktar
 57 West Coast Way
 #12-11

Singapore 127018

GST Reg.No:M28920628X
 0 Page 2
 Inv.No. : B&P
 Inv.date. : 25/10/2022
 WIP No. : 46811
 Veh.In/Out:
 *Tel.No. : Mobile: 91762378
 Reg.No. : SKN6966U
 Reg.date : 28/05/2019
 Mileage : 0
 Chassis No: SADCB2AX7JA321158

Closed by : Paul Ong Qing Yong
 Svc Consultant :
 Remarks : Ms Yuhong Dai Bayrak

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
	BUMPER BEAM REAR XE <i>Xan</i>	1.0	EA	753.50			753.50	S
	PANEL-TRUNK LID <i>? ca</i>	1.0	EA	2726.90	24.54	21	2,726.90	S
	BADGE <i>m</i>	1.0	EA	215.10	153.59		215.10	S
	BADGE - half leaper <i>m</i>	1.0	EA	187.30	168.57		187.30	S
	BADGE <i>m</i>	1.0	EA	131.60	118.44		131.60	S
	D PRIMER GLASS & P <i>? m</i>	1.0	EA	45.50	40.95		45.50	S
	SEALANT WINDSCREEN <i>? m</i>	2.0	EA	175.60	316.02		351.20	S
	GLASS-BACKLIGHT <i>? ca</i>	1.0	EA	1361.50	1225.35		1,361.50	S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Labour Total 9,101.00
 Parts Total 10,385.30
 Package Total 0.00

Gross Total. 19,486.30

Net..... 19,486.30

GST @ 7.0% 1,364.04

Total..... 20,850.35

Paid..... 0.00

Please Pay.. 20,850.35

GST: S=StdRated; O=OutOfScope; Z=ZeroRated