

A.S.S. REC. BY:

REF:

CC4/TU 22010540/DPK³

ASSIGNMENT

COE Nov 2027

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 10 8 days Res.: Yes or No

Lum Sum: 10 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHIA 8352 G Yr Regn: Nov / 2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Ioniq c.c. 1590

Colour: Yellow A/C: Insured / Std / NI / NA

Sp. Reading: 339163 T/Radio: Insured / Std / NI / NA

Eng/No: G4LEKU384109

C/No: KMHC85LCVLU182655

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 22/10/2022 D.O.I. 26/10/2022

Survey held at 3000000 Sin Ming

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TU GBL 8502D

14/3/23

page 2/5 16,300 - with 10 days of work

Date/Time, File Pass to?



Prel. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

Photos

Others

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Insp (\$)

Report Format: _____

1. Service 2. Form 3. & 4. P. 5. 10

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 25-Oct-22

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHA 8352 G

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey ~~is~~ on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

INSURANCE:

Acknowledged by Repairer

Signature:

Date:

Description	Qty	List Price	Amount
Boot Lid <i>Double</i>	1	\$ 2,549.70	\$ 2,549.70
Boot Lid Rubber <i>changed</i>	1	\$ 187.40	\$ 187.40
Boot Lid Hinge (LH/RH) <i>HH</i>	2	\$ 71.30	\$ 142.60
Boot Lid Absorber (LH/RH) <i>HH</i>	2	\$ 86.70	\$ 173.40
Boot Lid Lock Upper <i>Don</i>	1	\$ 224.00	\$ 224.00
Boot Lid 'H' Emblem <i>Hec</i>	1	\$ 28.00	\$ 28.00
Emblem-Hybrid <i>Hec</i>	1	\$ 24.30	\$ 24.30
Emblem-Ioniq <i>Hec</i>	1	\$ 31.30	\$ 31.30
Rear Spoiler <i>HH</i>	1	\$ 665.40	\$ 665.40
Third Brake Light <i>HH</i>	1	\$ 385.60	\$ 385.60
BOOT HANDLE <i>HH</i>	1	\$ 31.80	\$ 31.80
Boot Lid Lamp(LH/RH) <i>many broken 794.40x2</i>	2	\$ 822.00	\$ 1,644.00
Boot Lid Trimboard <i>many broken</i>	1	\$ 259.70	\$ 259.70
Boot Lid Trimboard Clips (10pcs) <i>Hec</i>	1	\$ 11.00	\$ 11.00
Boot Lid Trimboard, Centre <i>HH</i>	1	\$ 159.60	\$ 159.60
Boot Lid Trimboard SIDE (LH/RH) <i>HH</i>	2	\$ 92.50	\$ 185.00
Boot Lid Trimboard REAR <i>HH</i>	1	\$ 124.80	\$ 124.80
Boot Lid Glass Upper Moulding <i>HH</i>	1	\$ 186.30	\$ 186.30
Boot Lid Glass Lower Moulding <i>HH</i>	1	\$ 145.20	\$ 145.20
Rear Bumper <i>Don</i>	1	\$ 459.40	\$ 459.40
Rear Bumper Reinforcement <i>Double</i>	1	\$ 394.80	\$ 394.80
Rear Bumper Reinforcement Bracket (LH/RH) <i>broken</i>	2	\$ 188.10	\$ 376.20
Antenna Assy-SMARTK outer <i>many broken</i>	1	\$ 689.50	\$ 689.50
Rear Bumper Centre Moulding Assy <i>broken</i>	1	\$ 451.25	\$ 451.25
Rear Bumper Lower Centre Moulding Assy <i>distorted</i>	1	\$ 155.00	\$ 155.00
Rear Bumper Stay <i>HH</i>	1	\$ 138.10	\$ 138.10
Rear Bumper Side retainer (LH/RH) <i>o/s broken n/s HH</i>	2	\$ <u>85.80</u>	\$ 171.60
Rear Bumper Cover Clips <i>Hec</i>	1	\$ 22.00	\$ 22.00
Rear Bumper Under Centre <i>distorted</i>	1	\$ 123.85	\$ 123.85
Rear Bumper Side Under(LH/RH) <i>broken</i>	2	\$ 123.10	\$ 246.20
Rear Bumper Rear Hook <i>HH</i>	1	\$ 94.60	\$ 94.60
Rear Bumper Reflector Lamp(LH/RH) <i>o/s HH n/s distorted</i>	2	\$ 82.90	\$ 165.80
Rear Bumper Towing Cover <i>distorted</i>	1	\$ 98.80	\$ 98.80
Rear Bumper Reserve Light (Parking Brake Light) <i>socket</i>	1	\$ 328.60	\$ 328.60
Licence Lamp <i>many broken for extra broken</i>	1	\$ 193.53	\$ 193.53
Tail Lamp(LH/RH) <i>many broken 870.40 x2</i>	2	\$ 935.40	\$ 1,870.80
Tail Lamp Quarter Panel(LH/RH) <i>key</i>	2	\$ 208.90	\$ 417.80
Rear Panel <i>Double</i>	1	\$ 532.00	\$ 532.00
Antenna Assy - TRUNK <i>many broken</i>	1	\$ 689.50	\$ 689.50
Rear Panel Garnish <i>changed</i>	1	\$ 346.80	\$ 346.80
Spare Tyre Holder <i>HH</i>	1	\$ 223.10	\$ 223.10
Spare Wheel Lock Nut <i>HH</i>	1	\$ 89.50	\$ 89.50
Spare Tyre Panel <i>Double</i>	1	\$ 892.50	\$ 892.50

1588.80
 40.50
 1740.80
 80.20

