



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: ALLIANZ INSURANCE SINGAPORE PTE LTD 12 MARINA VIEW #04-01, ASIA SQUARE TOWER 2 SINGAPORE 018961	Document No.	: SQT22003090	Page	1
Registration No	: SJG523C	Date	: 21. Oct 2022		
Chassis No	: MRHFC5650GT000939	Customer No.	: WZA011		
Model	: CIVIC 1.6 VTI YM2016	Svc Advisor	: IVAN TEO BOON KIAT		
Owner's Name	: ONG HONG SENG	Engine No	: R16B21601216		
Ins Policy No.	:	Date Time	: 21. Oct 2022 12:45:35 PM		
Date of Accident	: 21/10/2022	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: ONG HONG SENG OWNER INSURER: GREAT EASTERN ACC DATE: 21/10/2022 SURVEYED BY: DATE: REF NO: TP INSURER: ALLIANZ TP VEH: SMK9555U						
71500-TEC-Q00ZZ	FACE ASSY.RR.BUMPER / <i>nn</i>	1	617.20	25	462.90	32.40	495.30 ✓
33505-TEA-T01	REFLECTOR ASSY.RR. X <i>nn</i>	1	19.20	25	14.40	1.01	15.41
33555-TEA-T01	REFLECTOR ASSYL.RR. X <i>nn</i>	1	19.20	25	14.40	1.01	15.41
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER / <i>nn</i>	1	42.00	25	31.50	2.21	33.71 ✓
71503-TEA-T00	GARNISH,R.RR.BUMPER SIDE X <i>nn</i>	1	9.00	25	6.75	0.47	7.22
71508-TEA-T00	GARNISH,L.RR.BUMPER SIDE X <i>nn</i>	1	9.00	25	6.75	0.47	7.22
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER / <i>nn</i>	1	190.10	25	142.57	9.98	152.55 ✓
71593-TEA-T01	SPACERR.RR.BUMPER SIDE / <i>nn</i>	1	11.50	25	8.62	0.60	9.22 ✓
71598-TEA-T01	SPACERL.RR.BUMPER SIDE / <i>nn</i>	1	11.50	25	8.62	0.60	9.22 ✓
91505-TM8-003	CLIP,BUMPER / <i>nn</i>	7	2.30	25	12.07	0.84	12.91 ✓
68500-TEA-N00ZZ	LID COMP TRUNK / <i>nn</i>	1	724.70	25	543.52	38.05	581.57 ✓
74865-TEA-T01	WEATHERSTRIPTRUNK LID / <i>nn</i> TN	1	70.00	25	52.50	3.68	56.18 ✓
75722-TBA-A00	EMBLEM SETRR. / <i>nn</i>	1	13.60	25	10.20	0.71	10.91 ✓
75725-TEA-T01	EMBLEMRR. / <i>nn</i>	1	12.70	25	9.52	0.67	10.19 ✓
33500-TEA-T01	TAILLIGHT ASSYR. X <i>nn</i>	1	301.70	25	226.27	15.84	242.11
33550-TEA-T01	TAILLIGHT ASSYL. X <i>nn</i>	1	324.70	25	243.52	17.05	260.57
66100-TEC-307ZZ	PANEL SETRR. / <i>nn</i> (photo)	1	280.70	25	210.52	14.74	225.26 ✓
84640-TEA-Z01ZA	LINING ASSYRR.PANEL / <i>nn</i>	1	50.30	25	37.72	2.64	40.36
Sum Item					2042.35	142.97	2,185.32

Printed on 21/10/2022 12:57:53 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.

HONDA

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : ALLIANZ INSURANCE SINGAPORE PTE LTD
12 MARINA VIEW
#04-01, ASIA SQUARE TOWER 2
SINGAPORE 018961
Registration No : SJG523C
Chassis No : MRHFC5650GT000939
Model : CIVIC 1.6 VTI YM2016
Owner's Name : ONG HONG SENG
Ins Policy No :
Date of Accident : 21/10/2022

Document No. : SQT22003090
Date : 21. Oct 2022
Customer No. : WZA011
Svc Advisor : IVAN TEO BOON KIAT
Engine No : R16B21601216
Date | Time : 21. Oct 2022 12:45:35 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount incld GST
BOSUN	SUNDRIES	1	110.00	50 ✓	110.00	7.70	117.70
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	280.00	✓	280.00	19.60	299.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	280.00	✓	280.00	19.60	299.60
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	560.00	500	560.00	39.20	599.20
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	560.00	500	560.00	39.20	599.20
BKTRR	REMOVE & TRANSFER ITEMS TO NEW TRUNK LID	1	560.00	480	560.00	39.20	599.20
BOJSE	BODY JOINT SEALANT END PANEL	1	120.00	✓	120.00	8.40	128.40
BKRP02S	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.	1	5200.00	3250	5200.00	364.00	5564.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	4160.00	2600	4160.00	291.20	4451.20
BOBC	BODY UNDERSIDE COATING (N)	1	380.00	350	380.00	26.60	406.60
Sum Labor					12210.00	854.70	13,064.70

Survey By

Date & Time

Excess

Status

Signature

Stew (LKK)
21/11/22, 12:33p
WIL
PIP
8 djs

Total Amount 14,252.35 997.67 15,250.02

Total (Inclusive of GST) 15,250.02

*Supplementary Parts

STIFFENERL.RR.PANEL SIDE \$23.10 ✓ BT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 21/10/2022 12:57:53 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.