

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC6/ A1622010544/U23

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

7 days

Res.: Yes or No

Lum Sum:

1.3.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

G3L 9099U

Yr Regn:

07/07/22

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Volkswagen Caddy

C.C.

1968

Colour

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

10743

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WV1222 SK7NX 051056

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/55-17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Giti

Front

Rear

R/Bal.

2

mm

R/Bal.

2

mm

L/Bal.

2

mm

L/Bal.

2

mm

D.O.A.

20/10/22

D.O.I.

28/10/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S & Rpt.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

20/12/22 P/P # 8291.05 informed here

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/GBL9099U/2210140

27th October 2022

The Manager
Motor Claim Department
AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way #07-16
Singapore 079120

not Authorised
28/10/22
P/P \$ 8291.05
Amplified Repairing
7 days

Date of Accident : 20th October 2022
Location : Lorong Chuan
Name of Policyholder : KSP Food Suppliers Pte Ltd
Policy No : DMCG22009427
Vehicle No : GBL 9099 U Volkswagen Caddy

Estimated Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Rear boot cover LH <i>body no</i>	1	2,472.25	\$ 2,472.25 ✓
2	Rear boot cover hinge (bottom) <i>Buf</i>	1	216.15	\$ 216.15 ✓
3	Rear windscreen glass with moulding <i>NN</i>	1	581.75	\$ 581.75 X
4	Rear lamp assy LH <i>11</i>	1	362.10	\$ 362.10 X
5	Rear end panel <i>R</i>	1	582.15	\$ 582.15 X
6	Rear bumper fascia <i>D13</i>	1	815.75	\$ 815.75 ✓
7	Rear bumper beam <i>11</i>	1	811.20	\$ 811.20 X
8	Rear bumper reflector LH <i>320</i>	1	51.15	\$ 51.15 ✓
9	Rear bumper clips <i>new</i>	1set	25.00	\$ 25.00 ✓
10	Rear bumper side retainer LH <i>one</i>	1	58.85	\$ 58.85 ✓
11	Rear fender LH <i>R</i>	1	2,817.95	\$ 2,817.95 X
12	Rear fender cowling LH <i>TORN</i>	1	225.50	\$ 225.50 ✓
13	Rear fender cowling clips <i>11</i>	1set	25.00	\$ 25.00 X
14	Rear fender glass <i>11</i>	1	381.10	\$ 381.10 X
15	Rear bumper under cover LH <i>D13</i>	1	192.75	\$ 192.75 ✓
16	Front bumper fascia <i>re/Torn</i>	1	1,106.55	\$ 1,106.55 ✓
17	Front bumper clips <i>new</i>	1set	25.00	\$ 25.00 ✓
18	Front bumper side retainer L&RH <i>Buf</i>	2	89.90	\$ 179.80 ✓
19	Headlamp assy LH <i>one</i>	1	781.25	\$ 781.25 ✓
20	Front support panel <i>R</i>	1	1,521.15	\$ 1,521.15 X
				\$13,232.40

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

LKR Auto Consultants hence notify

the following:

• To display damaged part(s) during resurvey

• To display damaged part(s) during resurvey

• To display damaged part(s) during resurvey

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and

is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SM/GBL9099U/2210140

21st October 2022

No.	Particulars	Qty	Price	Amounts
	Balance b/f			\$13,232.40
21	Front bumper beam <i>11</i>	1	881.75	\$ 881.75 X
22	Front bumper sponge <i>11</i>	1	92.10	\$ 92.10 X
23	Front grille emblem <i>one</i>	1	128.95	\$ 128.95 ✓
24	Rear bumper sensor (s/nett) <i>shaded</i>	1 set	380.00	\$ 380.00 <i>200 s/w</i>
25	Rear boot cover sticker (s/nett) <i>70 km/h</i>	1	18.00	\$ 18.00 <i>10 s/w</i>
26	Rear windscreen sealant (s/nett) <i>nee</i>	1	60.00	\$ 60.00 <i>40 s/w</i>
27	Rear end panel sealer (s/nett) <i>nee</i>	1	80.00	\$ 80.00 X
28	Rear fender glass sealant (s/nett) <i>11</i>	1	60.00	\$ 60.00 X
29	Front number plate (s/nett) <i>Best</i>	1	50.00	\$ 50.00 <i>40 s/w</i>
				\$14,983.20

Labour Charges :-

	Amounts
Cut out, renew, knocking & welding front support panel, remove & install all damage parts & re-align body	\$ 980.00 <i>400</i>
Cut out, renew, knocking & welding rear boot cover LH, rear fender LH, rear end panel LH, remove & install all damage parts, straighten & re-align body	\$ 1,800.00 <i>1000</i>
Remove & install rear windscreen glass	\$ 120.00 ✓
Remove & install rear fender glass <i>11</i>	\$ 120.00 X
Remove & install rear bumper sensor	\$ 80.00 <i>50</i>
Tuff-kote on rear damage parts	\$ 120.00 <i>50</i>
Spray painting on rear damage parts	\$ 1,380.00 <i>700</i>
Check lighting on front & rear after repairs	\$ 45.00 <i>30</i>
Labour Charge	\$ 4,645.00
Total Amount	\$19,628.20

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

2-6278.98
102
5651.05
290
2350
8291.08