

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22010545/EPA3Q2**Date:** 11/05/2023REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2001050783
Claimant Vehicle No :	FBN9819Z	Insured Vehicle No :	SMX4429R
Date of Loss:	07/10/2022	Nature of Claim:	TP
		Claim No:	202222007317FR

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBN9819Z	Engine No:	NC42E1402634
Make & Model:	HONDA CB400A, 399cc	Chassis No:	NC421902635
Reg. Date:	31/01/2019 (Man. Year: 2018)	Odometer:	38339 km
Colour:	White		
Engine Capacity:	399 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/60Z R17	Rear Tyre Size:	160/60Z R17
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,029.50	3,793.50	1,236.00	24.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	465.00	445.00	20.00	4.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,494.50	4,238.50	1,256.00	22.86
Approved Total (Overridden) (S\$)		4,333.50		
Nett Amount (S\$)	5,494.50	4,333.50	1,161.00	21.13
+ Loss of Use (3.0 x S\$30.00/day) (S\$)		90.00		
Nett Liability (S\$)		4,423.50		
Global Sum Settlement (S\$)		4,420.00		

INSPECTION

Date of Assignment:	21/10/2022	
Date Inspected:	27/10/2022	Inspected At: Southern Motor (HQ) BLK 1006 BUKIT MERAH LANE 2, #01-10 Singapore 159762
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 11 May 2023)	
Parts:	N/A	HONDA CB400A 399cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBN9819Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET METER COMP	Broken	1,680.00 FL	*1,465.00 FL
2	1		*HANDLE BAR	Bent	160.00 FL	*160.00 FL
3	1		*MIRROR	Cut	110.00 FL	*110.00 FL
4	1		*CLUTCH LEVER	Cut	35.00 FL	*35.00 FL
5	1		*ENGINE GUARD	Bent	190.00 FL	*190.00 FL
6	1		*HANDLE BALANCER	Cut	45.00 FL	*45.00 FL
7	1		*REAR GIVI BOX	Cut	180.00 FL	*180.00 FL
8	1		*IU	Not Necessary	165.00 FS	*- FS
9	1		*FRONT SPORT RIM	Cut	780.00 FL	*780.00 FL
10	1		*FORK FORK KIT RH	Bent	860.00 FL	*860.00 FL
11	1		*FORK BRAKE DISK	Repair	485.00 FL	*- FL
12	1		*ABS SENSOR	Torn	280.00 FL	*280.00 FL
13	1		*ABS FRONT PLATE	Cut	110.00 FL	*110.00 FL
14	1		*FRONT BRAKE CALIPER	Repair	490.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,570.00	4,215.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	540.50	421.50
Total Parts (\$\$)	5,029.50	3,793.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	40.00	40.00
2	ALIGNMENT FRONT FORK	New	85.00	85.00
3	LABOUR	New	200.00	200.00
4	SPRAY FUEL TANK	New	140.00	120.00
Gross Labour Cost (\$\$)			465.00	445.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >