



# 南方摩哆 Southern Motor

Business Reg. No: 234147/00L  
Block 1006, Bukit Merah Lane 2. #01-10, Singapore 159762  
Tel: 6273-0369 (3 Lines) Fax: 6274-6614

19 Oct 2022

Allianz Insurance Singapore Pte Ltd  
79 Robinson Road #09-01  
Singapore (068897)

Dear Sirs,

**RE: Cost of repair to Honda CB400 - FBN9819Z**

1set of Meter Comp	S\$	1,680.00
1pc of Handle Bar		160.00
1pc of Mirror		110.00
1pc of Clutch Lever		35.00
1pc of Engine Guard		190.00
1pc of Handle Balancer		45.00
1pc of Rear Givi Box		180.00
		<hr/>
		2,400.00
	Less 10%	240.00
		<hr/>
	Nett	2,160.00
	IU	165.00
	Towing	40.00
	Alignment Front Fork	85.00
	Labour	200.00
		<hr/>
		<u>\$2,650.00</u>

Yours Faithfully,  
Southern Motor





Date: 19 Oct 2022

Southern Motor  
Blk 1006 Bukit Merah Lane 2  
#01-10  
Singapore 159762

Motor Claims Department  
Allianz Insurance Singapore Pte Ltd  
79 Robinson Road #09-01  
Singapore 068897

Dear Sirs,

RE: ACCIDENT INVOLVING FBN9819Z AND SMX4429R ALONG  
Poh Huat Road West ON 07-10-2022 AT 09:30AM

Please be informed that the above-said motorcycle bearing registration no: FBN9819Z was seriously damaged during the above-said accident and was beyond economic repair.

Kindly arrange for your surveyor to survey the above-mentioned motorcycle at Blk 1006, Bukit Merah Lane 2 #01-10 Singapore 159762. (Tel:62730369)

Thanking you in advance,

Yours Faithfully,



Enc.