



南方摩哆 Southern Motor

Business Reg. No: 234147/00L

Block 1006, Bukit Merah Lane 2, #01-10, Singapore 159762

Tel: 6273-0369 (3 Lines) Fax: 6274-6614

27 Oct 2022

Allianz Insurance Singapore Pte Ltd
79 Robinson Road #09-01
Singapore (068897)

Dear Sirs,

RE: Additional Cost of repair to Honda CB400 -FBN9819Z

Supplementary

1pcs of Front Sport Rim ✓ *CVT*
1pc of Spray Fuel Tank (and sticker) ✓ *nec*

SS	780.00
	140.00
	920.00
	92.00
	828.00
	<u>\$828.00</u>

Less 10%

Nett

Yours Faithfully,
Southern Motor



Steve (LKK)
27/10/22