

ASS. REC-BY: Tauja

REF: CC4/ASM 22 01 546/TP 93

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Date: _____ Person Contacted: Hilam Vehicle: IN / OUT

Veh No: PD 3399U Yr Regn: 2021 Feb

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Volvo B8R C.C. 7698

Colour: Mult A/C: Insured / Std / NI / NA

Sp. Reading: 55217 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: YU 3T 74527 KA 197581

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: M / S/Rim / STD A/Rim or

Tyre Size: F: 245/80 R22.5

R: 245/80 R22.5 (D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Golden Crown

Front R/Bal. 8 mm Rear R/Bal. 8/8 mm

L/Bal. 8 mm L/Bal. 8/8 mm

D.O.A. _____ D.O.L. 26/10/22

Survey held at The One Holdings

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Fnt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Prel. Report

1) Date/Time, File Return to? ☐ : Final Report

2) _____

Rep. Format: _____

Lump Sum / L.B.A. / P: _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS \$ _____

Photos _____

Others _____



THE ONE HOLDINGS
PRIVATE LIMITED

(Specialize in commercial vehicle repair works)
Business and GST Reg No. : 2017040522

The One Holdings Pte Ltd

No 8 Woodlands Industrial Park E3 Singapore 757786

Telephone: +65 6755 8810 Facsimile: +65 6755 8809

Email: enquiry@theoneholdings.com.sg

Website: www.facebook.com/the1holdings

QUOTATION

To: AXA Insurance Pte. Ltd

8 Shenton Way

#24-01

AXA Tower

Singapore 068811

Our Ref :Q221036

Date :25/10/2022

Term :COD

In Charge :Hilmi

Dear Sir / Madam,

RE: Quotation for PD3399U

Remarks :BPT Loss of Use 3days X \$200 = \$600

No.	Description	Qty	UOM	U/P (\$)	Amt (\$)
	Ad hoc				
1	To supply labour to dismantle attached items to facilitate the following repairs, 1) To replace aluminium plate for the front door. Uninstall door unit and re alignment. 2) To repair the LHS front corner dented areas, fibre up and sand. - Items 1 & 2 is \$1400 ✓ 3) Seca 6pcs X \$50=\$300 240 ✓ 4) Labour for spray back original colours on all repaired bodyworks. \$900 800 ✓ 360	1.00	UT	2,600.00	2,600.00

[Signature]

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanjiin 9749 5749/62563561
up! 20/10/22 01045
P/P Resurvey before part ✓ amr. 7.
02 days
Tanjiin @ lkkauto.com.

Prices are subject to change without prior notice, additional parts need to be replaced, subject to final checking and bill separately.

Accepted and Confirmed by :

Subtotal: 2,600.00
GST 7.0% : 182.00
Total Amount: 2,782.00